
U39



No. F6/DFS/MS/Metro/WZ/2025/ 6 0 1 To.

Dated: 0 8 / 12 /2025

Sh. Rajesh Agarwal, General Manager (E & M), Delhi Metro Rail Corporation Ltd., Metro Bhawan, 13 Fire Brigade Lane, Barakhamba Road, New Delhi-110001.

Sub: - Regarding renewal of Fire Safety Certificate in r/o Paschim Vihar (West) Metro Station, (Elevated) located at Paschim Vihar (West), New Delhi- 110063.

Sir,

This has reference to your application no. DMRC/O&M/Fire/NOC/L-5/2025/12 dated 29/10/2025 received through outdoor diary number 7815 dated 04/11/2025 on the subject cited above. In this connection, it is to inform you that the inspection of above said metro station has been carried out by officer concerned of this department on 28/11/2025 to see the compliance of the requisite fire safety measures. Sh. Ashish (Senior Inspector Fire) were present at the time of inspection.

During the course of inspection it was observed that the metro station building comprised of Ground + 1<sup>st</sup> Floor (Concourse level) + 2<sup>nd</sup> Floor (Platform level). Your request for renewal of FSC is rejected as the following shortcomings were observed:

- 1. Door closer of fire check door found removed at some places.
- 2. Detectors found removed at some places.
- 3. Sprinkler found removed at some places.

In view of the above shortcomings, the application for renewal of Fire Safety Certificate is not considered at this stage & rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall is at the risk and liabilities of the Owner/ Occupier.

Yours faithfully,

(S.K. Dua)

Dy. Chief Fire Officer (WZ)

**Delhi Fire Service** 

our