GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI

No. F6/DFS/MS/WZ/2025/ 362

FIRE SAFETY CERTIFICATE

Certified that the M/s. Pearls Best Heights-II, Located at C-9, Netaji Subash Place, Pitampura, New Delhi-110034, comprised of Basement + Ground + 13 Upper Floors, owned/occupied by M/s. Pearls Best Heights-II, was issued FSC vide this department letter no. F6/DFS/MS/WZ/2019/175 dated 24/01/2019. The premises was re-inspected by the officer concerned of this department on 20/06/2025 in the presence of Sh. Nityanand Prasad Yadav and found that the said building/premises have deemed complied with the fire prevention and fire safety requirements in accordance with rules 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class "Mercantile & Business Building" Group-F & Group-E with effect from ollo7/25 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010. Conditions mentioned below.

107 בלכר at New Delhi by.

Copy to: -

- 1. The Executive Engineer (Bldg.) HQ, North Delhi Municipal Corporation, 8th floor, Minto Road, New Delhi- 110002.
- 2. The Vice Chairman, DDA, INA, Vikas Sadan, New Delhi-110023.
- 3. The Owner/Occupier, M/s. Best Infrastructure (INDIA) Pvt. Ltd., located at 141, 1st floor, Best Business Park, Plot No. P2, Netaji Subash Place, New Delhi-110034. Email ID:mail@bestgroupindia.com.

Conditions for the validity of FSC:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The Fire Safety certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The Basement shall be used strictly as per the provision of unified building bye laws.
- 7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the available on Service Rules 2010, form is Fire of Delhi schedule www.dfs.delhigovt.nic.in.

1		<u></u>	NSPEC	TION REPOR	T			
1								
			M/s. Pearls Best Heights-II, Located at C-9, Netaji Subash Place, Pitampura, New Delhi-110034.					
	Type of	Occupancy	Mercan	tile + Busines	s (M	lixed), (Basement, Gr	ound.	- 1 10
_	·	0.0	upper f	loors.	(med), (Basement, Gr	ouna	and 13
	Type o		Renewa	al				
		of previous NOC	F6/DFS	S/MS/WZ/2019	/175	dated 24/01/2019		
• = 1		fety directives letter No	F6/DFS	S/MS/BP/2005/	1036	dated 18/05/2005		
		inspection	20/06/2	2025				
		of the Inspecting Officers		et Singh ADO				
3.		and designation of	Sh. Nit	yanand Prasad	Yada	ıv		
		s from the building side						
0.		f Construction	2007 (As per previous	insp	ection report dated 10/	01/20	19)
0.	/.E. (ant's letter No.		dated 04/04/202				
he		ilding comprised of basen	nents, gr	ound & thirte	en u	pper floors.		
S.	l .	imum Standards on fire		ired as per Ru		Provided at site	R	emarks
Vo		tion and fire safety U/R 33	35(6)	of DFS Rule 2	010		M	R/NMR
•5	Access	to building						
	•	Road width		24 mts		Provided		MR
	•	Gate width		06 mts		Provided		MR
	•	Width of internal road		06 mts	As	per DDA controlled draw	ving	MR
2	Numb	er, Width, Type & Arran	gement	of Exits				
	a. Nun	iber of staircases						
	•	Upper Floors Basements		02		Provided		MR
	•			02		Provided		MR
	b. Wid	th of staircases						
	. •	Upper Floors		1.5m &1.25m		.5m &1.14m Provided		Old case
	•	Basements		1.5m &1.25m	1	.5m &1.14m Provided	MR	(Old case
	c. Prot	otection of exits				D 11-1		MR
	•	Fire check door		Required		Provided Provided		MR
	•	Pressurization	*.	Required		Provided		MR
		of continuous staircases to to	errace	Required	_	Provided		MR
		th of Corridor		1.5 mts	-	Provided		MR
	g. Doo	Door Size		1mts		Flovided		
3	Comp	artmentation.	44		-1	Provided	Г	MR
	•	Fire check door		Required		Provided		MR
		Sealing of electrical shafts	S	Required		19.59VA		MR
		Fire Rating of shaft door		Required		Provided		NA
		Water Curtain		NA		NA NA		NA
		Fire Dampers		NA		NA	9	
4	Smalle Management System.							
4	Sillok	Basements	1	Required		Provided		MR
		Upper floors		Required		Open able Window		IVIIX
2	-			Bear III L		0.74		
5	Fire Extinguishers			35 nos.		Provided	_	MR
	•	Total numbersTypes		CO ₂ , ABC typ	oe	Provided		MR
				ISI marked		Provided		MR
	•			A 100 miles				
	•	IS marking	A			Y		
6	First-	Aid Hose Reels.		01	-	Provided		MR
6	First-		oor	01 30m	Ti	Provided Provided		MR MR

	H			-
	Automatic fire detection and alarming	system.	D :1.1	ND ND
	Type of detectors	Smoke & Heat	Provided	MR
	Location of Main Panel	Required	Provided	MR
	Location of Repeater Panel	Required	Provided	MR
	Alternate source of power	Required	Provided	· MR
	Hooters' Location	Required	Provided	MR
		Required	Provided	MR
	MOEFA Public Address System.	Required	Provided	MR
	•	-		
0	Automatic Sprinkler System.	Dogwired	Provided	MR
	Basement	Required	Provided	MR
	Upper Floor	Required	Provided	MR
	Sprinkler above false ceiling	Required	Hovided	
1	Internal Hydrants	7	2 111	MR
	Size of riser/down-comer	150 mm	Provided	MR
	Number of hydrants per floor	01	Provided	MR
	Hose Box	01	Provided	MIK
2	Yard Hydrants.	s		
	Total number of hydrants	05	Provided	MR
	Hose Box	Required	Provided	MR
13	Pumping Arrangements.			
None.	Ground Level			
	 Discharge of main Pump 	2850 LPM	Provided	MR
	➤ Head of Main pump	70 M	Provided	MR
	Number of main pumps	01	Provided	MR
	Jockey Pump out put	2 x 180 LPM	Provided	MR
	Jockey pump head	70 M	Provided	MR
	Standby Pump out put	2850 LPM	Provided	MR
	➤ Standby Pump Head	70 M	Provided	MR
	> Auto Starting/ Manual stopping	Required	Provided	MR
	Pump House Access	Required	Provided	MR
	Terrace level			
	Discharge of pump	NA	NA	NA
	➤ Head of the pump	NA NA	NA	NA
	Power Supply	NA NA	NA NA	NA
	Auto Starting of pump	4	NA	NA
4	Captive Water Storage for fire fightin		D	
	Underground tank capacity	2,00,000 ltrs	Provided	MR
	➤ Draw-off connection	Required Required	Provided	MR
	Fire service inletAccess to tank	•	Provided	MR
5	E SS G	Required	Provided	MR
	Overhead Tank capacity Exit Signage	30,000 ltrs	Provided Provided	MR
)	Exit Signage. Provision of Lifts.	Required	Fiovided	MR
		Domina	D	
	Pressurization of Lift Shaft	Required	Provided	MR
	 Pressurization of Lift lobby 	Required	Provided	MR
	Communication In lift Car	Required	Provided	MR
	 Fireman's Grounding Switch 	Required	Provided	MR
1	Lift Signage	Required	Provided	MR

	A summly	PIVI					
1	Standby power supply	Required	Provided	MR			
4	Refuge Area.						
18	> Total Area	Required	Provided	MR			
R	> Location	5 th , 7 th &10 th floor	Provided	MR			
19 1	Fire Control Room						
117	Detector System Panel	Required	Provided	MR			
	Flow Switch Panel	Required	Provided	MR			
	PA System Panel	Required	Provided	MR			
	Battery backup	Required	Provided	MR			
	Building Floor Plans	Required	Provided	MR			
200	pecial Fire Protection Systems for rotection of special Risks, if any:	NA	NA	NA			

The fire protection systems provided in the building were checked and found functional at the time of inspection. Earlier all the shortcomings issued by this department have been complied by building management.

In view the deemed compliance of the minimum standards on fire prevention & fire safety requirement under the rules, renewal of FSC issued vide letter No. F6/DFS/MS/WZ/2022/23 dated 18/01/2022, is recommended under rule 37 of the Delhi fire Service Rules 2010.

10/mN

Signature of the Inspecting Officer
Sarabjeet Singh ADO (MN)

Director Ly

Aoymn

Sir FT i's put up for your med pusued &

Signapu pls

6117/20

Directed