



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/2025/SZ/ 172

Dated: 07 6 4 /2025

FIRE SAFETY CERTIFICATE

Certified that **Phase 3A-Terminal Building Zone 27** located at Terminal–1, IGI Airport, New Delhi–110037, comprised of 3A-Terminal Building Zone–27 for Toilet + Terminal Manager Room + Check-in Counter, owned/occupied by Delhi International airport Limited was issued **FSC** by this department vide letter No. F.6/DFS/MS/2022/SZ/107 dated 14/03/2022. The premise was re-inspected by the officer concerned of this department on 26/03/2025 in the presence of Sh. Rakesh Kumar (Head–FP&S) and observed that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the said building is fit for occupancy class "**Mixed**" (Business/Assembly) with effect from <u>07 / 04 /</u>2025 for a period of **three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 0 / 12025 at New Delhi by

DIRECTOR

Ph. 011-23414000

Copy to: -

 Sh. Selvaraj Arumugam Head ARRF, D.I.A.L, New Udaan Bhawan, Opp. Terminal 3, IGI Airport, New Delhi–110037

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection.
- Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of fire-fighting system.
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, prior to its expiry.
- 7. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

1-20

	INSPECTION Name & Address of the Building	Phase 24 Th			
1	Name & Address of the Building	Torminal 1	minal Building Zo	ne 27 at	
	Type of Occupancy	reimmal-I.	Lal Almort Doll:	11000=	
2	Building Comprised of	White occupancy "Business/Assembly"			
3	Building Comprised of	Basement, Ground + Mezzanine floor. 3A Terminal BldgZone 27 for Toilet,			
	κ.	Terminal Mans	ager Room + Check	ilet,	
4	Type of Case	Renewal	ger Room + Check	in counte	
5	Details of Previous NOC	Control of the Contro			
	Fire Safety Directives Letter No	F.6DFS/MS/2022/SZ/107 dated 14.03.2022			
6	Date of Inspection	F6/DFS/MS/2020BP/237 dated 02/11/2020 26/03/2025			
7	Name of the Inspecting Officers	ADO (SJ)			
8	Name & Designation of Officers	Sh. Rakesh Kumar, Head-FP&S			
9	from the building side	Sn. Rakesh Ku	mar, Head-FP&S		
10	Year of construction	2021			
10		2021			
11	Applicant letter No. Minimum standards on Fire	Email dated 12.03.2025 < Rakesh.Kumar4@gmrgroup.ii			
S.	Prevention and Fire Safety U/R 33	Requirement	Provided at Site	Remark	
No. 1	Access to Building.	s Rule 35(6)		MR/NM	
-	Road width	20	122		
	Gate width	20 mtr	Provided	MR	
	Width of internal road	N/A	N/A	N/A	
2		6m	Provided	MR	
4	Number, width, type & arrangemen	nt of exits.			
	a) Number of Staircase	Common ar	rangements for the	complex	
	> Upper floors.	02 Nos	Provided	MR	
	➤ Basements	02 Nos	Provided	MR	
	b) Width of Staircase	Common arrangements for the complex			
	> Upper floors	1.20 mtr	1.5m & 1.3m	MR	
	➤ Basement floor	1.20 mtr	1.5m & 1.3m	MR	
	c) Protection of exits	Common at	rangements for the	complex	
	➢ Fire check door	Required	Provided		
	Pressurization	Required	Provided	MR	
	d) No. of continuous staircase to terrace	02 Nos	Provided	MR	
	e) Width of corridor	2.0 mtr	Provided	MR	
	f) Door size	Required	3.0/2.0/1.8/1.5/1.	MR	
3	Compartmentation.	District of Danies State			
	 Fire check door. 	Required	rrangements for the		
	Sealing of electrical shafts.	Required	Provided Provided	MR	
	Fire rating of shaft door.	Required	Provided	MR	
	Water curtain	N/A	N/A	MR N/A	
4	Fire dampers.	N/A	N/A	N/A	
4	Smoke Management system.	Common as	rrangements for the		
	Basement	Required	MV Provided	MR	
5	• Upper floors	Required	MV Provided	MR	
3	Fire Extinguishers.				
	 Total numbers 		Provided	MR	
	• Types	ISI marked	ABC & CO ₂	MR	
	ISI Marking		Provided	MR	
6	First Aid Hose Reels.	Common arrangements for the complex			
	 Total numbers on each floor. 		Provided	MR	
	 Length of hose-reel hose. 	Hose-reel	30m	MR	
	Nozzle Diameter	(Car 3752	5mm	MR	

14-51

7	Automatic fire detection & alarmin	ng system.		
	 Type of detectors 	Required	Smoke & Heat	MR
	 Location of Main Panel 	Required	Provided	MR
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	Required	Provided	MR
	and the second s	-	Provided	MR
0	Hooter's location	Required	TODO STANSON DE LA CONTRACTOR DE LA CONT	MR
8	MOEFA	Required	Provided	N/A
9	Public Address System	N/A	N/A	
10	Automatic Sprinkler System		ngements for the com	MR
	Basement	Required	Provided Provided	MR
	 Upper floors 	Required	Provided	MR
	 Sprinkler above false ceiling 	Required	ngements for the com	plex
11	Internal Hydrants.		Provided	
	Size of Riser/Down-comer	200mm	Provided	MR
	Number of Hydrant per floor	Required Required	Provided	MR
	Hose box.	Common arran	gements for the com	plex
12	Yard Hydrants.	Required	Provided	17.0
	Total number of hydrants.	Required	Provided	MR
	Hose box.			
13	Pumping arrangements.	Common arran	gements for the com	plex
	Ground Level Discharge of main pump.	Hvd: 4730 LPM	Provided	MR
	Discharge of main pump.	Sprk: 3785 LPM	Provided	MR
	➤ Head of main pump.	105m 75m	Provided	MR
	Number of main pumps.	2 Nos 437 & 378 LPM	Provided	MR
	> Jockey Pump output.	112m & 84m	Provided	MR
	Jockey Pump head.Standby Pump output.	Hyd: 4730 LPM Sprk: 3785 LPM	Provided	MR
	n II Power head	105m 75m	Provided	MR
	Standby Pump head.Auto Starting/Manual Stopping.	Required	Provided	MR
	> Pump house access.	Required	Provided	MR
	Terrace Level		27/4	N/A
	Discharge of pump.	N/A	N/A N/A	N/A
	➤ Head of pump.	N/A N/A	N/A N/A	N/A
	> Power supply.	N/A N/A	N/A	N/A
	> Auto starting of pump. Captive water storage for fire fighting.		gements for the com	_
14	Underground tank capacity.	5,00,000 Ltr	2 x 2,50,000 Ltr	MR
	> Draw-off connection.	Required	Provided	MR
	> Fire Service Inlet.	Required	Provided	MR
	> Access to tank.	Required	Provided	MR
	Overhead tank capacity.	N/A	N/A	N/A
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	Common arrangements for the complex		_
	Pressurization of lift shaft.	Required	Provided	MR
	Pressurization of lift lobby.	Required	Provided	MR
	Communication in lift car.	Required	Provided	MR
	Fireman's switch.	Required	Provided	MR
	Lift signage.	Required	Provided	MR
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			TILL
	Total area	NA	NTA T	
	Approximated to	A12 X	NA	NA

N-52

19	Fire Control Room.			
	MOEFA System Panel.	Required	Provided	MR
	 Flow switch panel. 	Required	Provided	MR
	 PA system panel. 	NA	As Above	NA
	Battery backup.	NA	As Above	NA
	Building floor plan.	Required	Provided	MR
20	Special Fire Protection System for Protection of special Risk, if any.	Trace tube-based panel flooding system in LT, UPS output & lift panel		MR

The fire protection systems provided in the building/premises were checked, tested at random and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F.6/DFS/MS/2022/SZ/107 dated 14.03.2022, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (SJ)

Director Muser is punt for your byog. pl.

Director March is punt for your byog. pl.

Director Director Director is punt for your byog. pl.