स्वयु पास्त

No. F.6/DFS/MS/EH/2025/SZ/ 342

Dated: 01/10/2025

FIRE SAFETY CERTIFICATE

Certified that the premise of M/s Pinjore Restaurant (Tasty Solutions LLP) at Prop. No. 1/4, Ground floor, East Patel Nagar, Delhi–110008, in a building comprised of basement, ground plus three upper floors but the restaurant running at ground floor only, was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/EH/SZ/2022/282 dated 06/10/2022. The said restaurant was re-inspected by the officer concerned of this department on 18/09/2025 in the presence of Sh. Madhav Singh Vohra (Manager)and found that said premises have complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the said premise is fit for occupancy class "Assembly Group D" (Restaurant at ground floor only) with effect from Od /10 /2025 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 01 / 10 /2025 at New Delhi by

(Virendra Singh) Chief Fire Officer Delhi Fire Service

Copy to: -

- 1. The DHO, Municipal Corporation of Delhi, Karol Bagh Zone, New Delhi–110005 (w.r.t. online application No. 2025091413442 dated 14/10/2025)
- 2. Sh. Karan Channa, M/s Pinjore Restaurant (Tasty Solutions LLP) at Prop. No. 1/4, Ground floor, East Patel Nagar, New Delhi–110008

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided there in shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 5. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, prior to its expiry.
- 6. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

N-15

	INSPECTION	REPURI		ons LLP)		
l.	Name & address of the building	Pinjore Restaurant (Tasty Solutions LLP) at Prop. No. 1/4, Ground floor, East Patel Nagar, New Delhi–110008				
2.	Type of Occupancy	Assembly Group D (Restaurant)				
3.	Building Comprised of	Restt. running at GF of building comprised of Basement, Ground + 03 upper floors.				
4	Type of Case	D				
4.	Details of previous NOC No.	F6/DFS/MS/EH/SZ/2022/282 dated 06/10/2022				
5.	Fire safety directives letter No.	Nil				
6.		18/09/2025				
7.	Date of inspection	ADO (SJ)				
8. 9.	Name of the Inspecting Officer Name and designation of Officer	Sh. Madhav Singh Vohra (Manager)				
7.	from the building side	Before 2010				
10.	Year of Construction	No. 2025091413442 dated 14/10/2025				
11.	Applicant's letter No./Online Appl	Requirement	Provided at site	Remarks MR/NMR		
S.	Minimum standards on fire prevention and fire safety U/R 33	As per N/8		MICHAL		
No.	Access of building	Sales	n 'ded	MR		
1.	Road width	6.0 mtr	Provided Directly accessible	The second second		
	Gate width	4.5 mtr	N/A	N/A		
	vy: 141 - Cinternal road	N/A	14/21			
2.	Number, width, Type & Arrangements	of exits	ant at Ground floor	only		
Ζ.	a. Number of staircases	19	N/A	N/A		
	Upper floors	N/A	N/A	N/A		
	Basements	N/A	IWA			
	b. Width of staircases		N/A	N/A		
	Upper floors	N/A	N/A	N/A		
	Basements	N/A	N/A	1,,,,,		
	Covite		2711	N/A		
	Protection of exits Fire check door	N/A	N/A	N/A		
	Pressurization	N/A	N/A N/A	N/A		
	d. No of continuous staircase to terrace	N/A	15000000	_		
	e. Width of Corridor	2.0 mtr	Opening in hall 2.44m, 1.51m &	MR		
œ.	f. Door Size	2.0 mtr	2.44m, 1.51m & 1.10m	(Old cas		
3.	Compartmentation	277	N/A	N/A		
J.	Fire check door	N/A	N/A	N/A		
	 Sealing of electrical shafts 	N/A N/A	N/A	N/A		
	 Fire Rating of shaft door 	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	4.11.2				
4.	Smoke Managements System	N/A	N/A	N/A		
	Basements GE	12 ACPH	Exhaust fan	MR		
	Upper floors (Restaurant–GF)					
5.	Fire Extinguishers	08 Nos	Provided	MR		
	Total numbers	ABC & CO ₂	Provided	MR		
	• Types	Required	Provided	MR		
	ISI marking	Required	A 5.5 (C. 7.5. W			
6.	First-Aid Hose Reels	200000	One	MR		
	Total numbers on each floor	One	30m	MR		
	 Length of hose reel hose 	30m		MR		
	Nozzle diameter	5mm	5mm	IVIIV		



N-16

7.	Automatic fire detection and alarming s Type of detector	N/A	Smoke & Heat	N/A
	Location of Main Panel	N/A	Ground floor	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	Battery back up	N/A
	Hooters' Location	N/A	Near exits	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
10.	Basements	N/A	N/A	N/A
	Upper Floor (Restaurant–GF)	N/A	Provided	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	Size of riser/down- comer	N/A	100 mm	N/A
	Number of hydrants per floor	N/A	One	N/A
	Hose Box	N/A	One	N/A
12.	Yard Hydrants			
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements	4	1	
	Ground Level		L. N)¥
	 Discharge of main pump 	N/A	N/A	N/A
	➤ Head of main pump	N/A	N/A	N/A
	> Number of main pumps	N/A	N/A	N/A
	Jockey pump out putJockey pump head	N/A N/A	N/A	N/A
	> Standby Pump out put	N/A	N/A N/A	N/A N/A
	➤ Standby Pump Head	N/A	N/A	N/A
	Auto Staring/Manual stopping	N/A	N/A	N/A
	Pump House Access	N/A	N/A	N/A
	Terrace level		IA II	
	➤ Discharge of pump	450 LPM	450 LPM	MR
	➤ Head of the pump	40 mtr	40 mtr	MR
	➤ Power supply	Required	Provided	MR
	Auto starting of pump	Required	Provided	MR
14.	Captive water Storage for fire fighting			12 17 17 17
	Underground tank capacity	N/A	N/A	N/A
	> Draw of connection	N/A	N/A	N/A
	> Fire service inlet	Required	Provided	MR
	➤ Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	4,000 ltr	Provided	MR (old case
15	Exit Signage	Required	Provided	MR
16.	Provision of Lifts		Troridou	17110
	 Pressurization of Lift Shaft 	N/A	N/A	N/A
	 Pressurization of lift lobby 	N/A	N/A	N/A
	Communication in lift Car	N/A	N/A N/A	C ACTIVE
	Fireman's Grounding Switch	N/A	150 CONTRACTOR 150 CO	N/A
	➤ Lift Signage	N/A	N/A	N/A
17.	Standby Power Supply		N/A	N/A
18.	Refuge Area	Required	Provided	MR
	> Total area			
	> Location	N/A	N/A	N/A
	1	N/A	N/A	N/A

Sh

N-17

19.	Fire Control Room			
	Detector system panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	> PA System Panel	N/A	N/A	N/A
	Battery backupBuilding Floor Plans	N/A	N/A	N/A
		N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of Special Risks, if any;	Required	Two ABC fire extinguishers provided near elect. panel.	MR

The fire protection systems provided in the building were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety as required under the rules, the fire safety certificate issued vide letter No. F6/DFS/MS/EH/SZ/2022/282 dated 06/10/2022, renewal under rule 37 of Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (SJ)

Crof Mung 24/9/25 Principal Director Pro to Second 24/5/17

81, F.T lette

0F0/H9/ 29/9120W

M