

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2025/289

Dated : 30.10.4/2025

FIRE SAFETY CERTIFICATE

Certified that the Palm D'or Guest House located at 8595/1, D.B. Gupta Road, Pahar Ganj, New Delhi-110055 comprised of Basement + Stilt+ Ground + 03 Upper floors, stilt floor (Parking), Ground floor (05 guest room), 1st floor to 3rd floor (08 guest rooms at each floor), total department this by **FSC** earlier granted rooms was No.F6/DFS/MS/GH/NDZ/2022/345 dated 14.07.2022. Now, the premises was inspected by the officer concerned of this department on 15.04.2025 in the presence of Mr. Mukesh Aggarwal and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Stilt floor (Parking), Ground floor (05 guest room), 1st floor to 3rd floor (08 guest rooms at each floor), total 29 guest rooms up to third floor only with effect from . 30/04/2025... for period of three years, in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 30/04/2025 at New Delhi by.

Delhi Fire Service

Copy to:-

1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above & deviation if any.

2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi.

Online id no. 2025031703688 dated 04.04.2025.

3. The Owner, Palm D'or Guest House located at 8595/1, D.B. Gupta Road, Pahar Ganj, New Delhi-110055

Conditions for the validity of Fire Safety Certificate

- 1. This FSC shall stand null and void if number of lodgers are found more than 10 at any one floor.
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

4. The trained fire fighting staff should be available round the clock.

- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.

9. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the MCD Portal along with a copy of this Certificate, six months prior to its expiry".

N/27 INSPECTION REPORT 1. Name & address of the building Palm D'or Guest House (A Unit of Comfort Hospitality And Infrastructures at 8595/1, 2. Type of occupancy:-D.B. Gupta Road, Pahar Ganj, New Delhi Residential, Sub Division-A-1 Basement+ stilt + Ground + 03Upper floors Basement- (storage), Stilt floor- (Parking), Ground floor (05 guest room) & 1st floor to 3st floor-3. Type of case:-08 guest rooms at each floor), total 29 Guest rooms 4. Details of previous FSC:-Renewal No. F6/DFS/MS/GH/2022/345 dated 5. Fire safety directives No.-14.07.2022 6. Date of inspection:-N/A 7. Name of the inspecting officer:-15.04.2025 8. Name & designation of officer ADO (RN) From the building side:-Mr. Mukesh Aggarwal 9. Year of construction:-2009 10. Applicant's letter No:-Online id no.2025031703688 dated 04.04.2025 Old Case S.No. Minimum Standards on fire Requirement/ Provided at Remarks Prevention and fire safety Existing fire safety site MR/NMR U/R 33 arrangements 1. Access to Building 1) Road width N/A 06 mtr. MR 2) Gate width N/A N/A N/A 3)Width of internal road N/A N/A N/A 2. Number, Width Type & Arrangement of Exits A. Number of staircases 1. Upper floors 01 Nos. 01 Nos. MR 2. Basements 01 Nos. 01 Nos. MR B. Width of staircase 1. Upper floors 0.80 mtr. 1.22m to 1.30m MR 2. Basements 0.80 mtr. 1.22m MR C. Protection of exits 1. Fire check door N/A N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous N/A N/A N/A staircase to terrace E. Width of corridor N/A. N/A N/A 1.0 mtr. 1.0 mtr. MR F. Door size 3. Compartmentation N/A N/A N/A 1) Fire check door 2) Sealing of electrical shafts N/A N/A N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers Smoke Management System 4. MR Exhaust fan Required 1) Basements MR Natural /Exhaust Required 2) Upper floors fan Fire Extinguishers 5. 10 Nos. MR 10 Nos. 1) Total numbers ABC & CO2 MR ABC& CO2 2) Types MR Provided Required 3) ISI marking First-Aid Hose Reel 6. MR 01 1) Total number of eachfloor 01 MR 30 mtr. 2) Length of hose reel hose 30 mtr. MR 05 mm 05 mm 3) Nozzle diameter **Automatic Fire Detection & Alarming System** 7. Provided MR 1) Type of detectors CO Required Provided Gr. Floor MR 2) Location of main panel N/A N/A 3) Location of repeater panel N/A Provided 4) Alternate source of power Required MR Each floor Provided 5) Hooter's Location MR

8.	MOEFA Required P				
9.		Required	Provided	MR	
10.	Public Address System	Required	Provided	MR	
	Automatic Sprinkler System 1) Basement		1		
	2) Upper floors	N/A	N/A	N/A	
	3) Sprinkles al. C.	N/A	N/A	N/A	
	 Sprinkler above false ceiling 	N/A	N/A	N/A	
11.	Internal Hydrants				
	1) Size of rice //		v)		
	1) Size of riser/down-comer	100mm	100mm	MR	
	2) Number of hydrants per floor	01	01	MR	
	3) Hose box	-		1	
12.	Yard Hydrants	01	01	MR	
	1) Total number of hydrants	1500		T. T. T.	
	2) Hose box	N/A	, N/A	N/A	
13.	Pumping Arrangement	N/A	N/A	N/A	
	1) Ground level	4			
	a) Discharge of main	N/A	N/A	N/A	
	pump	N/A	N/A	N/A	
	b) Head of main pump			1	
	C) Number of main min	N/A	. N/A	N/A	
	d) Jockey pump out put		N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A	
	f) Stand by pump output	N/A	N/A	N/A	
	B) Stand by numn head		N/A	N/A	
	h) Auto starting/Manual	N/A N/A	N/A	N/A	
	stopping	N/A	. N/A	N/A	
	2) Terrace level	F	2 40		
	a) Discharge of pump	450 LPM	450 7 7		
	b) Head of pump	30 mtr.	450 LPM	MR	
	c) Power supply	Required	30 mtr.	MR	
	d) Auto starting of pump	Required	Provided Provided	MR	
14.			Flovided	MR	
	Captive Water Storage for F	ire Fighting		1	
	Under ground tank Draw-off connection	N/A	N/A	NIA	
	a) Draw-off connectionb) Fire service inlet	N/A	N/A	N/A N/A	
	c) Access to tank	N/A	N/A	N/A	
	d) Over head tank	Required	Provided	MR	
	capacity	5000 ltr.	5000 ltr.	MR	
5.	Exit Signage.	D .	2 4 1	I WIK	
6.	Provision of Lifts.	Required	Provided	MR	
		152			
	a) Pressurization of lift shaft	N/A	N/A	N/A	
	b) Pressurization of lift	N//		TVA	
	lobby	N/A	2 N/A	N/A	
	c) Communication in	Dage			
	lift car	Required	Provided	MR	
	d) Fireman's switch	Dogu-		1	
	e) Lift signage	Required	Provided	MR	
	0/ 1/ 5	Required	Provided	MR	
	D.C.	Required	Provided	MR	
).		N/A	N/A	N/A	
	Fire Control Room	N/A	N/A	100 100 000	
	a) Detector system	N/A	N/A	N/A	
	panel		IV/A	N/A	
	b) Flow switch panel	N/A	N/A	3.77	
		N/A	N/A N/A	N/A	
Mar.		N/A	N/A N/A	N/A	
	,	zutint√m ki	IVA	N/A	
		y W			

	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any: ABC & CO ₂		MR	

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2022/345 dated 14.07.2022, renewal under rule 37 of the Delhi Fire Service rules 2010, is recommended up to third floor only.

Signature of the Inspecting Officer
Name: - C.L. Meena
Designation: - ADO (RN)

DOJEC

16/4/25

Sycho (mos) Liv Bayley

24 (41) 2015

Dinector

Any RA

As approved, F.T. letter is Purus For your signature blacks. ____

Director (Dr.)

01/5/25

P