

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001

No.F.6/DFS/MS/EH/2025/SZ/216

Dated..02./06./2025

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of **M/s Platinum Restaurant** located at 137/9 Aruna Asaf Ali Marg, Vasant Kunj, New Delhi 110070 comprised of Ground and Mezzanine floor owned/occupied by Unit of PLUTOS EXIM Pvt Ltd was issued Fire Safety Certificate by this department vide letter No. F6/MS/DFS/EH/2017/SZ/978 dated 30/03/2017 for ground floor. The restaurant premise was re-inspected by the officers concerned of this department on 21/05/2025 in the presence of Mr. Surender Bist and found that there is addition of mezzanine floor. Now Restaurant running at **Ground & Mezzanine floor** have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy **Class D "Assembly Building"** Restaurant running at **Ground & Mezzanine floor only** and **validity upto 31/03/2028** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 02/06/2025 at New Delhi by


(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police (Lic/Branch) 1st Floor PS Defence Colony, New Delhi 110049 (Ref. MCD Portal 2025050708069 dated 07/05/2025)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

INSPECTION REPORT

2	Name & Address of the Building	M/s Platinum Restaurant at 137/9 Aruna Asaf Ali Marg, Kishangarh, New Delhi 110070		
3	Type of Occupancy	Restaurant at Ground & mezzanine floor		
4	Building Comprised of	Ground & Mezzanine floor		
5	Type of Case	Addition alteration		
6	Details of Previous NOC	F6/MS/DFS/EH/2017/SZ/978 dated 30/03/2017 for ground floor.		
7	Fire Safety Directives Letter No	Nil		
8	Date of Inspection	21/05/2025		
9	Name of the Inspecting Officers	Mr. Suman Kumar ADO		
10	Name & Designation of Officers from the building side	Mr. Raj Kumar		
11	Year of construction	2012		
12	Applicant letter No.	MCD Portal 2025050708069 dated 07/05/2025		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	UBBL/ NBC- 2016	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	<ul style="list-style-type: none"> Road width Gate width Width of internal road 	09 mtr	Provided	MR
		Required	Provided	MR
		N/A	N/A	N/A
2	Number, width, type & arrangement of exits.			
	a) Number of Staircase			
	➤ Upper floors.	02 No	Provided	MR
	➤ Basement floor.	N/A	N/A	N/A
	b) Width of Staircase			
	➤ Upper floors	1.50 mtr each	1.50 mtr each	MR
	➤ Basement floor	N/A	N/A	N/A
	c) Protection of exits			
	➤ Fire check door	N/A	N/A	N/A
	➤ Pressurization	N/A	N/A	N/A
	d) No. of continuous staircase to terrace	Required	Provided	MR
	e) Width of corridor	N/A	N/A	N/A
	f) Door size	1.50 mtr	1.80m & 2 x 1.50m	MR
3	Compartmentation.			
	<ul style="list-style-type: none"> Fire check door. Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. 	Required	Provided	MR
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
4	Smoke Management system.			
	<ul style="list-style-type: none"> Basement Upper floors 	NA	N/A	N/A
		12 ACPH	Exhaust fan	MR
5	Fire Extinguishers.			
	<ul style="list-style-type: none"> Total numbers Types ISI Marking 	06 Nos	06 Nos	MR
		ABC/CO ₂	ABC- & CO ₂	MR
		ISI marked	Provided	MR
6	First Aid Hose Reels.			
	<ul style="list-style-type: none"> Total numbers on each floor. Length of hose-reel hose. 	One	Provided	MR
		30m	Provided	MR

	• Nozzle Diameter	5mm	Provided	MR
7	Automatic fire detection & alarming system.			
	• Type of detectors	N/A	N/A	N/A
	• Location of Main Panel	N/A	N/A	N/A
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooter's location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System	Required	Provided	MR
10	Automatic Sprinkler System			
	• Basement	N/A	N/A	N/A
	• Ground/ upper floors.	N/A	N/A	N/A
	• Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.			
	• Size of Riser/Down-comer	Required	Provided	MR
	• Number of Hydrant per floor	Required	Provided	MR
	• Hose box.	Required	Provided	MR
12	Yard Hydrants.			
	• Total number of hydrants.	N/A	N/A	N/A
	• Hose box.	N/A	N/A	N/A
13	Pumping arrangements.			
	• Ground Level			
	➤ Discharge of main pump.	N/A	N/A	N/A
	➤ Head of main pump.	N/A	N/A	N/A
	➤ Number of main pumps.	N/A	N/A	N/A
	➤ Jockey Pump output.	N/A	N/A	N/A
	➤ Jockey Pump head.	N/A	N/A	N/A
	➤ Standby Pump output.	N/A	N/A	N/A
	➤ Standby Pump head.	N/A	N/A	N/A
	➤ Auto Starting/Manual Stopping.	N/A	N/A	N/A
	➤ Pump house access.	N/A	N/A	N/A
	• Terrace Level			
	➤ Discharge of pump.	450 LPM	Provided	MR
	➤ Head of pump.	40m	Provided	MR
	➤ Power supply.	Required	Provided	MR
	➤ Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.			
	• Underground tank capacity.	N/A	N/A	N/A
	➤ Draw-off connection.	N/A	N/A	N/A
	➤ Fire Service Inlet.	N/A	N/A	N/A
	➤ Access to tank.	N/A	N/A	N/A
	• Overhead tank capacity.	20,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	• Pressurization of lift shaft.	N/A	N/A	N/A
	• Pressurization of lift lobby.	N/A	N/A	N/A
	• Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	• Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			

MR	19	Fire Control Room.	Total area	N/A	N/A	N/A
			Location	N/A	N/A	N/A
N/A	20	Special Fire Protection System for the Protection of special Risk, if any.	Detector system panel.	N/A	N/A	N/A
N/A			Flow switch panel.	N/A	N/A	N/A
N/A			PA system panel.	N/A	N/A	N/A
			Battery backup.	N/A	N/A	N/A
			Building floor plan.	N/A	N/A	N/A
				N/A	N/A	N/A

The fire protection system provided in the building were randomly checked and found functional at the time of inspection. The building is comprised of ground & mezzanine floor having with separate entry/ exit. An affidavit submitted by the management in the concerned is endorsed at C/194 & 193.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 80 dated 21/02/2024.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

22/05/2025

Signature of the Inspecting Officer
Name: Sh. Suman Kumar
Design: ADO

DO (South)

[Handwritten signatures and dates]
23/5/2025
Director

Any Sm

03/6/25

[Handwritten mark]