



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE**  
**NEW DELHI- 110 001**

No.F.6/DFS/MS/BB/2025/SZ/ 95

Dated: 06/03/2025

To,

The Executive Engineer cum Sr. Manager (E)  
Development Project Circle-II, CPWD,  
East Block-I, Level-I, R.K. Puram,  
New Delhi-110066

**Subject:-Regarding Issuance of Fire Safety Certificate in r/o Directorate of Revenue Intelligence  
Head Qaurter locate at Plot No. 11 (B), Vasnat Kunj, New Delhi.**

Sir,

Please refer to your ID no. ADG Project Delhi Region 20241205/2380 dated 17/02/2025 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department have carried out the inspection of the above mentioned business building from fire safety point of view in presence of Mr. Prabal Verma, A.E.(Civil) on dated 20/02/2025. The building comprised of basement & ground plus four upper floors. The following shortcomings were observed during the time of inspection.

1. Sealing of electrical shafts not provided.
2. Lift shaft & Lift lobby pressurization system provided but not functional at the time of inspection.
3. Building floor plan not provided in fire control room.
4. Special Fire Protection not provided in the HT/LT panel room/electrical sub-station as per UBBL.

In view of above, the application for issuance Fire Safety Certificate is rejected. Applicant is requested to rectify the above said shortcomings at the earliest and resubmitted the application for further necessary action.

Yours faithfully

(ATUL GARG)  
DIRECTOR

DELHI FIRE SERVICE

2.