

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6 /DFS/MS/Industrial/SZ/2025/ 554

Dated: 26/11 /2025

To,

The Authority Signatory, Plot No. 52, Ohkla Industrial Area, Phase – I, New Delhi – 110020.

Subject: - Regarding grant of Fire Safety Certificate in r/o M/s Plot No. 52, Ohkla Industrial Area, Phase – I, New Delhi – 110020.

Sir,

This has a reference to your Outdoor Dairy No. 6362 dated 24/09/2025, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officers concerned of this department on 03/11/2025 in the presence of Mr. Anil Kumar Lamba and observed that building comprised of Basement, Ground plus two upper floors and following shortcomings were observed during time of inspection:

- 1. Hose reel hose provided but nonfunctional.
- 2. Automatic Sprinkler concealed with false ceiling at ground floor.
- 3. Fire pump of 900 LPM provided but nonfunctional.
- 4. Exit Signage's and lift signage's found removed.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

O(A.K. Malik)

Dy. Chief Fire Officer

Delhi Fire Service

Copy to: -

1. The Executive Engineer (Building), South DMC, Jal Vihar, Lajpat Nagar, New Delhi - 110024.