

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/EH/2025/SZ/ 252

Dated: 02/07/2025

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s Jubilant Foodworks Ltd (Dominos Pizza) located at Ground Floor, Plot No 268, Block-A, Defence Colony, New Delhi 110024 comprised of Basement, Ground plus Three upper floors owned/occupied by M/s Jubilant Foodworks Ltd have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and verified by the officer concerned of this department on 23/06/2025 in the presence of Mr. Kapil and found that the said building / premises is fit for occupancy Class Group-D "Assembly Building" (Restaurant running at Ground floor only) and Validity upto 31/03/2028 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 02/07/2025 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

1. The Public Health Officer, Health Department, MCD, Central Zone, Jal Vihar Lajpat Nagar, New Delhi 110024. (Ref. MCD Portal ID 2025060409615 dt 04/06/2025)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire-fighting

4. The basement shall be used as per the provisions of UBBL/NBC Part- IV.

5. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

	Name & Address of the Building	ON REPORT	आज़ार	री का			
	Name & Address of the Building	M/s Jubilant Foodworks Ltd (Dominos Pizza) located at Ground Floor, Plot No 268, Block-A, Defence Colony, New Delhi 110024.					
- 7	Type of Occupancy						
E.0	Type of Occupancy	Group-D-4 Assembly					
-	Building Comprised of	Basement, Ground plus Three upper floors					
	Type of Case	New Case					
	Details of Previous NOC	Nil					
	Fire Safety Directives Letter No	UBBL / NBC - 2016					
	Date of Inspection	23/06/2025					
	Name of the Inspecting Officers		Suman Kumar ADO				
147	Name & Designation of Officers from the building side	Mr. Kapil					
0	Year of construction	2000 Restt. ru	nning at Ground floo	4 04/06/2025			
11	Applicant letter No.	MCD Portal ID 2025060409615 dt 04/06/202					
S.No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	UBBL 2016 requirements	Provided at Site	Remarks MR/NMR			
1	Access to Building.	-1V	Ta 11 1	LMD			
	Road width	06 mtr	Provided	MR N/A			
	Gate width	N/A	N/A	N/A			
	Width of internal road	N/A	N/A	INA			
2	Number, width, type & arrangement of exits.						
		Restaur	ant at Ground floo	or only			
	Number of Staircase	N/A	N/A	N/A			
- 6	Upper floors.	N/A	N/A	N/A			
	Basement floor.		7281421 1 16				
	Width of Staircase	N/A	N/A	N/A			
A	Upper floors	N/A	N/A	N/A			
A	Basement floor		(6.89.1	Lago			
	Protection of exits Fire check door	N/A	N/A	N/A			
	Fire check door Pressurization	N/A	N/A	N/A			
	No. of continuous staircase to terrace	N/A	N/A	N/A			
	Width of corridor	N/A	N/A	N/A MR			
	Door size	1.50 mtr each	Provided	IVIK			
2	Compartmentation.	771		17.3			
3		N/A	N/A	N/A			
	Fire check door.	N/A	N/A	N/A			
7	Sealing of electrical shafts.	N/A	N/A	N/A			
	Fire rating of shaft door.	N/A	N/A	N/A			
	Water curtain	N/A	N/A	N/A			
	Fire dampers.		gri (Toronia)				
4	Smoke Management system.	10 ACDII	N/A	N/A			
	Basement	12 ACPH 12 ACPH	N/A	N/A			
	Upper floors	12 ACFT	1111				
5	Fire Extinguishers.		Provided	MR			
	Total numbers	03 Nos	ABC & CO ₂	MR			
	Types	ABC/CO ₂	Provided	MR			
	ISI Marking	ISI marked	Librided	1041444			
6	First Aid Hose Reels.	01 Nos	Provided	MR			
	Total numbers on each floor.	30m	Provided	MR			
	Length of hose-reel hose.	5mm	Provided	MR			
-	Nozzle Diameter			nyll			
7	Automatic fire detection & alarming sy	N/A	N/A	N/A			
-	Type of detectors Location of Main Panel	N/A	N/A	N/A			
	r Jetion of Main Palici	N/A	N/A	N/A			

	Alternate source of power	Table		नादी का मृत महे
	Hooter's location	N/A	N/A	N/A
3	MOEFA	N/A	N/A	N/A
	Public Address System	Required	Provided	MR
0	Automatic Sprinkler System	N/A	N/A	N/A
	Basement Sprinkler System			IN/F
		N/A	N/A	N/A
	Ground floor & upper floor	N/A	N/A	
1	Sprinkler above false ceiling	N/A	N/A	N/A
	Internal Hydrants.		1 - 1/4 -	N/A
	Size of Riser/Down-comer	100 mm	Provided	100
	Number of Hydrant per floor Hose box.	One	Provided	MR
2		One	Provided	MR
2	Yard Hydrants.		Trovided	MR
	Total number of hydrants.	N/A	N/A	1
2	Hose box.	N/A	N/A	N/A
3	Pumping arrangements.		IVA	N/A
	Ground Level			
	Discharge of main pump.	N/A	NT/A	
	Head of main pump.	N/A	N/A	N/A
	Number of main pumps		N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head	N/A	N/A	N/A
	Standby Pump output	N/A	N/A	N/A
	Standby Pump head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
	Pump house access.	N/A	N/A	N/A
ŀ		N/A	N/A	N/A
- 1	Terrace Level		10, 100,	IVA
	Discharge of pump.	450 LPM	Provided	100
	Head of pump.	40m		MR
	Power supply.	3077 (A-708) A	Provided	MR
	Auto starting of pump.	Required	Provided	MR
4	Captive water storage for fire fighting.	Required	Provided	MR
	Underground tank capacity.	NI/A	137/1	
	Draw-off connection.	N/A	N/A	N/A
	Fire Service Inlet.	N/A	N/A	N/A
	Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	N/A	N/A	N/A
5	Exit Signage.	20,000 Ltrs	Provided	MR
6	Provision of Lifts.	Required	Provided	MR
	Pressurization of lift shaft.	37/4		
	Pressurization of lift lobby.	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A
	Fireman's switch.	N/A	N/A	N/A
	Lift signage.	N/A	N/A	N/A
7		N/A	N/A	N/A
8	Standby Power Supply	N/A	N/A	N/A
0	Refuge Area			
	Total area	N/A	N/A	N/A
0	Location	N/A	N/A	N/A
9	Fire Control Room.			
	Detector system panel.	N/A	N/A	N/A
	Flow switch panel.	N/A	N/A	N/A
	PA system panel.	N/A	N/A	N/A
	Battery backup.	N/A	N/A	N/A



	Building floor plan.			जनृत महात्सव
20	Special Fire Protection Succession	N/A	N/A	N/A
	Protection of special Risk, if any. The fire protection system for the	N/A	N/A	N/A
	The fire protection custs		= 4	- "

ction system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Suman Kumar

Design: ADO

DO (South)

letter, is but up for signature they