



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/2025/SZ/ 53

Dated: 31 / 01 / 2025

FIRE SAFETY CERTIFICATE

Certified that the **Building at Plot No. 4, Pocket No. 8, Mata Sundri Marg, New Delhi**, comprised of **Basement, Ground plus three upper floors**, owned/occupied M/s Ved Vignan Maha Vidya Peeth, have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on dated 28/01/2025 in the presence of Sh. Vipul Gupta (Architect) and that the said building/premises is fit for occupancy class "**Educational Building**" with effect from the issuance of this certificate for a period of **three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 31 / 01 / 2025 at New Delhi by


(ATUL GARG)
DIRECTOR

T. No. 011-23414000

Copy to: -

1. The Commissioner, Municipal Corporation of Delhi, Dr. S.P.M. Civic Centre, JLN Marg, New Delhi-110002 (w.r.t. online request Id. No. 10114576 dated 21/01/2025)
2. Mr. Mahesh Gupta, M/s Ved Vignan Maha Vidya Peeth at Plot No. 4, Pocket No. 8, Mata Sundri Marg, New Delhi-110001

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection.
3. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
4. Presently, basement is lying vacant.
5. All the staff members must know the correct method of operation of fire-fighting system.
6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
7. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, prior to its expiry.

INSPECTION REPORT

1	Name & Address of the Building	Building at Plot No. 4, Pocket No. 8, Mata Sundri Marg, New Delhi-110001		
2	Type of Occupancy	Educational Building		
3	Building Comprised of	Basement, Ground + 03 Upper Floors.		
4	Type of Case	New		
5	Details of Previous NOC	Nil		
6	Fire Safety Directives Letter No	F6/DFS/MS/BP/2023/92 dated 21/03/2023		
7	Date of Inspection	28/01/2025		
8	Name of the Inspecting Officers	ADO (SJ)		
9	Name & Designation of Officers from the building side	Sh. Vipul Gupta (Architect)		
10	Year of construction	2024		
11	Applicant letter No. / Online request	ID: 10114576 dated 21/01/2025		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	NBC/UBBL Requirement	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	• Road width	06 mtr	10 mtr	MR
	• Gate width	-NA-	-NA-	-NA-
	• Width of internal road	-NA-	-NA-	-NA-
2	Number, width, type & arrangement of exits.			
	a) Number of Staircase			
	➤ Upper floors.	02 Nos	Provided	MR
	➤ Basements	02 Nos	Provided	MR ✓
	b) Width of Staircase			
	➤ Upper floors	2.0 mtr	2.0 mtr	MR
	➤ Basement floor	1.5 mtr	2.0 mtr	MR ✓
	c) Protection of exits			
	➤ Fire check door	Required	Provided	MR ✓
	➤ Pressurization	-NA-	-NA-	-NA-
	d) No. of continuous staircase to terrace	02 Nos	Provided	MR
	e) Width of corridor	-NA-	-NA-	-NA-
	f) Door size	1.5 mtr	1.5 mtr	MR
3	Compartmentation.			
	• Fire check door.	Required	Provided	MR ✓
	• Sealing of electrical shafts.	Required	Provided	MR ✓
	• Fire rating of shaft door.	-NA-	-NA-	-NA-
	• Water curtain	Required	Provided	MR
	• Fire dampers.	-NA-	-NA-	-NA-
4	Smoke Management system.			
	• Basement	12 ACPH	Provided	MR ✓
	• Upper floors	12 ACPH	Natural Ventilation	MR
5	Fire Extinguishers.			
	• Total numbers	20 Nos	20 Nos	MR ✓
	• Types	ABC/CO ₂	CO ₂ , & ABC	MR
	• ISI Marking	ISI marked	Provided	MR
6	First Aid Hose Reels.			
	• Total numbers on each floor.	01 No.	Provided	MR
	• Length of hose-reel hose.	30m	30m	MR
	• Nozzle Diameter	5mm	5mm	MR

87 6

7	Automatic fire detection & alarming system.			
	• Type of detectors.	-NA-	-NA-	-NA-
	• Location of Main Panel	-NA-	-NA-	-NA-
	• Location of Repeater Panel	-NA-	-NA-	-NA-
	• Alternate source of power	-NA-	-NA-	-NA-
	• Hooter's location	-NA-	-NA-	-NA-
8	MOEFA	-NA-	-NA-	-NA-
9	Public Address System	-NA-	-NA-	-NA-
10	Automatic Sprinkler System			
	• Basement	Required	Provided	MR
	• Upper floors	-NA-	-NA-	-NA-
	• Sprinkler above false ceiling	-NA-	-NA-	-NA-
11	Internal Hydrants.			
	• Size of Riser/Down-comer	-NA-	-NA-	-NA-
	• Number of Hydrant per floor	-NA-	-NA-	-NA-
	• Hose box.	-NA-	-NA-	-NA-
12	Yard Hydrants.			
	• Total number of hydrants.	-NA-	-NA-	-NA-
	• Hose box.	-NA-	-NA-	-NA-
13	Pumping arrangements.			
	• Ground Level			
	➤ Discharge of main pump.	-NA-	-NA-	-NA-
	➤ Head of main pump.	-NA-	-NA-	-NA-
	➤ Number of main pumps.	-NA-	-NA-	-NA-
	➤ Jockey Pump output.	-NA-	-NA-	-NA-
	➤ Jockey Pump head.	-NA-	-NA-	-NA-
	➤ Standby Pump output.	-NA-	-NA-	-NA-
	➤ Standby Pump head.	-NA-	-NA-	-NA-
	➤ Auto Starting/Manual Stopping.	-NA-	-NA-	-NA-
	➤ Pump house access.	-NA-	-NA-	-NA-
	• Terrace Level			
	➤ Discharge of pump.	2 x 450 LPM	2 x 450 LPM	MR
	➤ Head of pump.	Required	40m	MR
	➤ Power supply.	Required	Provided	MR
	➤ Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.			
	• Underground tank capacity.	-NA-	-NA-	-NA-
	➤ Draw-off connection.	-NA-	-NA-	-NA-
	➤ Fire Service Inlet.	-NA-	-NA-	-NA-
	➤ Access to tank.	-NA-	-NA-	-NA-
	• Overhead tank capacity.	15,000 Ltr	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	• Pressurization of lift shaft.	-NA-	-NA-	-NA-
	• Pressurization of lift lobby.	-NA-	-NA-	-NA-
	• Communication in lift car.	Required	Provided	MR
	• Fireman's switch.	Required	Provided	MR
	• Lift signage.	Required	Provided	MR
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	• Total area	-NA-	-NA-	-NA-
	• Location	-NA-	-NA-	-NA-

19	Fire Control Room.			
	• MOEFA System Panel.	-NA-	-NA-	-NA-
	• Flow switch panel.	-NA-	-NA-	-NA-
	• PA system panel.	-NA-	-NA-	-NA-
	• Battery backup.	-NA-	-NA-	-NA-
	• Building floor plan.	-NA-	-NA-	-NA-
20	Special Fire Protection System for Protection of Special Risk, if any.	-NA-	-NA-	-NA-

The fire protection systems provided in the building were test checked and found functional at the time of inspection. The shortcomings issued and communicated by this department vide letter No. F.6/DFS/MS/2024/NDZ/616 dated 08/11/2024 found complied.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety as required under the rules, grant of the fire safety certificate, under rule 35 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Suman
29/11/25
Signature of the Inspecting Officer
Name: Santosh Kumar
Designation: ADO (SJ)

DO (CD)

Ed
29/11/25

Dy. C.F.O (1x02)

Liv P
30/11/25

C.F.O

This is ISI case. Team of officers (Fire) should inspect the new building as per Rule 35(3).

Thugh
30/11/2025

Director

yes I agree, for further we should do this.

Chit Hq
31/11/2025

ADYJ

Sir, FT letter is pending for your sig. pl

Director
31/11/25

Md

Thugh
31/11/25

Suman
31/11/25