## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

अप्रादी व अमृत महोत्सव

No. F6/DFS/MS/GH/NDZ/2025/205

Dated: 16 04 2015

#### FIRE SAFETY CERTIFICATE

Certified that the Prakash Dx. Guest House located at 7864, Arakashan Road, Pahar Ganj, New Delhi-110055, comprised of Ground + 04 upper floors: Ground floor - Reception, 1st floor to 3rd floor - 03 guest rooms each, 4th floor (an affidavit dated 20.12.2019 not to use any floor above third floor submitted by the owner), was granted Fire Safety Certificate (FSC) by this department vide letter no. F.6/DFS/MS/GH/NDZ/2022/46 dated 25.01.2022 for total for 09 guest rooms. The premises was re-inspected by officer concerned of this department on 07.04.2025 in presence of Mr. Lalit (Manager) and found that guest house has complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of Group 'A (Residential) sub division A-1, total 09 guest rooms (Ground floor - Reception, 1st floor to 3rd floor- 03 guest rooms each) with effect from 16.04.25..and valid upto 31.03.2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on 16 04 2025 at New Delhi by

(Aful Garg)
Director
i Fire Service

Reference: elt.mcdonline application no. 2025032004135.

Copy to-

1. The Commissioner, MCD, Dr. S.P.M. Civic Centre, Minto Road, New Delhi-110002:- To ensure the occupancy as detailed above.

# Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 7. The means of escape shall be kept unobstructed/unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

1	Name & address of the building  Building is comprised of  Type of occupancy		M/s Prakash Dx. Guest House located at 7864 Arakashan Road, Pahar Ganj, New Delhi- 110055.  Ground + 04 upper floors Ground floor - Reception + 02 room (sealed by brick wall) First floor - 03 Guest rooms + 02 room (sealed by brick wall) Second floor -03 Guest rooms + 02 room (sealed by brick wall) Third floor -03 Guest rooms + 02 room (sealed by brick wall) Fourth floor - 01 guest room & staff room (given affidavit dated 20.12.2019 regarding not to use any floor above third floor) Residential Sub Division- A-1					
3								
4			Renewal	VALUE OF THE PARTY				
	Type of case  Details of previous FSC			ID7/2022/46 dated	25.01.2022			
			F.6/DFS/MS/GH/NDZ/2022/46 dated 25.01.2022					
6	Fire	safety directive letter no.	Nil 07.04.2025					
7	Date	of inspection						
8	Nam	e of the inspecting officers	Rajesh Kumar Shu	kla, ADO (M. Road	1)			
9	Name of the designation of officer From the building side		Mr. Lalit (Manager)					
10		of construction	Before 2001					
11	App	licant's letter no.	elt.mcdonline appl	ication no. 2025032	004135			
	Minimum standard of Fire Prevention and Fire Safety U/R 33		Requirement as per Rule 35 (6)	Provide at site	Remarks MR/NMR			
1	Acc	ess to Building	Les	105	MR			
	A	Road width	NA	2.5 m	NA NA			
	В	Gate width	NA NA	NA NA	NA NA			
	C	Width of internal roads		INA	INA			
2	-	Number, Width, Type & Arrangement of Exits  A No. of staircase:						
	A	AND	11-2	l no.	MR			
1	1	a) Upper floor	l no.	NA	NA			
		b) Basements	IVA	INA	141			
	В	Width of the staircase:	0.80 m	1.0 m	MR			
		a) Upper floors b) Basements	NA	NA NA	NA			
	C	Protection of exits	INA	IVA	1101			
			NA	NA	NA			
		a) Fire check door b) Pressurization	NA NA	NA NA	NA			
×	D	No. of continuous staircase to	l no.	l no.	MR			
		terrace:						
	E	terrace: Width of the corridor	NA	NA	NA			
	E	TOWNSHIELD .	NA 1.0 m	NA 1.0 m	NA MR			
3	F	Width of the corridor Door size npartmentation:		1.0 m	MR			
3	F	Width of the corridor Door size  npartmentation: Fire check doors	1.0 m	1.0 m	MR NA			
3	Cor A B	Width of the corridor Door size  npartmentation: Fire check doors Sealing of horizontal & vertical opening	NA NA	NA NA	NA NA			
3	F Con A B	Width of the corridor Door size  npartmentation: Fire check doors Sealing of horizontal & vertical opening Fire rating of shaft doors	NA NA NA	NA NA NA	NA NA NA			
3	F Con A B C D	Width of the corridor Door size  npartmentation: Fire check doors Sealing of horizontal & vertical opening Fire rating of shaft doors Water curtain	NA NA NA NA	NA NA NA NA	NA NA NA NA			
3	F Cor A B C D E	Width of the corridor Door size  npartmentation: Fire check doors Sealing of horizontal & vertical opening Fire rating of shaft doors Water curtain Fire dampers	NA NA NA	NA NA NA	NA NA NA			
	F Cor A B C D E	Width of the corridor Door size  npartmentation: Fire check doors Sealing of horizontal & vertical opening Fire rating of shaft doors Water curtain	NA NA NA NA	NA NA NA NA	NA NA NA NA			
	F Con A B C D E Sn	Width of the corridor Door size  npartmentation: Fire check doors Sealing of horizontal & vertical opening Fire rating of shaft doors Water curtain Fire dampers noke Management System:	NA NA NA NA NA	NA NA NA NA NA NA	NA NA NA NA NA NA			
	F Con A B C D E Sm A B	Width of the corridor Door size  npartmentation: Fire check doors Sealing of horizontal & vertical opening Fire rating of shaft doors Water curtain Fire dampers loke Management System: Basements	NA NA NA NA NA NA	NA NA NA NA NA NA	NA NA NA NA NA			
4	F Con A B C D E Sm A B	Width of the corridor Door size  npartmentation: Fire check doors Sealing of horizontal & vertical opening Fire rating of shaft doors Water curtain Fire dampers noke Management System: Basements Upper floors	NA NA NA NA NA NA NA NA Required	NA NA NA NA NA NA NA NA Exhaust Fans	NA NA NA NA NA NA NA NA NA			
4	F Con A B C D E Sn A B Fir	Width of the corridor Door size  npartmentation: Fire check doors Sealing of horizontal & vertical opening Fire rating of shaft doors Water curtain Fire dampers noke Management System: Basements Upper floors e Extinguishers	NA NA NA NA NA NA	NA NA NA NA NA NA	NA NA NA NA NA			

لبأ

### 2125

+	OTHER DESIGNATION.	st Aid Hose Reel Total no. at each floor	l no.	l no.	MR	
- No		Length of hose reel	30 m	30 m.	MR	
- 1	0	Normala diameter	£ mm	5 mm	MR	
	Automatic Fire Detection and Alarm System (ADAS) (Required as per clause 7.31.viii, UBBL 2016).					
	A 1	The of detectors	CO detector	Provided	MR	
1	A	Type of detectors	At ground	Provided	MR	
1	B	Location of main Panel	NA	NA	NA	
	_	Location of repeater panel	Required	Provided	MR	
	D	Alternate power source Hooter's location	Required	Provided	MR	
	E		NA	NA	NA	
8		OEFA	Required	Provided	MR	
9	Pu	blic Address System tomatic Sprinkler System	Roquite			
10	-		NA	NA	NA	
	A	Basement Linner floor	NA	NA	NA	
	B	Upper floor Sprinklers above false ceiling	NA	NA	NA	
••	C		****			
11	-	ternal hydrants Size of the riser/down comer	NA	NA	NA	
	A		NA	NA	NA	
	B	The state of the s	NA	NA	NA	
	C		1.17.1	Landston Sept.		
12	_	Total no. of hydrants	NA	NA	NA	
	A		NA	NA	NA	
••			1112	NOW IN		
13	-	Imping arrangements Ground Level				
	A	a) Discharge & head of main	NA	NA	NA	
			1111	2.00		
		pump	NA	NA	. NA	
		b) Number of main pump	NA	NA	NA	
	1	c) Discharge & head of jockey	INA	INA.		
		pump	NA	NA	NA	
		d) Discharge & head of Standby	NA.	IVA	IVA	
		pump	NA	NA	NA	
	-	e) Auto starting/ manual stopping	INA	INA	INA	
	В	Terrace Level	205 7 77 6		Lvm	
	1	a) Discharge of terrace	225 LPM	Provided	MR	
		pump	100		1 200	
		b) Head of terrace pump	30 m	Provided	MR	
	-	c) Alternate power supply	Required	Provided	MR	
		d) Auto starting of pump	Required	Provided	MR	
14	Ca	aptive Water Storage for Fire Figl	nting			
	A	Underground tank capacity	NA	NA	NA	
	В	Draw off connection	NA	NA	NA	
	C	Fire Service Inlet	NA	NA	NA	
	E	Access to tank	NA	NA	NA	
	D	Overhead tank capacity	2,500 ltrs	5,000 ltrs	MR	
15	E	xit Signage	Required	Provided	MR	
16	_	rovision of lift		11011000	MIK	
	A		NA	NA	NIA	
	В		NA NA		NA	
	C			NA	NA	
	D		NA	NA	NA	
	E		NA	NA	NA	
17			NA	NA	NA	
	3	tandby Power Supply	Required	Provided	MF	

M/s Prakash Dx. Guest House located at 7864, Arakashan Road, Pahar Ganj, New Delhi-110055.





M/s Prakash Dx. Guest House located at 7864, Arakashan Road, Pahar Ganj, New Delhi-110055.

18	Refuge Area						
	A	location	NA	NA	NA		
	В	Total area	NA	NA	NA		
19	Fire Control Room						
	A	Fire Detection System panel	NA	NA	NA		
	В	Flow switch panel	NA	NA	NA		
	C	P A system panel	NA	NA	NA		
	D	Battery backup	NA	NA	NA		
	E	Building floor plan	NA	NA	NA		
20							
	A	A   Special Fire Protection system for Protection of Special Risk, if any:					

# LEGENDS:-Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

Note:- Two additional rooms were noticed at every floor which have been sealed with masonry wall by the owner and an undertaking/affidavit alongwith photos has been submitted by the owner in conformity with the same.

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

The shortcomings issued to the building vide letter no. F6/DFS/MS/GH/2025/88dated 18.02.2025 has been rectified by the management.

If agreed to the note above & In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F.6/DFS/MS/GH/NDZ/2022/46 dated 25.01.2022 is recommended to be renewed under Rule 37 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (M. Road)

DO (CD)

8415

C:F0-

Director

(IV)

12/4/20