GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/Hospital/WZ/2025/ 59

FIRE SAFETY CERTIFICATE

Dated: 03 02 2025

Certified that the Pushpanjali Hospital Located at RR-30, Mianwali Nagar, New Delhi-110087, comprised of basement, stilt plus four upper floors only, owned/occupied by Pushpanjali Hospital, was issued Fire Safety Certificate vide Letter No. F6/DFS/MS/Hospital/WZ/2022/90 dated 02/03/2022. The said premise was re-inspected by the officer concerned of this department on 15/01/2025 in the presence of Dr. Rakesh Sharma and found that the building/premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010, and that the premises/building is fit for occupancy class "Institutional Building" Group C with effect from concerned of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on 03 02 2025. at New Delhi by.

Director Tel. No. 011-23414000

Copy to:-.

1. The Directorate of General of Health Services, Nursing Home Cell, S-1, School Block, Shakarpur, Delhi-110092.

2. The Authorized Signatory, Pushpanjali Hospital, RR-30, Mianwali Nagar, New Delhi-110087.

Following fire safety directives must be adhered to:-

1. All the means of escape shall be kept free of all type of obstruction all the time. It should not bolt /locked.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and

method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any loss of life any property due to the non-functional of any fire safety measures, management shall be held responsible.

4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be

got verified from the concerned authorities.

5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.

6. Porta Cabin Structure on Terrace shall be removed within 30 days from the date of issue of this FSC

otherwise this FSC shall be treated as null & void.

7. All comments / directions of building Department shall always be permitted and followed.

8. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

9. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

10. The basement shall be used as per BBL.

INSPECTION REPORT

1.Name & address of the building : Pushpanjali Hospital located at RR-30, Mianwali

Nagar, New Delhi-110087

: Institutional Building 2. Type of Occupancy

: Renewal 3. Type of Case

: F6/DFS/MS/Hospital/WZ/2022/90 dated 02/03/2022 4. Details of previous NOC

5. Fire Safety directives Letter No. : F.6/DFS/MS/BP/2021/Hospital/2330 dated 05/11/2021

: 15/01/2025 6. Date of inspection

7. Name of the Inspecting Officer : Aman Kumar Lathar, ADO (JWP)

8. Name and designation of Officer

: Dr. Rakesh Sharma from the building side

: 2020-21 9. Year of Construction

Ph/Admin/Fire/309/24-25 Dated 11/12/2024

S No	fire prevention and fire safety U/R 33	BBL/NBC Requirements/ as per earlier FSC dated 02/03/2022	site		Remarks MR/NMR		
1.	Access of building	00	Dro	wided		MR	
	 Road width 	09 m	Provided Provided		-	MR	
	Gate widthWidth of internal road	05 m NA		NA		NA	
2.	Number, width, Type & Arra	ngements of exits					
2.	a. Number of staircases					· /D	
	Upper floors	02	Provided		MR		
1	Basements	02	Pr	ovided		MR	
	b. Width of staircases					1	
1	Upper floors	2.0 m x 1 & 1.5 n	n x 1	Provi	200	MR	
	Basements	2.0 m x 1 & 1.5 n	n x 1	Provi	ded	MR	
	c. Protection of exits		100				
	Fire check door	Required	P	rovided	2.0	MR	
	Pressurization	NA		NA		NA	
	d. No of continuous	02	P	Provided		MR	
	staircase to terrace	02		1011404			
	**************************************	2.40 m	2.20	to 2.40	m	MR	
	The contract of the contract o	DOMESTIC OF THE PARTY OF THE PA		rovided	-	MR	
	f. Door Size	1.25/2.0 m		Tovided		IVIIC	
3.	Compartmentation	Required	p	Provided		MR	
Į.	Fire check door			rovided	-	MR	
1	Sealing of electrical	Required	P	Tovided		IVIIC	
	shafts) TA	+	NA		NA	
	 Fire Rating of shaft 	NA		INA		INA	
	door	274		NIA	-	NA	
	Water Curtain	NA	NA D id-d			MR	
	Fire Dampers	Required	P	rovided		IVIN	
4.	Smoke managements System		-	D da a		NAD	
Ē	 Basements 	Required		rovided	_	MR	
	Upper floors	Required	- P	rovided		MR	
5.	Fire Extinguishers		1 1				
	Total numbers	30 nos.		rovided		MR	
	 Types 	ABC/CO2	_	rovided		MR	
1	IS marking	ISI marked	P	rovided	L.	MR	
6	First-Aid Hose Reels			16			
	Total numbers on	01	02			MR	
	each floor	LI LI			A	la	
	Length of hose reel	30 m	P	rovided		MR	
	_						
100	hose	A Y				MR	

N-13	•
------	---

7.	N-15			_
/.	Automatic fire detection and alarm		Provided	MR
1	Type of detectors	Required	Provided	MR
	 Location of Main Panel 	Required	Provided	
į.	Location of Repeater	Required	Provided	MR
	Panel	Doguired	Provided	MR
	Alternate source of	Required	Flovided	IVIK
	powerHooters' Location	Required	Entire building	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	Basements	Required	Provided	MR
4	Upper Floor	Required	Provided	MR
	Sprinkler above false	NR	NR	NR
	ceiling			11
11.	Internal Hydrants:		-	
	Size of riser/down-	100 mm	Provided	MR
	comer			
-	 Number of hydrants per 	02	Provided	MR
	floor			
	Hose Box	02	Provided	MR
12.	Yard Hydrants			
	 Total number of 	02	Provided	MR
	hydrants			
	Hose Box	02	Provided	MR
13			17-12-1-12	
	Ground Level	2		Į.
	 Discharge of main pump 	1620 lpm	Provided	MR
	Head of main pump	40 m	Provided	MR
	Number of main pumps	01	Provided	MR
1	> Jockey pump out put	180 lpm	Provided	MR
	➤ Jockey pump head	40 m	Provided	MR
	Standby Pump God	1620 lpm	Provided	MR
	Standby Pump HeadAuto Staring/Manual	40 m	Provided	MR
	stopping	Required	Provided	MR
	Pump House Access	Poguin- J	D., 2. 2. 1. 1	3.00
	Terrace level	Required	Provided	MR
	> Discharge of pump	NA	NA	NIA
	> Head of the pump	NA NA	NA NA	NA NA
	> Power supply	NA NA	NA NA	NA NA
	Auto starting of pump	NA NA	NA NA	NA NA
14	. Captive water Storage for firefig		4 M 5	IVA
	Underground tank	75,000 ltrs.	U.G50,000 ltr	rs. N
	capacity		Terrace-25,000	
			directly connected	to the
	g 1944 2005 U		underground ta	
	Draw off connection	Required	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Accessible	Provided	MR
1	Overhead Tank capacity Evit Signage	10,000 ltrs.	Provided	MR
-	5 Exit Signage 6. Provision of Lifts	Required	Provided	MR
-	Provision of Lifts Pressurization of Lift Share	aft NA	NA NA	NA
	 Pressurization of Lift Sha Pressurization of lift lobb 		Provided	MR
	Communication in lift Ca		Provided	MR
	Fireman's Grounding	Required	Provided	MR
	Switch	Required	Tiorided	WIIC
	➤ Lift Signage	Required	Provided	MR
-	7. Standby power supply	Required	Provided	MR
	8. Refuge Area	,		
	> Total area) NA	NA	NA
) P [Olal alea	NA NA	/A	F-00/F-0

19.	Fire control room				
k 4	Detector system panel	Required	Provided	MR	
	> Flow Switch Panel	ÑA	NA	NA	
	> PA System Panel	Required	Provided	MR	
	➤ Battery backup	Required	Provided	MR	
	➤ Building Floor Plans	Required	Provided	MR	
20.	Special Fire Protection Systems for Protection of special Risks, if any;	Required	02 nos. CO2 fi extinguishers pro- near electrical pa	vided	

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Note:- 1. Management has provided 50,000 ltrs. underground tank & 25,000 ltrs overhead tank, which is directly inter-connected in place of 75,000 ltrs underground tank.

2. Porta Cabin Structure on Terrace shall be removed within 30 days from the date of issue of this FSC otherwise this FSC shall be treated as null & void.

In view of the deemed compliance of minimum standards on fire prevention and fire safety requirements under the rules, renewal of Fire Safety Certificate issued vide letter no. F6/DFS/MS/Hospital/WZ/2022/90 dated 02/03/2022 is recommended under rule 37 of the Delhi Fire Service Rule, 2010 under DFS Act 2007.

Accordingly DFA is prepared put up for approval please.

Aman Kumar Lathar ADO (JWP)

renewal case one porter Cabin Structure is exects on terrace of Bodays lime is given to remove the above structure by the impality ran otherwise For will be null froid with automittally.

As discussed in earlier case, we are may issue short comming for above, it agreed.

(As height is given up dreyand 15 mts.)

of ochul, take Ult that tay WIM & remut 100 30dg.