

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE **NEW DELHI- 110 001**

No. F.6/DFS/MS/EH/2025/SZ/ 14-3

Dated: 22 0 4/2025

FIRE SAFETY CERTIFICATE

Certified that M/s Pyramid Tonino located at Khasra No. 76/27 Andheria More, Mehrauli, Delhi-110030, comprised of Ground floor only, owned/occupied by Parmeet Singh Sawhney this department vide letter was earlier granted **FSC** by F.6/DFS/MS/EH/2022/SZ/104 Dated 27/04/2022. The premise was re-inspected by the officer concerned of this department on 15/04/2025 in the presence of Mr. Vijay Kumar Joshi, (GM) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building, (Restaurant) with effect from 22/04/2025 valid up to 31/03/2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 22 04/2025 at New Delhi by

To,

1. The Addl. Commissioner (Lic.), 1st floor Police Station Defence Colony, New Delhi

2. The Dy Health Officer, Public Health Department, South Zone, Aurobindo Marg, Green Park, NewDelhi-110016 MCD ID No. 2025032004104, Dated- 23/03/2025

Conditions for the validity of Fire Safety Certificate

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipment and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized

6. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry. 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of

Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

8. Any flammable material for interior decoration shall strictly prohibit.

M/33

Name & address of the building

: M/s Pyramid (Tonino) at Khasra No. 76/27, Andheria More, Mehrauli, Delhi-110030

2. Building is comprised of

: Ground floor only

3. Type of Occupancy

: Group-D Assembly Building, (Restt. & Bar)

4. Type of Case

: Renewal

5. Details of Previous NOC letter

: F.6/DFS/MS/EH/2022/SZ/104 Dated 27/04/2022

6. Fire Safety directive letter No

: Nil

7. Date of Inspection

: 15/04/2025

8. Name of the Inspecting officers

: ADO (Shd.) Deepak Kumar

9. Name and designation of Officer

from the building side 10. Year of Construction

: Mr. Vijay Kumar Joshi, (GM) : 1965

11. Applicant's letter No

: 2025032004104, Dated- 23/03/2025

Sr. No.	Minimum Standards on Fire Prevention and Fire Safety U/R33	Old NOC Requirement	Provided at Site	Remarks MR/NMR		
01	Access to Building	he total a				
-17	Road width	12 mtr.	Provided	MR		
	Gate width	N/A	N/A	N/A		
	Width of internal road	N/A	N/A	N/A		
02	Number, Width, Type and Arrangen	nent of Exits	- musicinate luis in			
Air	a. Number of Staircases		I I I I I I I I I I I I I I I I I I I			
	Upper floor	N/A	Restt. At GF only	N/A		
	Basement	N/A	N/A	N/A		
	B. Width of Staircases	Linear Linear	Company of the second			
	Upper floor	N/A	N/A	N/A		
	Basement	N/A	N/A	N/A		
	c. Protection of Exits	second hard				
	Fire check door	N/A	N/A	N/A		
	Pressurization	N/A	N/A	N/A		
	d. No. of Continuous Staircases to Terrace	N/A	N/A	N/A		
	e. Width of Corridor	N/A	N/A	N/A		
	f. Door Size	02 Exits	1.50 mtr each	MR		
03	Compartmentation.	27/	and the first of the party of t			
1	Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A	N/A		
	Fire rating of shaft door	N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
	Fire dampers	N/A	N/A	N/A		
04	Smoke Management System.	n	Andrew Williams			
	Basement	N/A	N/A	N/A		
	Upper floor	12 ACPH	Provided in kitchen	MR		
05.	Fire Extinguishers					
	Total numbers	10 nos.	10 nos.	MR		
	Types	ABC /CO ₂	ABC /CO ₂	MR		
	IS marking	Required	Provided	MR		

	First-Aid-Hose Reels. Total numbers on each floor. 02 nos Provided							
	Total numbers on each floor	02 nos 30 mtr	Provided	MR MR				
	a Longth of base real base	05 mm	Provided	MR				
	Length of hose reel hoseNozzle diameter	05 11111	1100.000					
07								
_	Type of detectors	N/A	N/A	N/A				
	Location of main panel	N/A	N/A	N/A				
	Location of repeater panel	N/A	N/A	N/A				
	 Alternate source of power 	N/A	N/A	N/A				
	Hooter	N/A	N/A	N/A				
80	MOEFA	Required	Provided	MR				
09	Public Address System.	N/A	N/A	N/A				
10	Automatic Sprinkler System							
	Basement	N/A	N/A	N/A				
	upper floor	N/A	N/A	N/A				
	sprinkler above false ceiling	N/A	N/A	N/A				
11	Internal Hydrants		rana ita ang Misa					
	size of riser/down-comer	N/A	N/A	N/A				
	Number of hydrants per floor	N/A	N/A	N/A				
	Hose box	N/A	N/A	N/A				
12	Yard Hydrants							
	Total number of hydrants	N/A	N/A	N/A				
	Hose box	N/A	N/A	N/A				
13	Pumping Arrangements							
	> Ground Level							
	Discharge of main pump	N/A	N/A	N/A				
	Head of main pump	N/A	N/A	N/A				
	Number of main pumps	N/A	N/A	N/A				
	Jockey pump out put	N/A	N/A	N/A				
	Jockey pump head	N/A	N/A	N/A				
	Standby pump out put	N/A	N/A	N/A				
	Standby pump head	N/A	N/A	N/A				
	Contraction of the second of t	2.30 ÅL, ob.	1974 N. 20	(#1.80.E.) \$				
	Auto starting /manual	N/A	N/A	N/A				
	stopping	249,00	Newscap	# 1645/5				
	Pump house access	N/A	N/A	N/A				
	> Terrace Level							
	Discharge of pump	450 LPM	Provided	MR				
	Head of the pump	35 m	Provided	MR				
	Power supply	Required	Provided	MR				
	Auto starting of pump	Required	Provided	MR				
e:	Captive Water Storage for Fire Fighting							
	Underground tank capacity	N/A	N/A	N/A				
	Draw-off connection	N/A	N/A	N/A				
	Fire service inlet	Required	Provided	MR				
	Access to tank	N/A	N/A	N/A				
- 1	Overhead tank capacity	3,000 ltr.	Provided	MR				
;	Exit Signage.							

16	Provision of Lifts.							
	Pressurization of lift shaft	N/A	N/A	N/A				
	Pressurization of lift lobby	N/A	N/A	N/A				
	Communication in lift car	N/A	N/A	N/A				
	Firemen's grounding switch	N/A	N/A	N/A				
	Lift signage	N/A	N/A	N/A				
17	Standby Power Supply	Required	Provided	MR				
18	Refuge Area.							
	7-1-1	N/A	N/A	N/A				
	Total area Location	N/A	N/A	N/A				
19	Fire Control Room							
11.000	Detector system panel Flow switch panel PA system panel Battery backup	N/A	N/A	N/A				
		N/A	N/A	N/A				
		N/A	N/A	N/A				
		N/A	N/A	N/A				
		N/A	N/A	N/A				
20	Building floor plans Special Fire Protection Systems for Protection of Special Risks, if Any:	N/A	N/A	N/A				

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules, the FSC issued vide letter No. F.6/DFS/ MS/EH/2022/SZ/104 Dated 27/04/2022, renewal under rule 37 of the Delhi Fire Service rules, 201 is recommended.

Signature of the Inspecting Officer Name : Deepak Kumar

Name : Deepak Kumar Designation : ADO (Shd)

DO (South)

in) Injury

Directary Directary

(St Spelan 22 04/2025

uplous plase

5011100 5011100