



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No.F.6 DFS/MS/School/2025/SZ/738

Dated: 09/06/2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Rajeshwari Karuna School, at D-95, Sanjay Colony, Bhati Mine, New Delhi 110074 comprised of Ground plus one upper floor but school running at Ground Floor only owned/occupied by Aashalata Victoria Wilkinson Memorial C. Trust department this by Safety Certificate Fire F6/DFS/MS/School/2022/SZ/737 dated 05/07/2022 for ground floor only. The said premises was re-inspected by officer concerned of this department on 22/05/2025 in presence of Mr. Anil Wilkinson (Manager) and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class "Educational Building Group - B" (School running at Ground floor only) with effect from 09/06/2025 for a period of Three years in accordance with rule 36 unless renewed under rule37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of Delhi Fire Service Rules 2010.

Issued on <u>69/66</u>2025 at New Delhi by

(VIRENDRA SINGH) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to: -

- 1. Rajeshwari Karuna School, D-95, Sanjay Colony, Bhati Mine, New Delhi 110074.
- 2. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-54.

Conditions for the validity of Fire Safety Certificate:-

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

4/13



•	Name & Address of the Building	ON REPORT	a School, D-95, Sanjay	Colony,	
1	Name & Address of the Building	Rajeshwari Karuna School, D-95, Sanjay Colony, Bhati Mine, New Delhi 110074.			
2	Type of Occupancy	BI .: (Come D (School)			
3	Building Comprised of	Ground floor only.			
4	Type of Case	The second secon			
5	Details of Previous NOC	F6/DFS/MS/School/2022/SZ/737 dated 05/07/2022 for Ground floor only			
6	Fire Safety Directives Letter No	F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011			
7	Date of Inspection	22-05-2025			
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)			
9	Name & Designation of Officers	Mr. Anil Wilkinson (Manager)			
	from the building side				
10	Year of construction	2011 & 2024 RKS/AVNMCT/1632/2025 dated 05-05-2025			
11	Applicant letter No.	RKS/AVNMC1/1	TAC STREET		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	DOE circular requirements	Provided at Site	MR/NMR	
1	Access to Building.		5.70 mtr	Old case	
	Road width	6 mtr	4 m	=NA=	
	Gate width	₽NA²	-NA-	-NA-	
	Width of internal road	-NA-	-11/1-		
2	Number, width, type & arrangement of ex	its.			
	a) Number of Staircase		-NA-	-NA-	
	➤ Upper floors.	-NA-	-NA-	-NA-	
	➤ Basement floor.	-NA-	-11/		
	b) Width of Staircase		-NA-	-NA-	
	> Upper floors	-NA-	-NA-	-NA-	
	➤ Basement floor	-NA-	-11/1-	3,755	
	c) Protection of exits		-NA-	-NA-	
	> Fire check door	-NA-		-NA-	
	> Přessuřízátion	-NA-	-NA-	MR	
	d) No. of continuous staircase to terrace	Required	Provided	-NA-	
	e) Width of corridor	-NA-	-NA-	MR	
	n Door size	1m	Provided	MIK	
3	Compartmentation.	\$-018 EL 7	374	-NA-	
	Fire check door.	-NA-	-NA-		
	Sealing of electrical shafts.	-NA-	-NA-	-NA-	
	Fire rating of shall door.	-NA-	-NA-	-NA-	
	Water curtain	-NA-	-NA-	-NA-	
	Fire dampers.	-NA-	-NA-	-NA-	
4.	Smoke Management system.				
	Basement	-NA-	-NA-	-NA-	
	Upper floors	-NA-	-NA-	-NA-	
5.	Fire Extinguishers.	·			
7	Total numbers	06 Nos	08 Nos	MR	
	Types	ABC / CO2	ABC & Co2	MR	
	ISI Marking	ISI mark	Provided	MR	
6.	First Aid Hose Reels.				
V .	Total numbers on each floor.	-NA-	-NA-	-NA	
	Length of hose-reel hose.	-NA-	-NA-	-NA	



-	Automatic fire detection & alarming system.	A THE CA		
7	Type of detectors	-NA-	-NA-	-NA-
	Location of Main Panel	-NA-	-NA-	-NA-
	Location of Repeater Panel	-NA-	-NA-	-NA-
	Alternate source of power	-NA-	-NA-	-NA-
	Hooter's location	-NA-	-NA-	-NA-
8.	MOEFA	-NA-	-NA-	-NA-
9.	Public Address System	-NA-	-NA-	-NA-
10.	Automatic Sprinkler System			
	Basement	-NA-	-NA-	-NA-
	Upper floors	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11.	Internal Hydrants.		Haracon Con	
	Size of Riser/Down-comer	-NA-	-NA-	-NA-
	Number of Hydrant per floor	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
12.	Yard Hydrants.			98.00
14.	Total number of hydrants.	-NA-	-NA-	NA-
	Hose box.	-NA-	-NA-	-NA-
12	Pumping arrangements.		THE THEFT IN	
13.	Ground Level		4119 Del 1	
	Discharge of main pump.	-NA-	-NA-	-NA
	Head of main pump.	-NA-	-NA-	-NA
	Number of main pumps.	-NA-	-NA-	-NA
	> Jockey Pump output.	-NA-	-NA-	-NA
	> Jockey Pump head.	-NA-	-NA-	-NA
	Standby Pump output.	-NA-	-NA-	-NA
	Standby Pump head.	-NA-	-NA-	-NA
	> Auto Starting/Manual Stopping.	-NA-	-NA-	-NA
	> Pump house access.	-NA-	-NA-	-NA
	Terrace Level			N.
1	Discharge of pump.	-NA-	-NA-	-NA
- 1	> Head of pump.	-NA-	-NA-	-NA
- 1	Power supply.	-NA-	-NA-	-N/
1	Auto starting of pump.	-NA-	-NA-	-NA
	Captive water storage for fire fighting.		The second second	
14.	Captive water storage for me figuring.	-NA-	-NA-	-N
-	Underground tank capacity.	-NA-	-NA-	-N.
	Draw-off connection.	-NA-	-NA-	-N.
- 1	Fire Service Inlet.	-NA-	-NA-	-N
- 1	Access to tank.	-NA-	-NA-	-N
	Overhead tank capacity.		Provided	M
	Exit Signage.	Required	Tiovided	
16.	Provision of Lifts.	-NA-	-NA-	-N
	 Pressurization of lift shaft. 	-NA-	-NA-	-N
	 Pressurization of lift lobby. 		-NA-	-N
	 Communication in lift car. 	-NA-	-NA-	-N
- 1	Fireman's switch.	-NA-		-N
	Lift signage.	-NA-	-NA-	-N
7.	Standby Power Supply	-NA-	-NA-	-P
	Refuge Area		374	1-1
	Total area	-NA-	-NA-	-N
	• I Ulai ai Ca		-NA-	_



19.	Fire Control Room.			
	Detector system panel.	-NA-	-NA-	-NA-
	Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel.	-NA-	-NA-	-NA-
	Battery backup.	-NA-	-NA-	-NA-
	Building floor plan.	-NA-	-NA-	-NA-
20.	Special Fire Protection System for the Protection of special Risk, if any.	-NA=	-NA-	-NA-

The fire protection system provided in the building were randomly checked and found

unctional at the time of inspection.

Further, the management has complied all the observation / Shortcoming already issued & ommunicated by this department vide letter of even no 286 dated 25/04/2025. The School nanagement submitted an undertaking that we will not use the 1st floor of the building without etting fire NOC from Delhi Fire Service.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and safety measures as required under the rules, the FSC issued vide letter no 6/DFS/MS/School/2022/SZ/737 dated 05/07/2022, renewal under rule 37 of the Delhi Fire Service

iles, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

approved, F.T. Letter en pulits your synature of All