## **GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI** HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No. F.6/DFS/MS/School/2025/SZ/ 218

Dated:

07/03/2025

## FIRE SAFETY CERTIFICATE

Certified that the Rajni Memorial Public School located at Plot No.-14,15,16, Sainik Enclave, Vikas Nagar, New Delhi-110059, comprised of ground floor only, having total 06 rooms (including Class Rooms & Office etc.) owned/occupied by Rajni Memorial Public School was issued FSC by this department vide letter No. F.6/DFS/MS/School/2022/SZ/191 dated 18.02.2022. The School building was re- inspected by the officer concerned of this department on dated 04.03.2025 in the presence of Sh. Kamal Lal Bansal (Manager), and found that the School building have complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/premises (Ground floor only) is fit for occupancy class "Educational Building" w.e.f. 07/03 2025 for a period of three years, subject to compliance of the conditions printed below.

Issued on 67/03/2025 at New Delhi.

Director

Delhi Fire Service

Copy to: -

1. The Manager, Rajni Memorial Public School located at Plot No.-14,15,16, Sainik Enclave, Vikas Nagar, New Delhi-110059.

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

## Conditions for validity of fire safety certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior



## **INSPECTION REPORT**

1. Name & address of the building: Rajni Memorial Public School, Plot No.-14,15,16, Sainik Enclave, Vikas

Nagar, New Delhi-110059

Building comprised of Ground floor only. 3. Type of Occupancy Educational 4. Type of Case Renewal

5. Details of Previous NOC F.6/DFS/MS/School/2022/SZ/191 dated 18.02.2022

6. Fire Safety directives letter No N/A 7. Date of inspection 04.03.2025

8. Name of Inspecting Officer A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side Sh. Kamal Lal Bansal (Manager)

10. Year of Construction 1999

S. No.	Minimum Standards on fire prevention and fire safety U/R 3	Requirements 3	Provided at site	Remarks MR/NMR
1.	Access to building			
	Road width	Accessible	05 m	M/R, old cas
	<ul> <li>Gate width</li> </ul>	4.5 m	Directly accessible from ro	
	<ul> <li>Width of internal road</li> </ul>	N/A	N/A	N/A
2.	Number, Width, Type & Arrang	ement of Exits		
	a. Number of staircases			
	Upper Floors	N/A	N/A	GF Only
	Basements	N/A	N/A	N/A
	b. Width of staircases		IVA	N/A
	Upper Floor	N/A	NT/A	
	Basements     Protection of exits		N/A	GF Only
	Fire check door	N/A	N/A	N/A
	Pressurization	and the state of t		
	riessurization	N/A	N/A	N/A
		N/A	N/A	N/A
	d. No. of continuous staircases to			
	terrace	N/A	N/A	N/A
	e. Width of Corridor	N/A	N/A	N/A
	f. Class Room Door Size	1.0 m	.90 to 1.06m (Single door)	M/R,being old case Students are less than
	Compartmentation			45 in each class.
	Fire check door	N/A	N/A	N/A
1	<ul> <li>Sealing of electrical shafts</li> </ul>	N/A	N/A	
	<ul> <li>Fire Rating of shaft door</li> </ul>	N/A	N/A	N/A
	<ul> <li>Water Curtain</li> </ul>	N/A		N/A
- 1	<ul> <li>Fire Dampers</li> </ul>	N/A	N/A	N/A
	Smoke Management System	IVA	N/A	N/A
	Basements	N/A	N/A	N/A
	<ul> <li>Upper floors</li> </ul>	N/A	N/A	N/A
	Fire Extinguishers			1 1111
-	Total numbers	03 no's	Deside	
	• Types	ABC/CO2 type	Provided	. M/R
	IS marking	ISI marked	Provided ISI marked	M/R
J	First-Aid Hose Reels		тот шагкед	M/R
-	Total numbers on each floor	N/A	NO . 10.70	
	Length of hose reel hose	N/A N/A	N/A	N/A
5	Nozzle diameter	N/A	N/A	N/A
A		C-765046	N/A	N/A

My

7.	Automatic fire detection and alarming s	ystem		
	Type of detectors			
	Location of Main Panel	N/A N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
8.	MOEFA		N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System	N/A	N/A	N/A
	Basement	N/A	N/A	7
	• Ground Floor	N/A	N/A	N/A N/A
	Sprinkler above false ceiling	N/A	N/A	N/A N/A
11,	Internal Hydrants		300000	IV/A
	Size of riser/down-comer	NIA		
	Number of hydrants per floor	N/A N/A	N/A	N/A
	Hose Box	N/A N/A	N/A	N/A
12.	Yard Hydrants	IVA	N/A	N/A
	<ul><li>Total number of hydrants</li><li>Hose Box</li></ul>	N/A	N/A	N/A
12	CONTRACTOR OF CO	N/A	N/A	N/A
13.	Pumping Arrangements		1	3.
	Ground Level			
	Discharge of main Pump	N/A	N/A	N//
	Head of Main pump	N/A	N/A	N/A
	➤ Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	3,000,000	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A N/A	N/A	N/A
	Standby Pump Head		N/A	N/A
	➤ Auto Starting/Manual	N/A	N/A	N/A
	Stopping	N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level		1771	IN/A
	➤ Discharge of pump	N/A	N/A	N/A
	➤ Head of the pump	N/A	N/A	N/A
	➤ Power Supply	N/A	N/A	N/A
	> Auto Starting of pump	N/A	N/A	N/A
4.	Captive Water Storage for fire fighting			
		NI/A	NT/A T	
V 1	Underground tank capacity	N/A	N/A	N/A
	<ul> <li>Draw-off connection</li> <li>Fire service inlet</li> </ul>	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
5.	Exit Signage.	N/A	N/A	N/A
16.	Provision of Lifts. (No Lift)			ft)
	Pressurization of Lift Shaft	N/A	N/A	NA
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
^	Lift Signage	N/A	N/A	NA
V	7	20		

17.	Standby power supply	N/A	N/A	N/A		
18.	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	Location	N/A	N/A	N/A		
19.	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2022/SZ/191 dated 18.02.2022, renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name: - R.K. Yadav Designation: - ADO (JKP)

DO (SW)

1 Nuc

Director