GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/NDZ/2025/ 280

Dated: 29/04/2025

FIRE SAFETY CERTIFICATE

Certified that the Ram Raj Dx Guest House, located at 7972, Arakashan Road, Paharganj, New Delhi-110055, in a building Comprised of Ground + 03 Upper Floors, Ground Floor (reception + 01 guest room + 01 office), 1st Floor to 3rd Floor (08 guest rooms at each floors) and Terrace Floor (02 staff rooms + mumty), total 25 guest rooms, owned/occupied by Ram Raj Dx Guest House, was issued FSC by this department vide letter no. F6/DFS/MS/GH/2022/353 dated 21/07/2022. Now the building/premises was re-inspected by the officer concerned of this department on 21/04/2025 in the presence of Sh. Ramvir and found that the said guest house building having given an affidavit dated 16/12/2019, regarding not to use any floor above 3rd floor and observed that all the fire prevention fire safety arrangements provided in the premises/ building found in good working condition. The premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential" Sub Division A-1 Ground Floor (Reception + 01 guest room), 1st Floor to 3rd Floor (08 guest rooms at each floor) up to 3rd Floor only, (Total 25 guest rooms), with effect from for period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010. Conditions mentioned below.

Issued on 29 04 2025 at New Delhi by.

Copy to:-

- 1. The Commissioner, MCD, Civic Centre, New Delhi. To ensure the occupancy as detailed above & deviation if any ID No. 2025040505697 dated 05/04/2025.
- 2. The Addl. Commissionr of Police (Lic), First Floor, P.S. Defence Colony, New Delhi. Email Id: (addlcp.lic-dl@nic.in)
- 3. The owner/occupier Ram Raj Dx Guest House, located at 7972, Arakashan Road, Paharganj, New Delhi-110055.

Conditions for the Validity of Fire Safety Certificate:-

- 1. The fire safety certificate shall stand null and void if no. of lodger found more than 10 at any one floor.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the risk and responsibility of managements.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation, with regards to construction shall be verified by the concerned building sanctioning agencies.
- 6. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 9. Any flammable material for interior decoration is prohibited.

Mrs

1			INSPECTION	REPORT				
1.	Name	& address of the building				VI.		
7.			DA Quest House, located at 7072 A-1					
2.	Type	of Occupancy						
3.		of Case	Residential (Guest House) Sub Division A-1 Renewal					
4.	Detail	s of previous NOC	F6/DFS/MS/GH/2022/353 dated 21/07/2022.					
5.	Fire S	afety directives letter No	Nil	1/2022/35	3 dated 21/07/2022.			
6.	Date	of inspection	21/04/2025			-6		
7.	Name	of the Inspecting Officers		10000				
8.	Name	and designation of						
	office	rs from the building side	on. Ramyn					
9.	Year	f Construction	1975 (As mor collins on 1)					
10.	FF	cant's letter No.	1975 (As per online application)					
The	guest	Applicant's letter No. Online application ID No. 2025040505697 dated 05/04/2025. guest house building comprised of Ground + 03 Upper Floors, Ground Floor (reception + 0						
staf not	f room to use s	s + mumty) (Total 25 guest any floor above 3 rd Floor.	TIOOT (IIX GUES	f roome a	t cook floor) and T	TH /0		
S.	Mi	nimum Standards on fire	Required as p	er Rule	Provided at site	Remarks		
No		ntion and fire safety U/R 33	35(6) of DFS R			MR/NMR		
1	Acces	s to building						
	•	Road width	06 mtr		06 mtr	MR		
	•	Gate width	NA	Directly	accessible from the roa	d NA		
	•	Width of internal road	NA		NA	NA		
2	Numl	er, Width, Type & Arrang	ement of Exits		a na madil			
	a. Nu	mber of staircases	4 1/2	100				
	•	Upper Floors	01 n	1901	01 no.	MR		
	L W	Basements	0.80 mtr NA		NA	NA		
	D. W10	dth of staircases						
	•	Upper Floors Basements			1.25 mtr	MR		
	a Dra	tection of exits			NA	NA		
	C. 110	Fire check door	NA		NA	NA		
		Pressurization	NA		NA NA	NA NA		
	973	of continuous staircases to terra			01	MR		
		th of Corridor			NA NA	NA		
	f. Doo		01 mtr		01 mtr	MR		
3	a management	artmentation.			VI III	04797		
	•	Fire check door	NA		NA	NA		
		Sealing of electrical shafts	NA		NA	NA		
		Fire Rating of shaft door	NA		NA	NA		
		Water Curtain	NA		NA	NA		
		Fire Dampers	NA		NA	NA		
4	Smoke	Management System.		L				
	•	Basements	NA		NA	NA		
		Upper floors	Required		Exhaust Fan	MR		
5	Fire Extinguishers							
	•	Total numbers	08 nos. CO ₂ , ABC type		08 nos.	MR		
	•	Types			ABC & CO ₂ Types	MR		
	•	IS marking	ISI marked		Provided	MR		
_	First_A	id Hose Reels.	-4					
5	T. 11 2 f V.	The state of the s	01		0.1	MR		
6	•	Total numbers on each floor	01		01	IVIIX		
6	•	Total numbers on each floor Length of hose reel hose	01 30 m	tr	30 mtr	MR		

2	V 23
_(~ A
~	~

7	Automatic fire detection and alarming system.			
	Type of detectors	Required	Provided	
	Location of Main Panel	Required	Provided	MR
	Location of Repeater Panel	NA	NA	MR
	Alternate source of power	Required	Provided	NA
	Hooters' Location	Required	Provided	MR MR
8	MOEFA	Required	Provided	MR
9	Public Address System.	Required	Provided	MR
10	Automatic Sprinkler System.		2 0 1 1	MIX
	Basement	NA	NA NA	I MA
	Upper Floor	NA	NA NA	NA NA
	Sprinkler above false ceiling	NA	NA NA	NA NA
11	Internal Hydrants			MA
	Size of riser/down-comer	NA	NA NA	NA
	Number of hydrants per floor	NA	NA	NA
	Hose Box	NA	NA NA	NA NA
12	Yard Hydrants.	la H	100 Test 100	
	Total number of hydrants	NA	NA	NA
	Hose Box	NA	NA	NA
13	Pumping Arrangements.		A 1	
	Ground Level	Carlo Tanagalori		
	➤ Discharge of main Pump	NA	NA	NA
	➤ Head of Main pump	NA	NA	NA
	➤ Number of main pumps	NA	NA	NA
	➤ Jockey Pump out put	NA	NA	NA
	➤ Jockey pump head	NA	NA	NA
	➤ Standby Pump out put	NA	NA	NA
	➤ Standby Pump Head	NA	NA	NA
1.	> Auto Starting/ Manual stopping	NA	NA	NA
	> Pump House Access	NA	NA	NA
1-1	Terrace level		2001701	1 10
	➤ Discharge of pump	225 LPM	225 LPM	MR
-	➤ Head of the pump	30 mtr	30 mtr	MR
	➤ Power Supply	Required	Provided	MR MR
	> Auto Starting of pump	Required	Provided	IVIK
14	Captive Water Storage for fire fighting		NA	NA
	Underground tank capacity	NA NA	NA NA	NA NA
	> Draw-off connection	NA NA	NA NA	NA
	➤ Fire service inlet	NA NA	NA NA	NA
	> Access to tank	NA 2 500 ltrs	2,500 ltrs	MR
	Overhead Tank capacity	2,500 ltrs Required	Provided	MR
15	Exit Signage.	Kedunen		
16	Provision of Lifts.	NA	NA	NA
	Pressurization of Lift Shaft	NA NA	NA NA	NA NA
	Pressurization of Lift lobby	NA	NA NA	NA NA
	Communication In lift Car	NA	NA NA	N/
	Fireman's Grounding Switch	NA	NA NA	N/
	 Lift Signage 	NA	INW	147

7			NIN				
17	Stand	by power supply	Required	Provided	MR		
18	Refug	lefuge Area.					
	>	Total Area	NA	NA	NI		
	>	Location	NA	NA NA	NA		
19	Fire C	Fire Control Room NA NA					
	•	Detector System Panel	NA	NA	NA		
	1	Flow Switch Panel	NA	NA	NA		
	- 1	PA System Panel	NA NA	NA	NA		
		Battery backup	NA	NA	NA		
^	Carat	Building Floor Plans	NA	NA	NA		
.0	Special Fire Protection Systems for Protection of special Risks, if any:		01 ABC fire extinguisher four provided near electrical panel		MR		

The fire protection systems provided in the building were randomly tested & checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules, the Noe vide letter no F6/DFS/MS/GH/2022/353 dated 21/07/2022, renewal under the rule 35 of the Delhi Fire Service rules 2010 is recommended for approval up to 3rd floor.

13 04 20x

20 (lubra)

Signature of the Inspecting Officer Sarabjeet Singh ADO (MN)

23415

by Cho Losses

LIV POUPX

Cr.0/ Nu

Director

de la

M

Janus Jaluss