

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001 Dated: 19/09/2025



No. F6/DFS/MS/2025/WZ/EH/ 33 O

FIRE SAFETY CERTIFICATE

Certified that the M/s Ricos (A unit of Jumbo Restaurants Pvt. Ltd.) located at UA-24, Jawahar Nagar, Malka Ganj, Near Gauri Nursing Home, Kamla Nagar, Delhi-110007, comprised of Basement + Stilt + Ground + 02 upper floors and restaurant running at upper ground floor only has already been issued FSC by this department vide letter No. F.6/DFS/MS/EH/2022/357 dated 21.12.2022. The premises was re-inspected by the officer concerned of this department on 02.09.2025 in the presence of Mr. Sumit |David (Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class -"D Assembly" (Restaurant) for upper ground floor only with effect from 19 09 202 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 19 09 2025 at New Delhi by

**Chief Fire Officer Delhi Fire Service** 

Copy to: -

MCD Portal ID-2025081912628 dated 20.08.2025.

2. Mr. Sumit David (Manager) M/s Ricos (A unit of Jumbo Restaurants Pvt. Ltd.) located at UA-24, Jawahar Nagar, Malka Ganj, Near Gauri Nursing Home, Kamla Nagar, Delhi-110007

## Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Fire+Safety+Acts+and+ http://www.delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Forms

	INSPE	CTION REPORT	<u>r</u>				
Name & address of the building	M/s R	cicos (A unit of Jur	mbo Restaurants Pvt 1	td ) located at I			
	M/s Ricos (A unit of Jumbo Restaurants Pvt. Ltd.) located at U 24, Jawahar Nagar, Malka Ganj, Near Gauri Nursing Hor Kamla Nagar, Delhi-110007.						
7 Type of Occupancy	Restai	rant Assembly	007.				
3 Comprised of building	Racen	nant Assembly	1.00				
4. Type of Case	Renev	val (Postanna + :	nd + 02 upper floors.				
Renewal (Restaurant is running at upper ground floor)  Details of Previous NOC  Fire Safety directives letter No  Renewal (Restaurant is running at upper ground floor)  F.6/DFS/MS/EH/2022/357 dated 21.12.2022.							
3. Name of Inspecting Officer							
Name and designation of officers		Sh. Ajay Kumar Sharma (ADO Rohini) Mr. Sumit David (Manager)					
From the building side	IVII. St	imit David (Manago	er)				
0. Year of Construction	2018 c	on MCD Portal					
1. Applicant's letter No.	Online	e application No.2025081912628 dated 20.08.2025.					
Minimum Standards on fire pre-	vention	Requirement	Provided at site	Remarks			
and fire safety U/R 33		existing fire safety arrangements		MR/NMR			
Access to building		4					
Road width		06mtr	06mtr	MR			
Gate width		05mtr	Directly accessible	MR			
<ul> <li>Width of internal road</li> </ul>		-NA-	-NA-	-NA-			
. Number, Width, Type & Arrang	ement of	Exits		***			
a. Number of staircases							
Upper Floors		02nos.	02nos.	MR			
Basements			-NA-	-NA-			
b. Width of staircases							
Upper Floor		2m & 1.35m	Provided	MR			
Basements		-NA-	-NA-	-NA-			
c. Protection of exits				• • • •			
Fire check door		-NA-	-NA-	-NA-			
Pressurization		-NA-	-ΝΛ-	-NA-			
d. No. of continuous staircases to	terrace	-NA-	-NA-	-NA-			
e. Width of Corridor		-NA-	-NA-	-NA-			
f. Door Size		2.0m & 1.35m	Provided				
3. Compartmentation		2.011 66 7.55111	Trovided	MR			
a) Fire check door		-NA-	-NA-	NIA			
b) Sealing of electrical shafts		-NA-	-NA-	-NA-			
c) Fire Rating of shaft door		-NA-	-NA-	-NA-			
d) Water Curtain		-NA-	The second secon	-NA-			
e) Fire Dampers		-NA-	-NA-	-NA-			
4. Smoke Management System		.,,,,	-NA-	-NA-			
a) Basements		-NA-	NIA				
b) Upper floors		12 a/c per hour	-NA-	-NA-			
5. Fire Extinguishers	Fire Extinguishers		Natural ventilation	MR			
a) Total numbers		06nos.	D.				
b) Types		ABC/CO2	Provided	MR			
c) IS marking		ISI marked	ABC/CO2	MR			
6. First-Aid Hose Reels		131 marked	Yes	MR			
<ul> <li>a) Total numbers on each floor</li> </ul>		01===					
b) Length of hose reel hose		01nos. 30mm	Provided	MR			
The strict rectifies		20	Provided				

	c) Nozzle diameter	5m	Provided				
7.			riovided	Mik			
	Automatic fire detection and alarming system  a) Type of detectors -NANA-						
		-NA-	-NA-	-NA			
	b) Location of Main Panel	-NA-	-NA-	-NA			
	c) Location of Repeater Panel	-ΝΛ-	-NA-	-NA			
	d) Alternate source of power	-NA-	-NA-	-NA			
0	e) Hooters' Location	-NA-	-NA-	-NA			
8.	MOEFA	Required	Provided	MR			
9.	Public Address System	-NA-	-ΝΛ-	-NA			
10.	Automatic Sprinkler System			1			
	a) Basement	-NA-	-NA-	-NA-			
	b) Ground & Upper Floors	Required	Provided	MR			
S0771	c) Sprinkler above false ceiling	Required	Provided	MR			
11.	Internal Hydrants						
	a) Size of riser/down-comer	Required	Provided	MR			
	b) Number of hydrants per floor	01nos.	Provided	MR			
	c) Hose Box	01nos.	Provided	MR			
12.	Yard Hydrants						
	a) Total number of hydrants	-NA-	-NA-	-NA-			
	b) Hose Box	-NA-	-ΝΛ-	-NA-			
13.	Pumping Arrangements						
	Ground Level						
	<ul><li>Discharge of main Pump</li></ul>	-NA-	-NA-	-NA-			
	Head of Main pump	-NA-	-NA-	-NA-			
	Number of main pumps	-NA-	-NA-	-NA-			
	Jockey Pump out put	-NA-	-NA-	-NA-			
	Jockey pump head	-NA-	-NA-	-NA-			
	Standby Pump out put	-NA-	-NA-	-NA-			
	Standby Pump Head	-NA-	-NA-	-NA-			
	Auto Starting/Manual Stopping	-NA-	-NA-	-NA-			
	> Pump House Access	-NA-	-NA-	-NA-			
	Terrace level						
	Discharge of pump	450lpm	450lpm	MR			
	Head of the pump	40m	40m	MR			
	> Power Supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
14.	Captive Water Storage for fire fighting						
	Underground tank capacity	-NA-	-NA-	-NA-			
	> Draw-off connection	-NA-	-NA-	-NA-			
	> Fire service inlet	Required	Provided	MR			
	> Access to tank	-NA-	-NA-	-NA-			
	Overhead Tank capacity	20,000ltr	20,000ltr	3700.000.0			
15.	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts.	Required	Trovided	MR			
10.	a) Pressurization of Lift Shaft	-NA-	-NA-	N1 x			
	b) Pressurization of Lift lobby	-NA-	-NA-	-NA-			
	c) Communication In lift Car	-NA-	-NA-	-NA-			
	d) Fireman's Grounding Switch	-NA-	-NA-				
	The state of the s			-NA-			

Y	Standby power supply	Required	Provided	MR		
X 1	Refuge Area.	-				
	a) Total Area	-NA-	-NA-	-NA-		
	b) Location	-NA-	-NA-	-NA-		
19.	Fire Control Room					
	a) Detector System Panel	-NA-	-NA-	-NA-		
	b) Flow Switch Panel	-NA-	-NA-	-NA-		
	c) PA System Panel	-NA-	-NA-	-NA-		
	d) Battery backup	-NA-	-NA-	-NA-		
	e) Building Floor Plans	-NA-	-NA-	-NA-		
20.	Special Fire Protection System for Protection of special Risks, if any:	-NA-	-NA-	-NA-		

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-4, and removal of shortcomings issued vide letter no. 273 dated 17.06.2025, the FSC issued vide letter no. F.6/DFS/MS/EH/2022/357 dated 21.12.2022, renewal of FSC under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

> Signature of the Inspecting Officer Ajay Kumar Sharma Name Designation ADO(Rohini)

100 (Rotini)