## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

८। ४ मा गुजादी ब अमृत महोत्सव

No. F6/DFS/MS/School/NDZ/2025/1042

Dated: 21 /08/2025

## FIRE SAFETY CERTIFICATE

Issued on 21 08 2025 at New Delhi by.

VIRENDRA SINGH CHIEF FIRE OFFICER 2 DELHI FIRE SERVICE

Copy to: -

- 1. The Dy. Director of Education, D Block, Anand Vihar, Delhi 110092.
- 2. The Manager, Rishi Convent School, E 65, New Ashok Nagar, Delhi 110096.

## Conditions for the validity of Fire Safety Certificate

- 1. Fire Safety Certificate is valid for ground plus two upper floors only.
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 4. The trained firefighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. At the time of inspection third floor closed by owner.
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 9. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 10. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

			CTION REPOR	N 62	1-10 8		
1		ne & address of the building		nt School located at Delhi - 110096.	E - 65, New		
2	Bui	ding is comprised of	Ground plus t	hree upper floors only	ing Ground +		
			New (Additio	n Of 02 floor on exist	ing Ground		
			01 upper floo	or). School running o	n G+2 uppe		
	T		The second secon	rd floor closed).			
3	_	e of occupancy	Educational B				
4		e of case	Addition/Alte	ration	oc/Cround		
5	Det	ails of previous FSC	F6/MS/DFS/0	06/2563 dated 15/09/20	00000100110		
	14 07.7		plus one upp	er floor only).	7/01/2005		
6	Fire	safety directives letter no.		No. 262 - 362 dated 1	7/01/2000		
7	Dat	e of inspection	31/07/2025				
8	Nar	ne of the inspecting officers	Yashwant Sin	gh Meena, ADO (L.N	)		
9		ne of the designation of office	r Mr. Ashok Ku	ımar (Manager) &			
		n the building side	Mrs. Rajkuma	ari Tripathi (Principal)			
10	Yea	r of construction	N	months a long.			
11	An	olicant's letter no.	Outdoor diary	y No. 3982 dated 21/0	7/2025		
		nimum standard of fire	Old Circular		Remarks MR/NMR		
No		vention and fire safety U/R 33	requirement	Provided at site	MR/NWIK		
	Access to Building:						
	A	Road width	6.0 mtrs.	6.0 mtrs.	MR		
		Gate width	N/A	N/A	N/A		
	В	y ray washing throughout	N/A	N/A	N/A		
	C	Width of internal road	MANORITACIONES	•			
2	Number, Width, Type and Arrangement of Exits:						
	A	Number of staircases		02 =03	MR		
		a Upper floor	01 no.	02 nos.	Old accepted		
1		b Basement	N/A	N/A	N/A		
-	В	Width of staircases	<u> </u>	and W.			
	Б	a Upper floor	1.50 mtrs.	1.0 mtr. & 0.94 mtr.	MR Old accepte		
			N/A	N/A	N/A		
1	18	b Basement	IVA	119 - 12 - 14 - 15 - 15 - 15 - 15 - 15 - 15 - 15	1.6		
1	C	Protection of exits a Fire check door	N/A	N/A	N/A		
1		1 1 11	N/A	N/A	N/A		
	D	b Pressurization No. of continuous staircases		01 no	MR		
	E	to terrace Width of corridor	1.50 mtr.	1.20 mtr.	MR		
	E		1.0 mtr.	1.0 mtr.	Old accepte MR		
	F	Door size	1.0 mu.	1.0 mu.	IVIIC		
3	Co	mpartmentation:		Action Co	Di BiGa		
	A	Fire check door	NA	NA	NA		
	В	Sealing of electrical shafts	N/A	N/A	N/A		
_	C	Fire rating of shaft door	N/A	N/A	N/A		
1	D	Water curtain	N/A	N/A	N/A		
		The state of the s	N/A	N/A	N/A		
	E	Fire dampers					
	E	Fire dampers oke Management System:					
	E	Fire dampers  oke Management System:  Basement	N/A	N/A	N/A		

Wa

## Rishi Convent School located at E - 65, New Ashok Nagar, Delhi - 110096.

5.		Extinguisher: Total numbers	06 nos.	08 nos.	MR
	A	The state of the s	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	MR
	B	Types	ISI Marked	ISI Marked	MR
	C	ISI marking	101111111111111111111111111111111111111	40.000	
5		st-Aid-Hose Reel:	01 no	01 no	MR
4	A	Total numbers of each		V1 110	IVIIC
	В	floor Length of hose reel hose	30 m	30 m	MR
	C	Nozzle diameter	05 mm	05 mm	MR
_	•	tomatic Fire Detection and	Alarming System:		
7		Type of detectors	N/A	N/A	N/A
ât	A	Location of main panel	N/A	N/A	N/A
	B	Location of repeater	N/A	N/A	N/A
	C	panel			
4.	D	Alternate source of power	N/A	N/A	N/A
	E	Hooters	N/A	N/A	N/A
8	- W	DEFA:	N/A	N/A	N/A
9		blic Address System:	N/A	N/A	N/A
10	20, 11	tomatic Sprinkler System:	Les land	-11	-
10	A	Basement	N/A	N/A	N/A
	B	Upper floor	N/A	N/A	N/A
	C	Sprinkler above false	N/A	N/A	N/A
11	In	ceiling ternal Hydrants:	PER 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
1.1	A	Size of riser/down-	N/A	N/A	N/A
	A	comer	IV/A	IN/A	IN/A
	В	Number of hydrants per floor	N/A	N/A	N/A
	C	Hose box	N/A	N/A	N/A
12	Ya	ard Hydrants:			
-	A	Total number of hydrants	N/A	N/A	N/A
20	В		N/A	N/A	N/A
13	Pu	imping Arrangements:			IVA
1		Ground level		-07 I- W	
	A	Discharge of main pump	N/A	N/A	N/A
12	В	Head of main pump	N/A	N/A	N/A
100	C	Number of main pumps	N/A	N/A	_
	D	Jockey pump out put	N/A	N/A	N/A
	E	Jockey pump head	N/A	N/A	N/A
	F	Standby pump out put	N/A	N/A	N/A N/A
10	G	Standby pump head	N/A		No. Control
. 1	H	Auto starting /manual	N/A	N/A N/A	N/A
	I	stopping	27072 <b>5</b> 0 <b>5</b> 0	IVA	N/A
2		Pump house access errace Level	N/A	N/A	N/A
_	A		.831		IN/A
	B	Discharge of pump Head of the pump	450 LPM	450 LPM	MR
	C		40 m	40 m	MR
	D		Required	Provided	MR
		rate starting of pump	Required	Provided	MR
			(1)		IVIK

(3)

7	<u></u>	pent School located at E - 65, New Ashok N ptive Water Storage for Fire Fight	ing:	letter letter			
ŀ	B		N/A	N/A	N/A		
	C	Diaw-OII Connection	N/A	N/A	N/A		
ŀ	D	Fire service inlet	N/A	N/A	N/A N/A		
	E	Access to tank	N/A	N/A	MR		
5		Overhead tank capacity	10,000 liters	10,000 liters	MR		
	EX	it Signage:	Required	Provided	IVIK		
16	Provision of Lifts:						
-	A	Pressurization of lift shaft	N/A	N/A	N/A		
	B	Pressurization of lift lobby	N/A	N/A	N/A		
	C	Communication in lift car	N/A	N/A	N/A N/A		
	D	Firemen's grounding switch	N/A	N/A	N/A		
	E	Lift signage	N/A	N/A	N/A N/A		
7	Sta	andby Power Supply:	N/A	N/A	IV/A		
8	Refuge Area						
	A	Total area	N/A	N/A	N/A		
ŀ	B	Location	N/A	N/A	N/A		
9		e Control Room:	1 11.2.				
-		The state of the s	N/A	N/A	N/A		
	A	Detector system panel	N/A	N/A	N/A		
	B		N/A	N/A	N/A		
-	D	PA system panel	N/A	N/A	N/A		
	E	Battery backup Building floor plans	N/A	N/A	N/A		
0		ecial Fire Protection systems for	N/A	N/A	N/a		
20	OD		(#07A(#1)06)		7770		
ote grack	prounced T	At the time of inspection building cond plus two upper floors only, third float C/07-15).  The fire protection system was random	nly checked and t	ested and was four	nd furctio		
ote grack the	prount sed	At the time of inspection building cond plus two upper floors only, third float C/07-15). The fire protection system was randomine of inspection.  The protection is a security of the deemed composition.	nly checked and to	ested and was four um standards of fir FSC issued vid	nd furction e prevent e letter		
ote of gracic the	prount sed The time K fire	At the time of inspection building cond plus two upper floors only, third float C/07-15). The fire protection system was random to of inspection.  The eping In view of the deemed composafety measures as required und DFS/06/2563 dated 15/09/2006, renew	nly checked and to	ested and was four um standards of fir FSC issued vid	nd furction e prevent e letter		
ote of gracic the	prount sed The time K fire	At the time of inspection building cond plus two upper floors only, third float C/07-15). The fire protection system was randomine of inspection.  The protection is a security of the deemed composition.	nly checked and to	ested and was four um standards of fir FSC issued vid	nd furction e prevent e letter		
ote of gracic the	prount sed The time K fire	At the time of inspection building cond plus two upper floors only, third float C/07-15). The fire protection system was random to of inspection.  The eping In view of the deemed composafety measures as required und DFS/06/2563 dated 15/09/2006, renew	nly checked and to diance of minimular the rules of val under Rule 3	ested and was four im standards of fir FSC issued vid 5 (6) of the Delhi 6   2   2	e prevente letter		
ote of gracic the	prount sed The time K fire	At the time of inspection building cond plus two upper floors only, third float C/07-15). The fire protection system was random to of inspection.  The eping In view of the deemed composafety measures as required und DFS/06/2563 dated 15/09/2006, renew	of closed by own half checked and to bliance of minimuler the rules of val under Rule 3	ested and was four im standards of fir FSC issued vid 5 (6) of the Delhi 6   9   22 nature of the Inspe	e prevente letter Fire Servente		
ote of gracic the	prount sed The time K fire	At the time of inspection building cond plus two upper floors only, third float C/07-15). The fire protection system was random to of inspection.  The eping In view of the deemed composafety measures as required und DFS/06/2563 dated 15/09/2006, renew	of closed by own only checked and to bliance of minimuler the rules of val under Rule 3  Sig	ested and was four im standards of fir FSC issued vid 5 (6) of the Delhi classical vid and the Delhi classical vid by classical vid classical	e prevente letter Fire Serveting Off		
ote of gracic the	prount sed The time K fire	At the time of inspection building cond plus two upper floors only, third floor at C/07-15). The fire protection system was random ne of inspection. Reeping In view of the deemed composafety measures as required und DFS/06/2563 dated 15/09/2006, renew 10, is recommended.	nly checked and to diance of minimular the rules of val under Rule 3 Sig Nan De	ested and was four im standards of fir FSC issued vid 5 (6) of the Delhi classical vid classical vid the Delhi classical vid the Delhi standards of fir the Delhi standards of the Delhi standards of the Delhi standards of the Insperme Yashwant	e prevente letter Fire Serveting Off		
ote of gracic the	prount sed The time K fire	At the time of inspection building cond plus two upper floors only, third floor at C/07-15). The fire protection system was random ne of inspection. Reeping In view of the deemed composafety measures as required und DFS/06/2563 dated 15/09/2006, renew 10, is recommended.	nly checked and to diance of minimular the rules of val under Rule 3 Sig Nan De	ested and was four im standards of fir FSC issued vid 5 (6) of the Delhi classical vid and the Delhi classical vid by classical vid classical	e prevente letter Fire Servente		
ote of gracic the	prount sed The time K fire	At the time of inspection building cond plus two upper floors only, third floor at C/07-15). The fire protection system was random the of inspection. Seeping In view of the deemed composafety measures as required und DFS/06/2563 dated 15/09/2006, renew 10, is recommended.	of closed by own only checked and to bliance of minimuler the rules of val under Rule 3  Sig	ested and was four im standards of fir FSC issued vid 5 (6) of the Delhi classical vid and the Delhi classical vid by classical vid classical	e prevente letter Fire Serveting Off		
ote of gracic the	prount sed The time K fire	At the time of inspection building cond plus two upper floors only, third floor at C/07-15). The fire protection system was random ne of inspection. Reeping In view of the deemed composafety measures as required und DFS/06/2563 dated 15/09/2006, renew 10, is recommended.	nly checked and to diance of minimular the rules of val under Rule 3 Sig Nan De	ested and was four im standards of fir FSC issued vid 5 (6) of the Delhi classical vid and the Delhi classical vid by classical vid classical	e prevente letter Fire Serveting Off		
ote of gracic the	prount sed The time K fire	At the time of inspection building cond plus two upper floors only, third floor at C/07-15). The fire protection system was random ne of inspection. Reeping In view of the deemed composafety measures as required und DFS/06/2563 dated 15/09/2006, renew 10, is recommended.	nly checked and to diance of minimular the rules of val under Rule 3 Sig Nan De	ested and was four im standards of fir FSC issued vid 5 (6) of the Delhi classical vid and the Delhi classical vid by classical vid classical	e prevente letter Fire Serveting Off		
ote of gracic the	prount sed The time K fire	At the time of inspection building cond plus two upper floors only, third floor at C/07-15). The fire protection system was random the of inspection. The deemed composafety measures as required und DFS/06/2563 dated 15/09/2006, renew 10, is recommended.	nly checked and to diance of minimular the rules of val under Rule 3 Sig Nan De	ested and was four im standards of fir FSC issued vid 5 (6) of the Delhi classical vid and the Delhi classical vid by classical vid classical	e prevente letter Fire Serveting Off		
ote of gracic the	prount sed The time K fire	At the time of inspection building cond plus two upper floors only, third floor at C/07-15). The fire protection system was random the of inspection. The deemed composafety measures as required und DFS/06/2563 dated 15/09/2006, renew 10, is recommended.	nly checked and to diance of minimular the rules of val under Rule 3 Sig Nan De	ested and was four im standards of fir FSC issued vid 5 (6) of the Delhi classical vid and the Delhi classical vid by classical vid classical	e prevente letter Fire Serveting Off		
oten gracio the did of /N. iles	pround seed T K fire IS/I 20:	At the time of inspection building cond plus two upper floors only, third float C/07-15).  The fire protection system was random ne of inspection.  Seeping In view of the deemed composafety measures as required und DFS/06/2563 dated 15/09/2006, renew 10, is recommended.	nly checked and to diance of minimular the rules of val under Rule 3 Sig Nan De	ested and was four im standards of fir FSC issued vid 5 (6) of the Delhi classical vid and the Delhi classical vid by classical vid classical	e prevente letter Fire Serveting Off		
oten gracio the did of /N. iles	pround seed T K fire IS/I 20:	At the time of inspection building cond plus two upper floors only, third floor at C/07-15). The fire protection system was random the of inspection. The deemed composafety measures as required und DFS/06/2563 dated 15/09/2006, renew 10, is recommended.	nly checked and to diance of minimular the rules of val under Rule 3 Sig Nan De	ested and was four im standards of fir FSC issued vid 5 (6) of the Delhi classical vid and the Delhi classical vid by classical vid classical	e prevente letter Fire Serveting Off		

Amolavil

CFO/ 111 (8+00)