शाजादी ब अमृत महोत्सव

No. F6/DFS/MS/School/NDZ/2025/1191

Dated: 25/09 /2025

FIRE SAFETY CERTIFICATE

Certified that the RML World School located at KH. No. 155, Chauhan Patti, Near Shiv Mandir, Delhi-110094, building comprised of Ground floor only owned/occupied by RML World School have complied with the Fire Prevention and Fire Safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 18/09/2025 in the presence of Mr. Rajesh (Manager) and observed that all the fire prevention and fire safety requirements provided in the premises found in good working condition and that the school building is fit for occupancy "Educational Building" (class B) with effect from 257 oq /2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 25/09/2025 at New Delhi by.

VIRENDRA SINGH CHIEF FIRE OFFICER OC DELHI FIRE SERVICE

Copy to: -

- 1. The Director of Education, GNCT of Delhi, Old Secretariat, Civil Lines, Delhi-110054.
- 2. The Principal, RML World School, KH. No. 155, Chauhan Patti, Near Shiv Mandir, Delhi-110094.

Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

| | | | INCDE | NION DEPO | DT. | | | | |
|----------|--|--|------------------------------------|---|---|-----------|--|--|--|
| 1 | TX | Io- | | CTION REPO | | | | | |
| .1 | Name & address of the building | | | RML Wor | RML World School located at KH. No. 155 | | | | |
| 2 | Building is comprised of Type of occupancy Type of case Details of previous FSC Fire safety directives letter no. Date of inspection | | | Chauhan Patti, Near Shiv Mandir, Delhi-110094 | | | | | |
| 3 | | | | | Ground floor only | | | | |
| 4 | | | | Educational Building New Case Nil NBC Part - IV | | | | | |
| 5 | | | | | | | | | |
| 6 | | | | | | | | | |
| 7 | | | | | | | | | |
| 8 | | | | 16/09/2025 | | | | | |
| 9 | Name of the designation of officers | | | Yashwant Singh Meena, ADO/Laxmi Nagar | | | | | |
| | Name of the designation of officer from the building side | | the huilding side | Mr. Rajesh (Manager) | | | | | |
| 10 | Year of construction Applicant's letter no. | | | 2024 Outdoor diary no. 5024dated 20/08/2025 | | | | | |
| 11 | | | | | | | | | |
| 1 | | | mum standard of fire | NBC Part I | | Remarks | | | |
| S.No | | prevention and fire safety U/R 33 | | Requiremen | nt Provided at site | MR/NMR | | | |
| 1 | Access to Building: | | | | | 2 | | | |
| | A | _ | Road width | 6.0 mtr. | 6.0 mtr. | MR | | | |
| | В | 1 | Gate width | N/A | N/A | N/A | | | |
| | C | - | Width of internal road | N/A | N/A | N/A | | | |
| 2 | Number, Width, Type and Arrangement of Exits: | | | | | | | | |
| | A | | Number of staircases | | | 5 | | | |
| | A. | SULVANISHON SULVANISHOOD SUCCESSION SUCCESSI | | N/A | Provided | N/A | | | |
| | \vdash | b | Upper floor Basement | N/A | N/A | N/A | | | |
| | В | | Vidth of staircases | 2.022 | 2500000000000 | 500 8 500 | | | |
| | | a | Upper floor | N/A | 1.45 mtr. & 1.90 mt | r. N/A | | | |
| | | b | Basement | N/A | N/A | N/A | | | |
| | C | 2.00 | rotection of exits | 1771 | 1,171 | 1011 | | | |
| - | | a | Fire check door | N/A | N/A | N/A | | | |
| | | b | Pressurization | N/A | N/A | . N/A | | | |
| | D | | o. of continuous staircases | N/A | 01 no | N/A | | | |
| | E | _ | terrace /idth of corridor | 1.50 meters. | 1.80 meters. | MR | | | |
| ŀ | F | . No. | oor size | | | | | | |
| | Compartmentation: | | | 1.20 meter. | 1.25 meter. | MR | | | |
| | A | - | | T | | | | | |
| | | | Mark Central State State State Co. | NA | NA | NA | | | |
| - | 8 or organism plants | | | N/A | N/A | N/A | | | |
| - | C Fire rating of shaft door D Water curtain | | re rating of shaft door | N/A | N/A | N/A | | | |
| _ | E Fire dampers | | -0.02-20 -0.02 49/00F000 | N/A | N/A | N/A | | | |
| | pv.b | | | N/A | N/A | N/A | | | |
| | Smoke Management System: | | | | | | | | |
| | A | | | N/A | N/A | N/A | | | |
| | В | υŗ | oper floor | N/A | N/A | N/A | | | |



RML World School located at KH. No. 155, Chauhan Patti, Near Shiv Mandir, Delhi-110094

| 5. | 1/0 | | | | | | | |
|----|---|--|-----------------------|-----------------------|--------|--|--|--|
| | A | Total numbers | 04 nos. | 04 nos. | MR | | | |
| | B | Types | CO ₂ & ABC | CO ₂ & ABC | MR | | | |
| | C | ISI marking | ISI Marked | ISI Marked | MR | | | |
| 6 | First-Aid-Hose Reel: | | | | | | | |
| | A | Total numbers of each floor | N/A | N/A | N/A | | | |
| | B | Length of hose reel hose | N/A | N/A | N/A | | | |
| | C | Nozzle diameter | N/A | N/A | N/A | | | |
| 7 | Automatic Fire Detection and Alarming System: | | | | | | | |
| | A | Type of detectors | N/A | N/A | N/A | | | |
| | В | Location of main panel | N/A | N/A | N/A | | | |
| | C | Location of repeater panel | N/A | N/A | N/A | | | |
| | D | Alternate source of power | N/A | N/A | N/A | | | |
| | E | Hooters | N/A | N/A | N/A | | | |
| 8 | MC | DEFA: | N/A | N/A | N/A | | | |
| 9 | Pul | blic Address System: | N/A | N/A | N/A | | | |
| 10 | Automatic Sprinkler System: | | | | | | | |
| | A | Basement | N/A | N/A | N/A | | | |
| | В | Upper floor | N/A | N/A | N/A | | | |
| | C | Sprinkler above false ceiling | N/A | N/A | N/A | | | |
| 11 | Internal Hydrants: | | | | | | | |
| | A | Size of riser/down-comer | N/A | N/A | N/A | | | |
| | B | Number of hydrants per floor | N/A | N/A | N/A | | | |
| | C | Hose box | N/A | N/A | N/A | | | |
| 12 | Yard Hydrants: | | | | | | | |
| 12 | A | Total number of hydrants | N/A | N/A | N/A | | | |
| | B | Hose box | N/A | N/A | N/A | | | |
| 13 | | POLICIA GENERAL CONTROL CONTRO | 14/21 | 1071 | 1 1/12 | | | |
| | Pumping Arrangements: Ground level | | | | | | | |
| 1 | | e e e e e e e e e e e e e e e e e e e | NI/A | NT/A | NI/A | | | |
| | A | Discharge of main pump | N/A | N/A | N/A | | | |
| 11 | B | Head of main pump | N/A | N/A | N/A | | | |
| | C | Number of main pumps | N/A | N/A | N/A | | | |
| | D | Jockey pump out put | N/A | N/A | N/A | | | |
| | E | Jockey pump head | N/A | N/A | N/A | | | |
| | F | Standby pump out put | N/A | N/A | N/A | | | |
| | G | Standby pump head | N/A | N/A | N/A | | | |
| | H | Auto starting /manual | N/A | N/A | N/A | | | |
| | - | stopping | 27/4 | | 200 | | | |
| | Tor | Pump house access | N/A | N/A | N/A | | | |
| 2 | Terrace Level | | | | | | | |
| } | A | Discharge of pump | N/A | N/A | N/A | | | |
| + | B | Head of the pump | N/A | N/A | N/A | | | |
| | C | Power supply | N/A | N/A | N/A | | | |
| | D | Auto starting of pump | N/A | N/A | N/A | | | |

0

RML World School located at KH No. 155

| 14 | L World School located at KH. No. 155, Chauhan Patti, Near Shiv Mandir, Delhi-110094 A Lindergraph of the Fighting: | | | | | | |
|-----|--|------------------------------------|------|------------|-----|--|--|
| | A Underground tank capacity | | ing: | 1 | 7. | | |
| | В | Draw-off connection | N/A | N/A | N/A | | |
| | C | Fire service inlet | N/A | N/A | N/A | | |
| | D | | N/A | N/A | N/A | | |
| | E | Access to tank | N/A | N/A | N/A | | |
| | - Thead talk capacity | | N/A | N/A | N/A | | |
| 15 | | it Signage: | N/A | N/A | N/A | | |
| 16. | Provision of Lifts: | | | | | | |
| | A | Pressurization of lift shaft | N/A | N/A | N/A | | |
| | B | Pressurization of lift lobby | N/A | N/A | N/A | | |
| | C | Communication in lift car | N/A | N/A | N/A | | |
| 17 | D | Firemen's grounding switch | N/A | N/A | N/A | | |
| | E | Lift signage | N/A | N/A | N/A | | |
| | Standby Power Supply: | | N/A | N/A | N/A | | |
| 18 | Refuge Area | | | | | | |
| | A | Total area | N/A | N/A | N/A | | |
| | В | Location | N/A | N/A | N/A | | |
| 19 | Fire Central Poom | | | | | | |
| 17 | 1 | Detector system panel | N/A | N/A | N/A | | |
| | A | Flow switch panel | N/A | N/A | N/A | | |
| | B | PA system panel | N/A | N/A | N/A | | |
| | C | | N/A | N/A | N/A | | |
| | D | Building floor plans | N/A | N/A N/A | N/A | | |
| •• | E Building floor plans Special Fire Protection systems for | | N/A | IVA | | | |
| 20 | Spe | stection of special Risks, if any: | | | | | |

The fire protection systems provided in the building were tested, checked at random

and found functional at the time of inspections

Keeping in view of the substantial compliance of the minimum standards of fire revention and fire safety required under the rules it is recommended to grant Fire Safety prevention and fire safety required under the rules 2010 is recommended.

Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer
Name Yashwant Singh Meena
Designation ADO/Laxmi Nagar

D.O/EAST

DFA flore.

17/09/2

They

Principal Director

@fs

to Jesus

22/58/25