

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No. F6/DFS/MS/2025/WZ/GH/ 230

Dated: 22 04 2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Royal Inn, located at Shop No.9520, Gali No.13, Multani Dhanda Pahar Ganj, New Delhi-110055, comprised of Ground + 03 upper floors, Ground floor-Reception & 02 guest rooms, 1st floor-05 guest rooms, 2nd floor-06 guest rooms & 3rd floor-06 guest rooms, total-19 guest rooms has already been issued FSC by this department vide letter No. F.6/DFS/Ms/GH/NDZ/2022/390 dated 17.08.2022. The premises was re-inspected by the officer concerned of this department on 12.04.2025 in the presence of Mr. Manoj (Manager) and found that the said guest house building having store & staff room at terrace and given an affidavit dated 27.09.2019 regarding not to use and floor above third floor, has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Residential (Sub-Division-A-1) for ground + 03 upper floors total-19 guest rooms with effect from 22 04 2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 22 04 2025 at New Delhi by

(Atul Garg)
DIRECTOR
Ph; 011-23414000

Copy to: -

1. MCD Portal Id- 2025032804804 dated 31.03.2025.

2. The Commissioner MCD, Civic Centre, New Delhi, to ensure the occupancy s detailed above.

 The Joint Commissioner of Police (Lic.) 1st floor, Licensing unit, Police Station, Defence Colony, New Delhi-

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

9. Standby power supply shall be provided with in six month, filling which it will be considered null & void.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/ http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

TE.							
1	No	INSPE	CTION REPORT				
1.	Name & address of the building				- 1- "1-		
		C20172.77	da Pahar Cari N	at Shop No.9520, Gali	No.13, Multan		
2.	- JP OI OCCUMANCO	Resid	da Pahar Ganj, New	v Delhi-110055.			
3.	Comprised of building	Grour	Residential, Sub Division-A-1 Ground + 03 upper floors & 3 rd floor terrace staff & store room				
4.	Type of Case	Renev	val -Ground + 03 u	inner floors-Total 10 room	& store room		
		Groun	Renewal –Ground + 03 upper floors-Total-19 rooms Ground floor- Reception & 02 guest rooms, 1st floor-05 guest				
		rooms	, 2" floor-06 guest	rooms, 3 rd floor-06 guest	rooms &		
			terrace floor-staff & store room not in use as per affidavit dated				
5.	Details of Previous NOC		27.09.2019 F 6/DES/Ma/GUAID 7/2022/200 detail 17.09.2022				
	Fire Safety directives letter No -NA- Date of inspection 12.04		/DFS/Ms/GH/NDZ/2022/390 dated 17.08.2022				
7.			2.04.2025				
8.	N 07 12.01		Ajay Kumar Sharma (ADO Rohini)				
	Name and designation of officer	s Mr. M	anoj (Manager)	10 20 00 00 00 00 00 00 00 00 00 00 00 00	18		
	From the building side						
10	0. Year of Construction	100000000000000000000000000000000000000	2008 on MCD Portal				
	1. Applicant's letter No. Online		e application No.2025032804804 dated 31.03.2025.				
S.	Minimum Standards on fire pr	revention	Requirement	Provided at site	Remarks MR/NMR		
No			Existing		1/11/11/11		
1.	Access to building		-NA-	6m approx	MR		
	Road width		-NA-	-NA-	-NA-		
	Gate width		-NA-	-NA-	-NA-		
- 4	Width of internal road		1-25 (4-50-4) (50)	-11/1-	211.2		
2.	Number, Width, Type & Arrai	igement of	Exits				
	a. Number of staircases		01nos.	01nos.	MR		
	Upper Floors		-NA-	-NA-	-NA-		
	Basements		-NA-	-14/1-			
	b. Width of staircases		0.80m	1.0 to 1.06m	MR		
	Upper Floor		2017-0312250-0344		-NA-		
	Basements		-NA-	-NA-	-INA-		
	c. Protection of exits			774	T NA		
	Fre check door		-NA-	-NA-	-NA-		
	Pressurization		-NA-	-NA-	-NA-		
	d. No. of continuous staircases to terrace		01nos.	01nos.	MR		
	e. Width of Corridor		-NA-	-NA-	-NA-		
	f. Door Size		1.0m	1.0m	MR		
3.	Compartmentation						
	a) Fire check door		-NA-	-NA-	-NA-		
	b) Sealing of electrical shafts		-NA-	-NA-	-NA-		
	c) Fire Rating of shaft door		-NA-	-NA-	-NA-		
	d) Water Curtain		-NA-	-NA-	-NA-		
	e) Fire Dampers		-NA-	-NA-	-NA-		
4.	Smoke Management System						
	a) Basements		-NA-	-NA-	-NA-		
	b) Upper floors		12 a/c per hour	Natural /Exhaust fan	MR		
5.	Fire Extinguishers			11/1			
	a) Total numbers		08nos.	Provided	MR		
	b) Types	The same	ABC/CO2	ABC/CO2	MR		
	c) IS marking		ISI marked	Yes	MR		

- 10	First-Aid Hose Reels) (P		
+	a) Total numbers on each floor	Olnos.	Provided	MR		
-	b) Length of hose reel hose	30mm	Provided	MR MR		
+	c) Nozzle diameter	5m	Provided	MK		
+	c) NOZZIE diametei					
		Required	Provided	MR MR		
	200 000 000	Gr. floor	Provided	-NA-		
-	b) Location of Main Panel	-NA-	-NA-	MR		
	c) Location of Repeater Panel	Required	Provided	MR		
	d) Alternate source of power	Each floor	Provided	MR		
	e) Hooters' Location	Required	Provided	MR		
	MOEFA	Required	Provided	IVIIC		
•	Public Address System	1000000		-NA-		
0.	Automatic Sprinkler System	-NA-	-NA-	-NA-		
	a) Basement	-NA-	-NA-	-NA-		
	b) Ground & Upper Floors	-NA-	-NA-	-IVA-		
-	c) Sprinkler above false ceiling			NA		
11.	Internal Hydrants	-NA-	-NA-	-NA-		
	a) Size of riser/down-comer	-NA-	-NA-	-NA-		
	b) Number of hydrants per floor	-NA-	-NA-	-NA-		
	c) Hose Box		574			
12.	Yard Hydrants	-NA-	-NA-	-NA-		
	a) Total number of hydrants	-NA-	-NA-	-NA-		
	b) Hose Box		111.8			
13.				1 A		
	Ground Level Discharge of main Pump	-NA-	-NA-	-NA-		
	> Head of Main pump	-NA-	-NA-	-NA-		
	> Number of main pumps	-NA-	-NA-	-NA-		
	> Jockey Pump out put	-NA-	-NA-	-NA-		
	> Jockey pump head	-NA-	-NA-	-NA-		
	> Standby Pump out put	-NA-	-NA-	-NA-		
	> Standby Pump Head	-NA-	-NA-	-NA-		
	> Auto Starting/Manual Stopping	-NA-	-NA-	-NA-		
	> Pump House Access	-NA-	-NA-	-NA-		
	Terrace level					
	> Discharge of pump	450lpm	450lpm	MR		
	> Head of the pump	30m	30m	MR		
	> Power Supply	Required	Provided	MR		
	> Auto Starting of pump	Required	Provided	MR		
14	C for fire fighting					
14	Underground tank capacity	-NA-	-NA-	-NA-		
	> Draw-off connection	-NA-	-NA-	-NA-		
		-NA-	-NA-			
	> Fire service inlet	54/05/25/2	EANG NO	-NA-		
	> Access to tank	-NA-	-NA-	-NA-		
	Overhead Tank capacity	2500ltr	Provided	MR		
		Required	Provided	MR		
15						
100.00	. Provision of Lifts.					
15 16	a) Pressurization of Lift Shaft	-NA-	-NA-	-NA-		

V	c) Communication In lift Car	-NA-	-NA-	-NA-	
1	d) Fireman's Grounding Switch	-NA-	-NA-	-NA-	
/	e) Lift Signage	-NA-	-NA-	-NA-	
17.	Standby power supply	Required	Shall be provided with in six months	MR	
18.	Refuge Area.				
-	a) Total Area	-NA-	-NA-	-NA-	
	b) Location	-NA-	-NA-	-1,7,1	
19.	Fire Control Room				
	a) Detector System Panel	-NA-	7/5/	-NA-	
	b) Flow Switch Panel	-NA-	-NA-	-NA-	
	c) PA System Panel	-NA-	-NA-	-NA-	
	d) Battery backup	-NA-	-NA-	-NA-	
	e) Building Floor Plans	-NA-	-NA-	-NA-	
20.	Special Fire Protection System for	-NA-	-NA-	A COAN	

Accordingly, the fire protection systems provided in the building were tested

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety randomly and found in working condition at the time of inspection. measures as required under the rules the NOC issued vide letter no. F.6/DFS/Ms/GH/NDZ/2022/390 dated 17.08.2022 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

> Signature of the Inspecting Officer Ajay Kumar Sharma Name Designation ADO(Rohini)