



To,

The Principal,
Samarambh Public School
Gharoli, Pocket C- 2, Mayur Vihar Phase - III,
Delhi - 110096..

Subject: - Regarding grant of Fire Safety Certificate in r/o Samarambh Public School located at Gharoli, Pocket C- 2, Mayur Vihar Phase - III, Delhi - 110096.

Sir,

This has a reference to your Outdoor Diary No. 11851 dated 27/02/2025, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 15/02/2025 in the presence of Manager and observed that building comprised of two blocks, Block A- Ground floor only, Block B- Ground plus two upper floors only.

Following shortcomings were observed during time of inspection:

1. Road width of 4.80 mtrs. provided against requirement of 6.0 mtrs.
2. One staircase of width 1.0 meter is provided in building instead of required 02 nos. of staircase of width 1.50 meter each
3. Door size of 0.90 meter provided against requirement of 1.20 meter.
4. First-Aid-Hose Reel at each floor not provided at B - Block.
5. Fire pump of 450 LPM not provided at B - Block.
6. Over head water storage tank of capacity 10,000 liters not provided.
7. Exit & floors Signage's not provided in strategic location in the building.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,


(ATUL GARG)
DIRECTOR

ok  DELHI FIRE SERVICE

Copy to:-

1. The Joint Director of Education, MCD, Udyog Sadan, Plot No.419, FIE, Patargang, Delhi - 110092.