


## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/Hospital/NDZ/2025/ 313

Dated: 30/06/2025

To,

Dr. Abdul Khalique Samra Hospital, C-3/52A-53A, Yamuna Vihar, Delhi - 110053.

Subject: - Regarding grant of Fire Safety Certificate in r/o Samra Hospital located at C-3/52A-53A, Yamuna Vihar, Delhi - 110053.

Sir,

This has a reference to Outdoor Diary No. 1953 dated 21/05/2025, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officers concerned of this department on 23/06/2025 in the presence of Dr. Abdul Khalique and observed that building comprised of Basement, ground plus two upper floors only.

Following shortcomings were observed during time of inspection:

- Two staircase of width 1.15 meters & 0.92 meters (upto 1<sup>st</sup> floor only) are provided instead of required width of 2.0 & 1.50 meter respectively on ground floor.
- 2. Two staircase of width 1.13 meters & 1.16 meters are provided instead of required width of 2.0 & 1.50 meter respectively in basement.
- 3. Fire check door not provided.
- 4. The corridor of width 1.49 meters against the requirement of 2.40 meters.
- 5. The width of door size is 0.95 meter against the requirement of 1.50 meter.
- 6. Smoke Management System not provided in basement and upper floors.
- 7. First-Aid-Hose Reel not provided.
- 8. Automatic Sprinkler System not provided in basement.
- 9. Internal Hydrants not provided.
- Pumping arrangements one electric pump of 1620 LPM, one jockey pump of 180 LPM and one diesel pump of 1620 LPM fire pump not provided.
- 11. Terrace fire pump of 900 LPM capacity is not provided.
- 12. Underground water storage tank capacity 75,000 liters not provided.
- 13. Overhead water storage tank capacity 10,000 liters not provided.
- 14. Exit & floors Signage's not provided at strategic location in the building.
- 15. Pressurization of lift shaft in basement not provided.
- 16. Lift signage's not provided.
- 17. Standby Power Supply not provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

(ATUL GARG) DIRECTOR OC DELHI FIRE SERVICE

## Copy to: -

The Medical Superintendent, Nursing Homes, Directorate General of Health Services, Govt. of NCT of Delhi, 3<sup>rd</sup> floor, Delhi Govt. Dispensary Building, S-1, School Block, Shakarpur, Delhi – 110032.