

c/82

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS : DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/Hospital/NDZ/2025/ 249

Dated: 15/05/2025

FIRE SAFETY CERTIFICATE

Certified that the **Sant Parmanand Hospital** located at **18, Sham Nath Marg, Civil Lines, Delhi - 110006**, comprised of Basement + Ground + 03 upper floors was granted FSC by this department vide letter no. F6/DFS/MS/Hospital/NDZ/2022/220 dated 17.05.2022. The building/premises was re-inspected by the officers concerned of this department on 10.05.2025 in presence of Mr. Harihar and found that the said hospital building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class group **(C-1) "Institutional Building"**, with effect from 15/05/2025 for a period of **three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 15/05/2025 at New Delhi by

(Atul Garg)

Director

Delhi Fire Service

Tel- 011-23414000

Copy to:-

1. The Commissioner, Municipal Corporation of Delhi, Dr. SPM Civic Centre, New Delhi - 110002.
2. The Director /Medical Superintendent, Sant Parmanand Hospital, 18, Sham Nath Marg, Civil Lines, Delhi-54.

Conditions for the validity of fire safety certificate

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

-2/14-

INSPECTION REPORT		
1.	Name and address of the building:	Sant Parmanand Hospital located at 18, Shyam Nath Marg, Civil Lines, Delhi
2.	Type of occupancy with details of floors:	Institutional Building C-1 (Basement + Ground + 03 Upper floors)
3.	Type of case:	Renewal
4.	Details of previous FSC:	F6/DFS/MS/Hospital/NDZ/2022/220 dated 17.05.2022
5.	Fire safety directives no.:	F6/DFS/MS/93/Hospital/398 dated 05.03.1993
6.	Date of inspection:	10.05.2025
7.	Name of the inspecting officer:	Rajinder Atwal (DO CD) & Sumit Kumar, (ADO SPM)
8.	Name and designation of the officer from the building side:	Mr. Harihar
9.	Year of construction:	1990
10.	Reference letter no.:	Letter no. SPH/HR/FIRE/26 dated 15.04.2025

S, No	Minimum standard of Fire Prevention and Fire Safety U/R 33	NBC Requirements	Provide at site (PSS)	Remarks MR/NMR
1	Access to Building			
	A Road width	9.0 mtrs.	30.48 mtrs.	MR
	B Gate width	4.5 mtrs.	6.0 mtrs.	MR
	C Width of internal roads	NA	NA	NA
2	Number, Width, Type & Arrangement of Exits			
	A No. of Staircase:			
	a) Upper floor	03 nos.	Provided	MR
	b) Basements	03 nos.	Provided	MR
	B Width of the Staircase:			
	a) Upper floors	2 mtrs.	2 mtrs.	MR
	b) Basements	2 mtrs.	2 mtrs.	MR
	C Protection of Exits			
	a) Fire check door	Required	Provided	MR
	b) Pressurization	NA	NA	NA
	D No. of continuous staircase to terrace:	02 nos.	03 nos.	MR
	E Width of the corridor	1.5 mtrs.	Provided	MR
	F Door size	1.0 mtrs.	Provided	MR
3	Compartmentation:			
	A Fire check doors	Required	Provided	MR
	B Sealing of electrical shafts	Required	Provided	MR
	C Fire rating of shaft doors	01 Hrs Rating	Provided	MR
	D Water curtain	NA	NA	NA
	E Fire dampers	NA	NA	NA
4	Smoke Management System:			
	A Basement	12 ACPH	Provided	MR
	B Upper floors	12 ACPH	Provided	MR
5	Fire Extinguishers			
	A Total numbers	60 nos.	Provided (78 nos.)	MR
	B Types	ABC & CO2	ABC & CO2	MR
	C ISI marking	Required	Provided	MR

- N/15-

6	First Aid Hose Reel			
	A	Total no. at each floor		
	B	Length of hose reel	02 nos.	Provided MR
7	C	Nozzle diameter	30 mtrs.	30 mtrs. MR
			05 mm	05 mm MR
	Automatic Fire Detection and Alarm System (ADAS)			
8	A	Type of detectors -Smoke type	Required	Provided MR
	B	Location of main Panel	Ground floor	Provided MR
	C	Location of repeater panel	Required	Provided MR
	D	Alternate power Source	Required	Provided MR
	E	Hooter's location	Required	Provided MR
9	MOEFA		Required	Provided MR
10	Public Address System		Required	Provided MR
11	Automatic Sprinkler System			
	A	Basement	Required	Provided MR
	B	Upper floor	NA	Provided NA
12	C	Sprinklers above false ceiling	NA	NA NA
	Internal Hydrants			
	A	Size of the riser/down comer	100 mm	Provided MR
13	B	No. of hydrants per floor	02 nos. each	Provided MR
	C	Hose box	02 nos. each	Provided MR
	Yard Hydrants			
14	A	Total no. of hydrants	05 nos.	Provided MR
	B	Hose box	05 nos.	Provided MR
	Pumping Arrangements			
15	A	Ground Level		
		a) Discharge of main pump	2280 LPM	Provided MR
		b) Head of main pump	60 m	Provided MR
		c) Number of main pump	01 no.	01 no. MR
		d) Discharge of jockey pump	180 LPM	Provided MR
		e) Head of jockey pump	60 m	Provided MR
		f) Discharge of standby pump	2280 LPM	Provided MR
		g) Head of standby pump	60 m	Provided MR
		h) Auto starting/ manual stopping	Required	Provided MR
	B	Terrace Level		
		a) Discharge of terrace pump	NA	900 LPM NA
		b) Head of terrace pump	NA	NA NA
		c) Alternate power supply	NA	NA NA
		d) Auto starting of pump	NA	NA NA
16	Captive Water Storage for Fire Fighting			
	A	Underground tank capacity	50,000 ltr.	1,50,000 ltr. MR
	B	Draw off connection	Required	Provided MR
	C	Fire service inlet	Required	Provided MR
	E	Access to tank	Required	Provided MR
	D	Overhead tank capacity	10,000 ltr.	Provided MR
17	Exit Signage		Required	Provided MR
18	Provision of lift			
	A	Pressurization of lift shaft	Required	Provided MR
	B	Pressurization of lift lobby	NA	NA NA
	C	Communication in lift car	Required	Provided MR
	D	Fireman switch	Required	Provided MR
	E	Lift signage	Required	Provided MR
19	Standby Power Supply			

-N/16-

18	Refuge Area			
	A	location	NA	NA
	B	Total area	NA	NA
19	Fire Control Room			
	A	Fire detection system panel	Required	Provided
	B	Flow switch panel	NA	NA
	C	P A system panel	Required	Provided
	D	Battery backup	Required	Provided
	E	Building floor plan	NA	NA
20	Special Fire Protection for special risk if any ABC&CO2		Co2 flooding system provided at HT/LT panel rooms	

Accordingly, the fire protection systems provided in the building were tested, checked at randomly and found in working condition at the time of inspections.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No. F6/DFS/MS/Hospital/NDZ/2022/220 dated 17.05.2022 is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

[Signature] 14/5/25
 Signature of the Inspecting Officer
 Name Rajinder Atwal
 Designation DO (CD)

[Signature] 14/05/2025
 Signature of the Inspecting Officer
 Name Sumit Kumar
 Designation ADO (SPM)

[Signature]
 Dy. CFO (NDZ)

[Signature]
 C.F.O.

[Signature]
 Director

[Signature]
 Director (D.F.S.)

[Signature]
 f.T. letter is put up for signature, please

[Signature] 15/05/25