

No.F.6/DFS/MS/School/2025/SZ/ 513

Dated:

22 04 2025

## FIRE SAFETY CERTIFICATE

Certified that the SantNirankari Public School at 20-B Block, Tilak Nagar, New Delhi-110018, comprised of ground plus three upper floors owned/occupied by SantNirankari Public issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/School/2022/SZ/622 dated 10.06.2022. The school building was re-inspected by the officer concerned of this department on 11.04.2025 in the presence of Smt. Leena Kapoor (HM) and found that school building have deemed complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules 2010 and that the building/ premises is fit for occupancy class "EducationalBuilding" w.e.f. 22 04 225 or a period of three years, in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delha Fire Service Rules, 2010 printed below.

Issued on 22 04 2025 at New Delhi.

Director

Delki Fire Service

Copy to:-

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

2. The Manager, Sant Nirankari Public School, 20-B Block, Tilak Nagar, New Delhi-110018

## Conditions for validity of fire safety certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior

## **INSPECTION REPORT**

1. Name & address of the building : Sant Nirankari Public School, 20-B Block, Tilak Nagar, New Delhi-18

2. Building comprised of : Ground plus three upper floors.

3. Type of Occupancy : Educational4. Type of Case : Renewal

5. Details of Previous NOC : F.6/DFS/MS/School/2022/SZ/622 dated 10.06.2022

6. Fire Safety directives letter No : UBBL/NBC
7. Date of inspection : 11.04.2025

8. Name of Inspecting Officer : A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side : Smt. Leena Kapoor (HM)

10. Year of Construction : 2005 (GF & FF) & 2017 (SF & TF)

11. Applicant's letter No. : SNPS/TN/2025-26/2512 dated 04.04.2025

S. No.		num Standards on fire prevention re safety U/R 33	Requirements UBBL/NBC	Provided at site	Remarks MR/NMR		
١.	Access to building						
	:	Road width Gate width Width of internal road	06 m 4.5 m N/A	Provided Directly accessible from road N/A	M/R M/R N/A		
2.	Numb	er Width, Type & Arrangement of	Exits				
	a. Nun	ber of staircases		04 No.'s	M/R		
	•	Upper Floors	02 No.'s	N/A	N/A		
	•	Basements	N/A	N/A			
	h Wid	th of staircases	1.50 m	1.80 (2 No's), 120& 1.10 m	M/R		
	D. WILL	Upper Floor	ASSOCIATION CONTRACTOR	N/A	N/A		
		Basements	N/A	13//3			
			N/A	N/A	N/A		
	c. Prote	ection of exits	250	N/A	N/A		
	•	Fire check door	N/A	10/20			
	•	Pressurization	Two	Provided	M/R		
		of continuous staircases to	1.50 m	Provided	M/R		
		ce h of Corridor r Size	1.0 m on GF &FF 1.20 m on SF & TF	Provided	M/R		
	Compa	tmentation	The state of the s				
	-		N/A	N/A	N/A		
		Fire check door	N/A	N/A	N/A		
		Sealing of electrical shafts	0.590.55	N/A	N/A		
		Fire Rating of shaft door	N/A	N/A	N/A		
		Water Curtain	N/A	N/A	N/A		
		Fire Dampers	N/A	1074			
	Smoke	Management System		N/A	N/A		
		Basements	N/A	Natural ventilation provided	M/R		
	• [	Jpper floors	Required	1 Communicated 85			
	Fire Extinguishers						
	• 7	Cotal numbers	03 no's/floor	Provided	M/R		
	1.0	ypes	ABC/CO <sub>2</sub> type	Provided	M/R		
		S marking	ISI marked	Provided	M/R		
	First-Aid	l Hose Reels	1		0		
	• т	otal numbers on each floor	02 no.'s per floor	Provided	M/R		
		ength of hose reel hose	30 m	Provided	M/R		
		Anger of Hose teet Hose	5 mm	Provided	M/R		

N/24

	Automatic fire detection and alarming system	m		
		N/A	N/A	N/A
	Type of detectors     Shair Panel	N/A	N/A	N/A
	Location of Main Panel     Secretar Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power     Hooters' Location	N/A	N/A	N/A
		N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
).	Public Address System			
10.	Automatic Sprinkler System	N/A	N/A	N/A N/A
	Basement	N/A	N/A	
	Ground Floor     Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
11.		N/A	N/A	N/A N/A
	Size of riser/down-comer  Size of riser-down-comer  Size of riser	N/A	N/A	N/A N/A
	Number of hydrants per floor     Hose Box	N/A	N/A	IVA
12	Yard Hydrants			
12.		N/A	N/A	N/A N/A
	Total number of hydrants     Hose Box	N/A	N/A	IN/A
12	Pumping Arrangements	No.		Page 2
13.	- ty1			N/A
	■ Ground Level     ➤ Discharge of main Pump	N/A	N/A	N/A
	> Head of Main pump	N/A	N/A	N/A
	> Number of main pumps	N/A	N/A	N/A
	> Jockey Pump out put	N/A	N/A	
	> Jockey pump head	N/A	N/A	N/A
	➤ Standby Pump out put	N/A	N/A	N/A
	> Standby Pump Head	N/A	N/A	N/A
	> Auto Starting/Manual Stopping	N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level		Provided	M/R
	> Discharge of pump	450 LPM	Provided	M/R
	➤ Head of the pump	40 m Required	Provided	M/R
	<ul> <li>➢ Power Supply</li> <li>➢ Auto Starting of pump</li> </ul>	Required	Provided	M/R
	Service Consistency of Section 50			
14.	Captive Water Storage for fire fighting		37/4	N/A
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	> Fire service inlet	N/A	N/A N/A	N/A
	> Access to tank	N/A	Provided	M/R
	Overhead Tank capacity	10000 ltrs Required	Provided	M/R
15.	Exit Signage.	Required		
16.	Provision of Lifts.		No Lift	
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
_	Lift Signage	N/A	N/A	N/A
¥	7	121		

N/A	N/A	N/A				
N/A	N/A	N/A				
Fire Control Room						
N/A	N/A	N/A				
N/A	N/A	N/A				
	N/A	N/A				
N/A	N/A	N/A				
N/A	N/A	N/A				
N/A	N/A	N/A				
	N/A N/A N/A N/A	N/A				

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required under the Rules the FSC was issued vide letter no. F.6/DFS/MS/School/2022/SZ/622 dated 10.06.2022 renewal under the Rule 37 of the Delhi Fire Service Rules 2010is recommended.

Signature of Inspecting

Name: -R.K. Yadav Designation: - ADO (JKP)

DO (South West)

16/4/25

17 41 20x

Director

Ballynn

-T hetter a put cy

DIRECTOR

er sign Mean

10/4/2016