

FORM 'H': FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[See sub-rule (1) of rule 35] GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.F.6/DFS/MS/School/2025/NDZ/ 922

Dated: 25/07/2025

FIRE SAFETY CERTIFICATE

Certified that the Sardar Patel Public Senior Secondary School located at Karawal Nagar, Delhi-110094, building comprised of Ground plus three upper floors only but school running on Grund and Two Upper floors only (The Principal of the school has submitted an affidavit dated 09/07/2025 that the 3rd floor is closed and not in use for the school or any other activity), owned / occupied by Sardar Patel Public Senior Secondary School, has already been issued Fire Safety Certificate Vide letter No. F6/DFS/MS/School/2022/NDZ/64 dated 24/01/2022. The premises was re-inspected by the officer concerned of this department on 09/07/2025 in the presence of Sh. Satish Kumar (Vice-Chairman) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with rule 33 of the Delhi Fire Service Rules, 2010 and found that the school building is fit for Ground plus two upper floors occupancy class "Educational" (Group-B) with effect from \$\(\frac{\mathbf{S}}{\subset} \) / O \(\frac{\subset}{2025} \) for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rules, 2010. Subject to conditions printed below.

Issued on 25/07/2025 at New Delhi by

W 15/7/20x

(VIRENDRA SINGH) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to :-

1. The Principal, Sardar Patel Public Senior Secondary School, Karawal Nagar, Delhi-110094.

2. The Dy. Director of Education, B-Block, Yamuna Vihar, Delhi-110053.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape / entry / exit shall be kept free from any obstruction.

- 2. All the fire safety arrangement provided there in shall be maintained in good working conditions at all times.
- Any loss of life or property due to non- functional fire safety measure shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of fire fighting system.

5. This Fire Safety Certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3. of UBBL-2016), if any.

6. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on <u>WWW.dfs.Delhigovt.nic.in.</u>

INSPECTION REPORT

1. Name & address of the building: Sardar Patel Public Sr. Sec. School

Karawal Nagar, Delhi-110094.

2. Type of Occupancy 3. Building Comprised of

: Educational, Group-B(School) : Ground plus three upper floors but

School running on G+2 upper floors only.

(3rd floor closed and not in use)

4. Type of Case

: Renewal

5. Details of previous NOC No. F6/DFS/MS/School/2022/NDZ/64 dated 24/01/2022

6. Fire Safety directives Letter No.: NBC (Part-IV) 7. Date of inspection : 09/07/2025

8. Name of the Inspecting Officer

: A.K. Jaiswal (D.O.)

9. Name and designation of Officer

from the building side

: Sh. Satish Kumar (Vice-Chairman)

I. AJ S No	Minimum standards on fire prevention and fire safety	NBC (Part-IV)		Provided at site	Remarks MR/NM		
	U/R 33	Requireme	ent		R		
1.	Access of building						
	Road width	6m		4.50 m	MR		
	Gate width	4.50 m		E-19455C1 2744	NA		
	Width of internal road	NA		NA			
2.	Number, width, Type & Arrar	ngements of e	exits	alimber and the			
	a Number of staircases						
	Upper floors	2	3		NA		
	Basements	NA -	NA		1 4		
	Width of staircases	1.50 m x 2	1.66m, 1.05m &0.95m		MR		
	Upper floors	AMAZONO LEMBARONA	NATE OF THE REPORT		NA		
	Basements	INA	NA NA		n Turker		
	Protection of exits NA NA NA						
- 11	 Fire check door 	NA			NA		
	 Pressurization 	NA	NA ,		MR		
	b. No of continuous staircase to terrace	1	2				
	c. Width Of Corridor	1.50m	2.13m		MR		
	d. Door Size	1.00m	1.06m	TO Lat 2 and	MR		
3.	Compartmentation		Tel-2004		9		
).	Fire check door	NA	NA		NA		
	 Sealing of electrical shafts 	NA	NA		NA		
	Fire Rating of shaft door	NA	NA		NA		
	Water Curtain	NA	NA		NA		
	Fire Dampers	NA	NA .		NA		
	Smoke managements System						
	Basements	NA	NA		NA		
	Upper floors	NA	NA	and the second of	NA		
.	Fire Extinguishers						
	Total numbers	12 Nos	15 Nos .		MR		
	• Types	ABC /Co ₂	Provided		MR		
-	ISI marking	ISI	Provided		ADDIVIOLOGIA		
	• 151 marking	Marked	X	lus vi	MR		
	- 1//			100			

i.	First – Aid Hose Reels	02 no.	02 no.	MR
	Total numbers on each floor	5/2=20	30m	MR
	 Length of hose reel hose 	30m	5 mm	MR
	Nozzle diameter	5 mm	J 111111	TARREST PARTY.
	Automatic fire detection and alarming	system	NA	NA
002	. Type of detector	NA	NA NA	NA
	Location of Main Panel	NA		NA
¢0	Location of Repeater Panel	NA	NA	NA
	Alternate source of power	NA	NA	PISSVISI
	Hooters' Location	NA	NA	NA .
	MOEFA	NA	NA	NA NA
	Public Address System	NA	NA	IVA
0.	Automatic Sprinkler System	NA	NA	NA
ř	Basements Upper Floor	NA	NA	NA
	Opper Floor Sprinkler above false ceiling	NA	NA	NA
1.	Internal Hydrants	1		
	Size of riser/down- comer	NA	NA .	NA NA
	Number of hydrants per floor	NA	NA	
	Hose Box	NA	NA	NA
2.	Yard Hydrants			NIA.
6	Total number of hydrants	NA NA	NA NA	NA NA
,	Hose Box Duraning Amongoments	NA .	INA	INA
3.	Pumping Arrangements Ground Level			
	Discharge of main pump	NA	NA	NA
1	Head of main pump	- NA	NA	NA
	Number of main pumps	NA	NA	NA
 ➢ Jockey pump out put ➢ Jockey pump head 		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
Standby Pump out put				-
- 2	Standby Pump Head	NA	NA	NA
Auto Staring/Manual stopping		NA	NA	NA
7	Pump House Access	NA	NA	NA
•	Terrace level			
>	2 isolarge of pump	450 LPM	450 LPM	MR
7		40 mtr	40 mtr	MR
-	1 ower suppry	Required	Provided	MR
_	or pump	Required	Provided	MR
S.	Captive water Storage for fire fighting	1	var Colf	1.
	Under ground tank capacity	NA	NA	NA
	> Draw of connection	NA	NA	NA
	Fire service inlet	NA	NA	NA
	> Access to tank	NA	NA	NA
	Overhead Tank capacity	10,000 Ltr	10,000 Ltr	MR
	70		*	

5	Exit Signage	Requiréd	Provided	MR			
16.	Provision of Lifts						
	Pressurization of Lift Shaft	NA	NA	NA			
izi.	 Pressurization of lift lobby 	NA	NA	NA			
	Communication in lift	NA	NA	NA			
	Car Fireman's Grounding	NA	NA ,	NA			
	Switch > Lift Signage	NA	ZANA E	NA			
17.	Standby power supply	NA	NA	NA			
CARLON CO.							
18.	Refuge Area	NA	NA	NA			
	> Total area		NA	NA			
	> Location	NA	NA .				
19.	Fire control room						
	> Detector system panel	NA	NA	NA NA			
		NA .	NA				
	> Flow Switch Panel	NA .	NA	NA			
	PA System Panel	83X 8	NA	NA			
	Battery backup	NA	NA ·	·NA			
	Building Floor Plans	NA .		NA			
20.	Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA .	Cah			

Note:- School Building presently comprised of Ground plus three upper floors. School is running only on Ground, 1st floor & 2nd floor only. The Principal of the school has submitted an affidavit dated 09/07/2025 that the 3rd floor is closed & not in use. Photographs & Affidavit regarding this is placed at C-48 to C-50.

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter No. F6/DFS/MS/School/2022/NDZ/64 dated 24/01/2022 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

> Signature of the Inspecting Officer : Ashok Kumar Jaiswal Name

Designation: D.O. (East)