

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**



No. F6/DFS/MS/2025/School/ 1093

Dated: 02 /09 /2025

## FIRE SAFETY CERTIFICATE

Certified that the Sarvodaya Co-ed Vidyalaya (School I.D No-1208013) located at Gulabi Bagh, Delhi-110007 comprised of 02 New blocks interconnected, ground & 03 upper floors each only owned/ occupied by Sarvodaya Co-ed Vidyalaya was issued Fire Safety Certificated vide this office letter no. F6/DFS/MS/2022/School/WZ/427 dated 19/04/2022 the premises was reinspected by the officer concerned of this department on 22/08/2025 in the presence of Sh. Atit Saini (H.O.S) and observed that all the fire prevention and fire safety arrangements as provided in the premise found in good working condition. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy under "Group B Educational (School)" with effect from ....02 .0.9. 2025 for a period of three years, in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

Issued on ... 02 09 2025 at New Delhi by

Virendra Singh Chief Fire officer Delhi Fire Service

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.

2. The Principal, Sarvodaya Co-ed Vidyalaya (School I.D No-1208013) located at Gulabi Bagh, Delhi-110007.

## Conditions for the validity of Fire Safety Certificate:

1. All the means of escape shall be kept free from any type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipment and method of smooth and speedy safe evacuation of occupants in case of emergency

3. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seem during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities. This Fire Safety Certificate is valid only for permanent building structure as per plan.

This fire safety certificate may not be treated in any case of regularizations of unauthorized construction/unauthorized use of land or activities, if any.

The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on the official website of Delhi Fire Service i.e. www.dfs.delhigovt.nic.in.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

**INSPECTION REPORT** 

1. Name & address of the building

2. Type of Occupancy

: Sarvodaya Co-ed Vidyalaya at Gulabi Bagh, Delhi-110007. (ID No-1208013) : Educational

3. Composition of building : Educ

: 02 New Blocks, Interconnected, Ground & 03 upper floors

4. Type of Case

: Renewal

5. Details of previous NOC

: F6/DFS/MS/2022/School/WZ/427 dated 19/04/2022

6. Fire Safety directives letter No

: Nil

7. Date of inspection

: 22/08/2025

8. Name of the Inspecting Officers

: ADO (RN)

9. Name and designation of officers

from the building side

: Sh. Atit Saini (H.O.S)

10. Year of Construction

: 2019-2020

11. Applicant's letter No.

: No- S.Co-Ed.V/GB/2025/306 dated: 11/08/2025

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Part-IV Requirements	Provided at site	Remarks MR/NMR		
1	Access to building			MR		
	Road width	06m	06m			
	Gate width	4.50m	06m	MR		
	Width of internal road	NA	NA	NA		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases			MR		
	Upper Floors	03	03	A1180000		
	Basements	NA	NA	NA		
	b. Width of staircases			MD		
		1.50m	03 nos. of 1.80m	MR		
	Upper Floors  Documents	NA	NA	NA		
	Basements		T	27.4		
	c. Protection of exits	NA	NA	NA		
	Fire check door	NA	NA NA	NA		
	Pressurization	02	02	MR		
	d. No. of continuous staircases to terrace	1.50m	1.50m	MR		
	e. Width of Corridor	1.20m	1.20m	MR		
	f. Door Size	1.2011	1.2011			
3	Compartmentation.	NA	NA	NA		
	Fire check door	NA NA	NA NA	NA		
	Sealing of electrical shafts	NA	NA	NA		
	Fire Rating of shaft door	NA	NA	NA		
	Water Curtain	NA	NA	NA		
	• Fire Dampers	137.6	- 7.			
4	Smoke Management System.	NA	NA	NA		
	Basements		1,50,000	======================================		
	Upper floors	Required	Natural Ventilation	MR		
5	Fire Extinguishers					
	Total numbers	28nos	Provided	MR		
	• Types	ABC/Co2	Provided	MR		
	ISI marking	ISI Marked	Provided	MR		
6	First-Aid Hose Reels					
	Total numbers on each floor     Length of hose reel hose	03 each floor	Provided	MR		
	Length of nose reel nose     Nozzle diameter	30m	Provided	MR		
	45.0	5mm	Provided	MR		
0.000		0. 1.		IVIK		

7	Automatic fire detection and alarming system	NIG			
	Type of detectors	NA NA	NΛ	NA	
	Location of Main Panel	NA	NA NA		
	Location of Repeater Panel	NA NA	NA NA	NA NA	
	Alternate source of power	NA	NA	NA NA	
	Hooters' Location  MOEFA	NA NA	NA NA	NA NA	
8					
9	Public Address System.				
10	Automatic Sprinkler System.				
	Basement	NA	NA	NA	
	Upper Floor	NA	NA	NA	
	Sprinkler above false ceiling	NA	NA	NA	
11	Internal Hydrants			1	
	Size of riser/down-comer	NA	NA	NA	
	Number of hydrants per floor	NA	NA	NA	
	Hose Box	NA	NA	NA	
12	Yard Hydrants.	L			
	Total number of hydrants	NA	NA	NA	
	Hose Box	NA	NA	NA	
3	Pumping Arrangements			1	
	Ground Level		) III		
	<ul> <li>Discharge of main Pump</li> </ul>	N/A	N/A	N/A	
	➤ Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	West Marth.			
	<ul> <li>Jockey Pump out put</li> </ul>	N/A	N/A	N/A	
	Jockey pump head	NA	N/A	NA	
	➤ Standby Pump out put	NA	N/A	NA	
	<ul> <li>Standby Pump Head</li> </ul>	N/A	N/A	N/A	
	<ul> <li>Auto Starting/ Manual stopping</li> </ul>	N/A	N/A	N/A	
	Pump House Access	N/A	N/A	N/A	
		19//4	N/A	19/1	
	Terrace level	450 LPM	Provided	MR	
	<ul><li>Discharge of pump</li></ul>		Provided	MR	
	Head of the pump	40m	433000000000000000000000000000000000000		
	Power Supply	Required	Provided	MR	
	Auto Starting of pump	Required	Provided	MR	
1	Captive Water Storage for fire fighting				
	Underground tank capacity	NA	N/A	NA NA	
	> Draw-off connection	NA NA	NA NA	NA NA	
	<ul><li>Fire service inlet</li><li>Access to tank</li></ul>	NA NA	NA NA	NA NA	
	Overhead Tank capacity	10,000 LTR	Provided	MR	
	Exit Signage.	Required	Provided	MR	
	Provision of Lifts.	1			
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	<ul> <li>Pressurization of Lift lobby</li> </ul>	N/A	N/A	N/A	
	<ul> <li>Communication In lift Car</li> </ul>	N/A	N/A	N/A N/A	
	<ul> <li>Fireman's Grounding Switch</li> </ul>	N/A N/A	N/A N/A	N/A N/A	
	Lift Signage	N/A	Transport.	N/A	
5	Standby power supply	N/A	N/A	IV/A	

18	Refuge Area.					
	<ul><li>Total Area</li><li>Location</li></ul>	N/A	N/A	N/A		
		N/A	N/A	N/A		
19	Fire Control Room					
	<ul> <li>Detector System Panel</li> <li>Flow Switch Panel</li> <li>PA System Panel</li> <li>Batter backup</li> <li>Building Floor Plans</li> </ul>	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. F6/DFS/MS/2024/School/349 dated 07/05/2025.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-4, it is recommended for renewal of fire safety certificate issued vide this department letter of even no. F6/DFS/MS/2022/School/WZ/427 dated 19/04/2022.

Signature of the Inspecting Officer

Name :- C.L. Meena Designation:- ADO/RN

D.B. Mukharjee (DO/NW)

letter is larup for your