

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/School/SZ/2025/ 1314

Dated: 13/11 /2025



FIRE SAFETY CERTIFICATE

Certified that the Sarvodaya Kanya Vidyalaya No.1 (Morning shift) Govt. Boys Sr. Sec. School No.1 (Evening shift) located at Madanpur Khadar New Delhi - 110076, building comprised of 02 block: A block - Ground + 3 Upper floors (Old block) & E block – Ground + 3 upper floors (New block) Each block Interconnected with all floors level owned / occupied by Sarvodaya Kanya Vidyalaya No.1 (Morning shift)/ Govt. Boys Sr. Sec. School No.1 (Evening shift), was issued FSC vide letter No. F6/DFS/MS//School/SZ/2022/1071 dated 27/09/2022. The school building was re-inspected by the officer concerned of this department on 25/10/2025 in presence of Mr. Roop Ram Meena (Principal/HOS) and overseed that all the Fire Prevention and Fire Safety arrangement provided found in good working condition. The premises have therefore deemed rule 33 of Delhi Fire Service Rules, 2010 and that the building / premises is fit for occupancy class "Educational Building" (Group-B) with effect from 13/11/2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

13 11 2 = 25 at New Delhi by,

(A.K.Malik) Dy. Chief Fire Officer Delhi Fire Service

Copy to: -

- The Director of Education, GNCT of Delhi, Old Secretariat, Delhi 110054.
- The Principal, Sarvodaya Kanya Vidyalaya No.1 (Morning shift) at Madanpur Khadar New Delhi -110076.
- 3. Principal, Govt. Boys Sr. Sec. School No.1 (Evening shift) at Madanpur Khadar New Delhi 110076

Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

					M)27				
			Ī	NSPE	CTION REPOR	RT			
1	Name & address of the building			ing	Sarvodaya Kanya Vidyalaya No.1 (Morning shift)/ Govt. Boys Sr. Sec. School No.1 (Evening shift) located at Madanpur Khadar New Delhi – 110076.School ID no. 1925062 (Morning shift) School ID no.1925448 (Evening shift) Building ID no. 19251416				
2	Building is comprised of				Comprised of 2 blocks: A block - Ground + 3 upper floors (Old block) E block - Ground + 3 upper floors (New block) Each block Interconnected with all floors level				
3	Type of occupancy				Educational Building Group - B				
4	Ту					Renewal			
5	Details of previous FSC				F6/DFS/MS//School/SZ/2022/1071 dated 27/09/2022				
6	Fire safety directives letter no.			ý.	NBC Part IV & UBBL 2016				
7		Date of inspection			25/10//2025	0.04 D4			
8		Name of the inspecting officers			Y.S.Meena AD	Means (Principal/HO	S)		
9	fro	Name of the designation of officer from the building side				Mr. Roop Ram Meena (Principal/HOS)			
10	Ye	ar c	of construction		2018 & 2022	No. 5564 Dated 03/09	/2025		
11	Ap		cant's letter no.		Outdoor Dairy	No. 5564 Dated 03/09. Provided at site	Remarks		
S.N	pr		inimum standard of fi ntion and fire safety U		NBC Part-IV Provided at site Remark Requirement MR/NM				
1.	Access to Building:			6.0 meters. MR					
	A Road width		9	6.0 meters.	New March Control of the Control of	N/A			
	В	Gate width		N/A		N/A	N/A		
	C	V	lidth of internal road		N/A	N/A	IVA		
2.	Nu	mb	er, Width, Type and A	rrange	ement of Exits:				
	A	N	lumber of staircases			A block – 4 nos.	MR		
		a	••		block – 4 nos. block – 3 nos. N/A	E block – 3 nos N/A	N/A		
		b			- ne-				
	В	a	Vidth of staircases Upper floor	1.5	meters, eachs	1.7 meters, each block	MR		
	-	b	Basement		N/A	N/A	N/A		
	C		rotection of exits		NT/A	NT/A	N/A		
		a	Fire check door		N/A N/A	N/A N/A	N/A N/A		
	D	b		02 n	os. each block	02 nos. each block	MR		
	ען	staircases to terrace				1.6 meters.	MD		
	E				1.5 meters	1.6 meters. 1.0 meters for class	MR		
	F	F Door size		1.0 met	ters for class room	room	MR		
3.	Compartmentation:				NA	NA	N/A		
	A	A Fire check door			N/A	N/A	NA N/A		
	В	shafts			N/A	N/A	N/A N/A		
	C	door			N/A	N/A			
3	D Water curtain		N/A		N/A N/A	N/A			
	E Fire dampers				IN/A	N/A			
4.	Smoke Management System:				N/A	N/A	NI/A		
	A	- 72	asement		N/A w	N/A	N/A		
	В	U	pper floor			- M.A.A	N/A		

5.		e Extinguisher:	-	T 10022	1930			
	A	Total numbers	30 nos.	162 nos	MR			
	B	Types	CO ₂ & ABC	CO ₂ & ABC	MR			
	C	ISI marking	ISI Marked	ISI Marked	MR			
6	Fi	rst-Aid-Hose Reel:		1				
	A	Total numbers of each	A block – 03 nos.	A block – 03 nos.	MR			
	_	floor	E block - 04 nos.	E block - 04 nos.				
	B	Length of hose reel hose	30 mtrs.	30 mtrs.	MR			
	C	Nozzle diameter	05 mm	05 mm	MR			
7	Automatic Fire Detection and Alarming System:							
	A	Type of detectors	N/A	N/A	N/A			
	B	Location of main panel	N/A	N/A	N/A			
	C	Location of repeater panel	N/A	N/A	N/A			
	D	Alternate source of power	N/A	N/A	N/A			
	E	Hooters Location	N/A	N/A	N/A			
8	M	OEFA:	N/A	N/A	N/A			
9	Pu	blic Address System:	N/A	Provided	N/A			
10								
	A	Basement	N/A	N/A	N/A			
	В	Upper floor	N/A	N/A				
	C	Sprinkler above false	N/A	NULL TO SAN TO S	N/A			
	Nest	ceiling	IVA	N/A	N/A			
1	In	ternal Hydrants:						
	A	Size of riser/down-comer	N/A	N/A	N/A			
	В	Number of hydrants per	N/A	N/A	N/A			
	C	floor Hose box	N/A	27/4	STORE WILL			
12	Ya	rd Hydrants:	IVIA	N/A	N/A			
	A	Total number of hydrants	N/A	N/4				
	В	Hose box		N/A	N/A			
3			N/A	N/A	N/A			
-		mping Arrangements: round level						
	A	A SINCE THE STATE OF THE STATE						
	B	Discharge of main pump	N/A	N/A	N/A			
		Head of main pump	N/A	N/A	N/A			
	C	Number of main pumps	N/A	N/A	N/A			
	D	Jockey pump out put	N/A	N/A	N/A			
	E F	Jockey pump head	N/A	N/A	N/A			
		Standby pump out put	N/A	N/A	N/A			
	G H	Standby pump head	N/A	N/A	N/A			
	п	Auto starting /manual stopping	N/A	N/A	N/A			
	I	Pump house access	NT/A					
		race Level	N/A	N/A	N/A			
1	A	Discharge of pump each	450 LPM each	0.000				
		block	block	2 nos of 450 LPM	MR			
	_	II - 1 Ca		each block				
	В	Head of the pump	40 mtrs	10 mtur	3 42			
	B C	Head of the pump Power supply	40 mtrs. Required	40 mtrs. Provided	MR MR			

M129

Sarvodaya Kanya Vidyalaya No.1 (Morning shift)/ Govt. Boys Sr. Sec. School No.1 (Evening shift) located at Madanpur Khadar New Delhi - 110076

14	Caj	Madanpur Khadar New Delhi - 1100/6 ptive Water Storage for Fire Figh	N/A	N/A	N/A	
199	A	Underground tank capacity	N/A	N/A	N/A	
	B	Draw-off connection	dpnN/Aabai	- N/A	N/A	
	C	Fire service inlet	N/A	N/A	N/A	
	D	Access to tank	10,000 liters	10,000 liters	MR	
	E	Overhead tank capacity	each block	each block		
	-		Required	Provided	MR	
15	San All Care Palacon and the C					
16		vision of Lifts:	N/A	N/A	N/A	
10	-	Programization of lift shaft	151	N/A	N/A	
	A	Pressurization of lift lobby	N/A	N/A	N/A	
	B	Communication in lift car	N/A	N/A	N/A	
	_	Firemen's grounding switch	N/A	N/A	N/A	
	D E	Lift signage	N/A	N/A	N/A	
17	Sto	andby Power Supply:	N/A	1,7.2		
17	-	fuge Area:		NI/A	N/A	
18	Ke	Tuge Area.	N/A	N/A	N/A	
E	A	Total area	N/A	N/A	11/2	
	B Location					
19	-		N/A	N/A	N/A	
	A	Detector system panel	N/A	N/A	N/A	
	B	Flow switch panel	N/A	N/A	N/A	
	C	PA system panel	N/A	N/A	N/A	
	D	Battery backup	N/A	N/A		
	E	Building floor plans	N/A	N/A	N/A	
20	Sp	ecial Fire Protection systems for otection of special Risks, if any:	randomly checked			

The fire protection system was randomly checked and tested and was found functional at the time of inspection.

Keeping In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules of Directorate of Education the FSC issued vide letter no F6/DFS/MS//School/SZ/2022/1071 dated 27/09/2022, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended.

2819/2025

Signature of the Inspecting Officer Name: Yashwant Singh Meena Designation ADO/ Mathura Road