

Dated: 31/10/2025

FIRE SAFETY CERTIFICATE

Certified that the Sarvodaya (Co-ed) Senior Secondary Vidyalaya, Qutab Mehrauli, New Delhi-110030 (School ID-1923004), building comprised of Ground floor only, owned / occupied by Directorate of Education, Govt. of NCT of Delhi, was earlier issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/School/2022/SZ/1117 dated 10/10/2022. Now, the said premises was re-inspected by ADO/BCP of this department on 17/10/2025 in presence of Mr. Amit Panday (Principal) and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with Directorate of Education Circular No.F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 issued by the Director of Education, Govt. of NCT of Delhi and that the school building is fit for occupancy class "Educational Building" (Group - B) with effect from 31/10/2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of Delhi Fire Service Rules 2010.

Issued on 31/10/2025 at New Delhi by.

Dy. Chief Fire Officer
Delhi Fire Service

Copy to: -

Ľ

٤

10

r

- 1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.
- 2. The Principal, Sarvodaya (Co-ed) Senior Secondary Vidyalaya, Qutab Mehrauli, New Delhi-110030 (School ID-1923004).

Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

01.	No	INSP	ECTION REPORT		a andory			
01.	INA	me & address of the building	Vidyalaya, Quta	Vidyalaya, Qutab Mehrauli, New Delhi-110030				
02.	Bu	ilding is comprised of		(School ID-1923004)				
03.	Tv	pe of occupancy	Ground floor on	Ground floor only				
04.	Tv							
05.		tails of previous FSC	Renewal	Renewal F6/DFS/MS/School/2022/SZ/1117 dated				
05.		tails of previous FSC		10/10/2022				
06.	E:	n no fate. diameti. 1 ee	10/10/2022	F.16/Estate/CC/Fire Safety/2011/3298 to 3398				
	1 11	e safety directives letter no.	F.16/Estate/CC/1	dated 01/03/2011				
07.	Do	to of ingression	7000 1000 1000 1000 1000	17.10.2025.				
08.	Date of inspection 17.10.2025. Name of the inspecting officers Yashwant Singh Meena, ADO (BCP)			CP)				
	_		4 (7)					
09.	10000		of Wir. Affilt I allow	Mr. Aillit Failuay (Finasper)				
		icer from the building side	1056					
10.	402dated 20/U							
11.	200	plicant's letter no.	Old NOC	Dworden at				
S.No	-	nimum standard of fire evention and fire safety U/R 33	100 OF 10	site	MR/NMR			
01.	Ac	cess to Building:		6.0 mtrs.	MR			
	A	Road width	Accessible	4.0 mtrs	N/A			
	В	Gate width	N/A	N/A	N/A			
	C	Width of internal road	N/A					
02.	Number, Width, Type and Arrangement of Exits:							
	A	Number of staircases	- 15,5,	N/A	N/A			
		a Upper floor	N/A N/A	N/A	N/A			
		C Basement	N/A					
	В	Width of staircases	N/A	N/A	N/A			
		a Upper floor	N/A	N/A	N/A			
		C Basement	11/11					
	C	Protection of exits	N/A	N/A	N/A			
		a Fire check door	N/A	N/A	N/A			
		b Pressurization	N/A	N/A	N/A			
	D	No. of continuous staircases to terrace			37/4			
		Width of corridor	N/A	N/A	N/A			
	E	Door size	1.0 mtr.	Provided	MR			
	F	mpartmentation:		27/4	3T/A			
03.	$\overline{}$	Eire check door	N/A	N/A	N/A			
	A	Sealing of electrical shafts	N/A	N/A	N/A			
	B	Fire rating of shaft door	N/A	N/A	N/A			
	C	Water curtain	N/A	N/A	N/A			
	D	Eiro damners	N/A	N/A	N/A			
	E	oke Management System:		Luki a .	4			
04.		Basement	N/A	N/A	N/A			
	Transfloor		N/A	N/A	N/A			
	B	Upper Hoor		3				
05.		e Extinguisher: Total numbers		20 nos.	MR			
	A		ISI Marked	ABC-10 &	MR			
	B	Types		CO ₂ - 10	IVIIC			
		-az -adring	_	Provided	MR			
	C	ISI marking	(Q)	The second secon	MIK			

06.	First-Aid-Hose Reel:							
	A Total numbers of each floor		N/A	N/A	N/A			
	В	Length of hose reel hose	N/A	N/A	N/A			
	C	Nozzle diameter	N/A	N/A	N/A			
07.	Αι	itomatic Fire Detection and Alarmir	ng System:	, and a second s				
	A	Type of detectors	N/A	N/A	N/A			
	В	Location of main panel	N/A	N/A	N/A			
	C	Location of repeater panel	N/A	N/A	N/A			
	D	Alternate source of power	N/A	N/A	N/A			
	E	Hooters	N/A	N/A	N/A			
08.	-0.500	OEFA:	N/A	N/A	N/A			
09		blic Address System:	N/A	N/A	N/A			
10.	- Joseph							
	A	Basement	N/A	N/A	N/A			
	B	Upper floor	N/A	N/A	N/A			
11.	C	Sprinkler above false ceiling	N/A	N/A	N/A			
11.		ernal Hydrants:						
-	A B	Size of riser/down-comer	N/A	N/A	N/A			
-	C	Number of hydrants per floor Hose box	N/A	N/A	N/A			
12.		Section 1995 Section 1995	N/A	N/A	N/A			
12.	A	rd Hydrants:	797					
	B	Total number of hydrants Hose box	N/A	N/A	N/A			
	S.TIO		N/A	N/A	N/A			
	Pumping Arrangements:							
	A Discharge C							
. 1	B	Discharge of main pump	N/A	N/A	N/A			
_	C	Head of main pump	N/A	N/A	N/A			
-	D	Number of main pumps	N/A	N/A	N/A			
-	E	Jockey pump out put	N/A	N/A	N/A			
	F	Jockey pump head	N/A	N/A	N/A			
	G	Standby pump out put	N/A	N/A	N/A			
	H	Standby pump head	N/A	N/A	N/A			
		Auto starting /manual stopping	N/A	N/A	N/A			
]		Pump house access	N/A	N/A	N/A			
	-	ace Level			14/21			
-	4	Discharge of pump	N/A	N/A	N/A			
	3	Head of the pump	N/A	N/A	N/A			
_		Power supply	N/A	N/A	N/A			
I)	Auto starting of pump	N/A	N/A				
l. (Captive Water Storage for Fire Fighting:							
A		Underground tank capacity	N/A	NT/A	271			
B		Draw-off connection	N/A	N/A	N/A			
(_	Fire service inlet		N/A	N/A			
D		Access to tank	N/A	N/A	N/A			
	_	C 0440 VIII MAG	N/A	N/A	N/A			
E		Overhead tank capacity	N/A	N/A	N/A			
. E	xit	Signage:	Required /	Provided	MR			

@

S

16.	De	ovision of Lifts:	0	The state of the s		
i () i		Addition of Plus			N/A	
0	٨	Pressurization of lift shaft	N/A	N/A	N/A	
	B	Pressurization of lift lobby	N/A	N/A	N/A	
	C	Communication in lift car	N/A	N/A	N/A	
	D	Firemen's grounding switch	N/A	N/A	N/A	
	E	Lift signage	N/A	N/A	N/A	
17.	Sta	ndby Power Supply:	NA	N/A	N/A	
18.	Refuge Area:					
	A	Total area	N/A	N/A	N/A N/A	
2	B	Location	N/A	N/A	N//	
19.	Fire Control Rooms					
	A	Detector system panel	N/A	N/A	N/A	
-	В	Flow switch panel	N/A	N/A	N/A	
-	C	PA system panel	N/A	N/A		
-	D	Battery backup	N/A	N/A	N/A	
	-		N/A	N/A	N/A	
	E	Building floor plans	NA	N/A	N/A	
20.	100	ecial Fire Protection systems for otection of special Risks, if any:		1	nd was	

The fire protection system was randomly checked and tested and was found

functional at the time of inspection.

Keeping in view of the deemed compliance of minimum standards on fire prevention and fire safety measures as required under the rules, the Fire Safety Certificate issued vide letter no. F6/DFS/MS/School/2022/SZ/1117 dated 10/10/2022, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Signature of the Inspecting Officer Name: - Yashwant Singh Meena

Designation: - ADO/BCP