

### GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No. F6/DFS/MS/School/NDZ/2025/ 38

Dated: 30/01/2025

#### FIRE SAFETY CERTIFICATE

Certified that the Sarvodaya Kanya Vidyalaya No. 1 located at Veer Udham Singh, Mandawali, Delhi - 110092, building comprised of Block A - Ground plus one upper floor & Block B & C - Ground plus three upper floors owned/occupied by Sarvodaya Kanya Vidyalaya No. 1 was issued FSC vide letter No. F6/DFS/MS/School/NDZ/2021/1098 dated 31/12/2021. The School building was re-inspected by the officer concerned of this department on 22/01/2025 in presence of Dr. Alka H. Singh (Principal) and observed that all the fire prevention and fire safety requirements provided in the premises found in good working condition. The premises have therefore deemed complied with rule 33 of Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class "Educational Building" (Group - B) with effect from 30/01/2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 30 01 2025 at New Delhi by.

(ATGLGARG)
DIRECTOR
COLLINI FIRE SERVICE

#### Copy to: -

- 1. The Director of Education, East Delhi Muncipal Corporation, 419, Udyog Sadan, Patparganj Industrial Area, Delhi-110092.
- 2. The Principal, Sarvodaya Kanya Vidyalaya No. 1 located at Veer Udham Singh, Mandawali, Delhi-110092.

## Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

- Nlig -

	INSPECTION REPORT							
1	Name & address of the building Sarvodaya Kanya Vidyalaya No. 1, located Veer Udham Singh, Mandawali, Delhi - 110092.							
2	- 1		ng is comprised of	A block - Ground plus one upper floor & B & block - Ground plus three upper floors				
3	Type of occupancy			Educational Building				
4	Type of case			Renewal	-			
5	Details of previous FSC		s of previous FSC	F6/DFS/MS/School/NDZ/2021/1098 dated 31/12/2021				
6	Fire safety directives letter no.			NBC Part - IV				
7	Date of inspection			22/01/2025				
8	Name of the inspecting officers Yashwant Singh Meena ADO (Laxmi Na			ni Nagar)				
9	Name of the designation of officer from the building side			Dr. Alka H. Singh (Principal)				
10			of construction	2016		100 54		
11	An	Applicant's letter no.		Email dated 17/01/2025				
S. No		M	inimum standard of fire ntion and fire safety U/R 33	Requirement Circular	Provided at site	Remarks MR/NMI		
1.	Ac	ces	s to Building:					
1	A	R	oad width	6.0 meters	10 meters	MR		
	В	G	ate width	4.5 meters	4.5 meters	MR		
	C		Vidth of internal road	N/A	N/A	N/A		
2.			er, Width, Type and Arrang					
2.	-		lumber of staircases	ement of Dates.				
	A	L				l MD		
1	Ty:	a	Upper floor	04 nos. A block 02 nos. B & C bloc	ks Provided	MR		
		b	Basement	N/A	N/A	N/A		
	В	V	Vidth of staircases					
1		a	Upper floor	1.5 meters.	1.5 meters. each	MR		
		b	Basement	N/A	N/A	N/A		
	C	P	rotection of exits	N/A	N/A	N/A		
		a	Fire check door	N/A	N/A	N/A		
	D	N	Pressurization  lo. of continuous staircases of terrace	02 nos.	02 nos.	MR		
	E		Vidth of corridor	1.5 meters	Provided	MR		
	F	D	oor size	1.0 meter.	1.10 meter.	MR		
3.	-		artmentation:		_			
	A Fire check door		the state of the s	NA	NA	NA		
	1.500	B Sealing of electrical shafts		N/A	N/A	N/A		
	C		ire rating of shaft door	N/A	N/A	N/A		
	D	_	/ater curtain	N/A	N/A	N/A		
	E	20	ire dampers	N/A	N/A	N/A		
1.	0.00		Management System:		- AND AND A			
-	-		asement	N/A	N/A	N/A		
	A B		pper floor	N/A	N/A	N/A		
	I D	U	pper moor	A 1/4 A	14/11	A 4/ 4 A		

- N/20 -

# Sarvodaya Kanya Vidyalaya No-1, Veer Udham Singh, Mandawali, Delhi-110092

5.	Fi	re Extinguisher:			+				
	A	Total numbers	30 nos.	40 nos.	MR				
	B	Types	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	MR				
	C	ISI marking	ISI Marked	ISI Marked	MR				
6	First-Aid-Hose Reel:								
	A Total numbers of each floor		B & C block 02 nos.	B & C block 02 nos.	MR				
	В	Length of hose reel hose	30 meters.	Provided	MR				
	C	Nozzle diameter	05 mm	Provided	MR				
7	Automatic Fire Detection and Alarming System:								
	A	Type of detectors	N/A	N/A	N/A				
	В	Location of main panel	N/A	N/A	N/A				
	C	Location of repeater panel	N/A	N/A	N/A				
	D	Alternate source of power	N/A	N/A	N/A				
	E	Hooters	N/A	N/A	N/A				
8	M	OEFA:	N/A	N/A	N/A				
9	Pu	blic Address System:	N/A	N/A	N/A				
10	Automatic Sprinkler System:								
a (20)	A	Basement	N/A	N/A	N/A				
	В	Upper floor	N/A	N/A	N/A				
	C	Sprinkler above false ceiling	N/A	N/A	N/A				
11		ternal Hydrants:	1 - 1 - 1	EMMAN'					
11	A	Size of riser/down-comer	N/A	N/A	N/A				
	B	Number of hydrants per floor	N/A	N/A	N/A				
	C	Hose box	N/A	N/A	N/A				
12		rd Hydrants:	- 200						
	A	Total number of hydrants	N/A	N/A	N/A				
	B	Hose box	N/A	N/A	N/A				
13		ATTORNOOT OF THE PROPERTY OF A TOP OF	1,771	1,171	- 1				
3		Pumping Arrangements:							
	A	Discharge of main pump	N/A	N/A	N/A				
- 1	B	Head of main pump	N/A	N/A	N/A				
	1000000	2	N/A	N/A	N/A				
	C	Number of main pumps	N/A	N/A	N/A				
	D	Jockey pump out put	N/A	N/A	N/A				
	E F	Jockey pump head Standby pump out put	N/A N/A	N/A N/A	N/A				
			N/A	N/A	N/A				
1	G H	Standby pump head Auto starting /manual stopping	N/A N/A	N/A N/A	N/A				
-		.5			N/A				
2	I Pump house access N/A N/A N Terrace Level								
-	A	Discharge of pump each block	450 LPM (	02 nos. X 450 LPM	MR				
			The state of the s	The second secon	MR				
-	B	Head of the pump	40 M	40 M Provided	MR				
-	-	Power supply	Required	Provided	MR				
	D	Auto starting of pump	Required	riovided	IVIR				

Sarvodaya Kanya Vidyalaya No-1, Veer Udham Singh, Mandawali, Delhi-110092

14		Captive Water Storage for Fire Fighting:						
-	A,	Underground tank capacity	N/A	N/A	N/A			
	B	Draw-off connection	N/A	N/A	N/A			
	C	Fire service inlet	N/A	N/A	N/A			
	D	Access to tank	N/A	N/A	N/A			
	E	Overhead tank capacity	10,000 liters	10,000 liters	MR			
15	Exit Signage:		Required	Provided 1	MR			
16	Provision of Lifts:							
	A	Pressurization of lift shaft	N/A	N/A	N/A			
ŀ	В	Pressurization of lift lobby	N/A	N/A	N/A			
	C	Communication in lift car	N/A	N/A	N/A			
	D	Firemen's grounding switch	N/A	N/A	N/A			
	E	Lift signage	N/A	N/A	N/A			
17	Sta	indby Power Supply:	N/A	N/A	N/A			
18	Refuge Area:							
	A	Total area	N/A	N/A	N/A			
1	В	Location	N/A	N/A	N/A			
19	Fire Control Room:							
	A	Detector system panel	N/A	N/A	N/A			
	В	Flow switch panel	N/A	N/A	N/A			
	C	PA system panel	N/A	N/A	N/A			
	D	Battery backup	·N/A	N/A	N/A			
Ī	E	Building floor plans	N/A	N/A	N/A			
20	Special Fire Protection systems for protection of special Risks, if any:		N/A	N/A	N/A			

The fire protection system provided in the school building were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/School/NDZ/2021/1098 dated 31/12/2021, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended.

No file is pending with me before disposal of this case.

Signature of the Inspecting Officer Name Yashwant Singh Meena Designation ADO/Laxmi Nagar

D.O/EAST

At 100000 225

by 000 (NAZ) on leave

CFO

Dinector M

April D. T. T