## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2025/75

Dated :-. 11./92/2025

## FIRE SAFETY CERTIFICATE

Issued ..!! 0.2 2.25.at New Delhi by.

Delki Fire Service

## Copy to:-

- 1. The Commissioner, MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above.
- The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID No 2025012701066 dated 27.01.2025.
- 3. The Manager, "Sawera International" Guest House at 7875, Arakashan Road, Pahar Ganj, New Delhi.

## Condition for the validity of fire safety certificate

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
   This FSC is valid for guest house first to third floor only
- Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- The trained fire fighting staff should be available round the clock.
- The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- The means of escape such as staircase, exits, corridor, etc shall be kept unobstructed / unlocked for unhindered
  evacuation in case of an emergency.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 9. Any flammable material for interior decoration is prohibited.

INSPECTION REPORT 1. Name & address of the building:-

"Sawera International" Guest House at 2. Type of occupancy:-7875, Arakashan Road, Pahar Ganj, New Delhi

Residential, Sub Division-A-1 Gr. + 04 Upper floors Total -21 guest rooms Ground floor (03 guest rooms + reception + office), 1st floor to 3rd floor (06 guest rooms at each floor),

4th floor (05 rooms ) and

not in use as per affidavit dated16.12.2019

Renewal

4. Details of previous FSC:-No.F6/DFS/MS/EH/NDZ/2022/78 dated

03/02/2022

5. Fire safety directives No.-

N/A 6. Date of inspection:-03/02/2025

7. Name of the inspecting officer:-Sh. Suman Kumar (ADO)

8. Name & designation of officer

From the building side:-Mr. Sarabjeet Singh

9. Year of construction:-

3. Type of case:-

CM	120			Old Case		
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement Existing fire safety arrangements	Provided at site	Remarks MR/NMR		
1.	Access to Building					
	1) Road width	N/A	03 mtr.	N/A		
	2) Gate width	N/A	N/A	N/A		
	3)Width of internal road	N/A	N/A	N/A		
2.	Number, Width Type & Arrangement of Exits					
	A. Number of staircases					
	1. Upper floors	01 No.	01 No.	MR		
	2. Basements	N/A	N/A	N/A		
	B. Width of staircase	ul.				
	1. Upper floors	0.80 mtr.	1.25 mtr.	MR		
	2. Basements	N/A	N/A	N/A		
	C. Protection of exits					
	1. Fire check door	N/A	N/A	N/A		
	2. Pressurization	N/A	N/A	N/A		
	D. No. of continuous staircase to terrace	01	01	MR		
	E. Width of corridor	N/A	N/A	N/A		
	F. Door size	1 mtr.	1 mtr.	MR		
3.	Compartmentation					
	1) Fire check door	N/A	N/A	N/A		
	2) Sealing of electrical shafts	N/A	N/A	N/A		
	3) Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System					
	1) Basements	N/A	N/A	N/A		
	2) Upper floors	Required	provided	MR		
5.	Fire Extinguishers					
	1) Total numbers	14 Nos.	14 Nos.	MR		
	2) Types	ABC & CO2	ABC & CO2	MR		
	3) ISI marking	Required	Provided	MR		

6.	First-Aid Hose Reel						
	1) Total number of eachfloo	or 01	01	M			
	2) Length of hose reel hose	30 mtr.	30 mtr.	M			
	3) Nozzle diameter	05 mm	05 mm	M			
7.	Automatic Fire Detection & Alarming System						
	1) Type of detectors CO Required Provided M						
	Туре	required	1101100				
K i	2) Location of main panel	Gr. floor	Provided	M			
	3) Location of repeater panel		N/A	N/A			
	4) Alternate source of power		Provided	MF			
	5) Hooter's Location	Ground floo		MR			
8.	MOEFA	N/A					
9.	Public Address System	Required	N/A	N/A			
10.	Automatic Sprinkler System		Provided	MR			
	1) Basement	N/A	NI/A				
	2) Upper floors		N/A	N/A			
	3) Sprinkler above false	N/A	N/A	N/A			
	ceiling	N/A	N/A	N/A			
11.	Internal Hydrants						
***	1) Size of riser/down-comer	LNIA	77/4				
	2) Number of hydrants per	N/A	N/A	N/A			
	floor	N/A	N/A	N/A			
	3) Hose box	N/A	77/4				
12.	Yard Hydrants	IN/A	N/A	N/A			
	1) Total number of hydrants	N/A	131/4				
	2) Hose box	N/A	N/A	N/A			
13.	Pumping Arrangement	IVA	N/A	N/A			
	1) Ground level	N/A	27/4				
	a) Discharge of main	N/A	N/A	N/A			
	pump	IVA	N/A	N/A			
	b) Head of main pump	N/A	N/A				
	c) Number of main	N/A	N/A	N/A			
	pump		IVA	N/A			
	d) Jockey pump out put	N/A	N/A	NIA			
	e) Jockey pump head	N/A	N/A	N/A N/A			
	f) Stand by pump output	N/A	N/A	N/A			
	g) Stand by pump head	N/A	N/A	N/A			
	h) Auto starting/Manual	N/A	N/A	N/A			
	stopping 2) Terrace level		- new market	1 TA			
	a) Discharge of pump     b) Head of pump	450 LPM	450 LPM	MR			
	c) Power supply	30 mtr.	30 mtr.	MR			
	d) Auto starting of pump	Required	Provided	MR			
	, same starting of pump	Required	Provided	MR			
4.	Captive Water Storage for Fir	e Fightine					
	1) Older ground tank N/A N/A						
	capacity	- 77.1	N/A	N/A			
	a) Draw-off connection	N/A	V/A				
	b) Fire service inlet	377	V/A	N/A N/A			

	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	1		
	a) Pressurization of lift	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System Risk, if any:	NA		

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/EH/NDZ/2022/78 dated 03/02/2022, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended up to third floor only.

Signature of the Inspecting Officer

Name: - Suman Kumar Designation: - ADO