




No. F6/DFS/MS/2025/School/ 1091

Dated: 02/09/2025

FIRE SAFETY CERTIFICATE

Certified that S.D. Memorial Public School located at 11/22, Kamal Vihar, Kamalpur Mazra, Burari, Delhi-110084 comprised of Ground & first floor only owned/ occupied by S.D. Memorial Public School was issued Fire Safety Certificated by this department vide letter no. F6/DFS/MS/2022/School/929 dated 31/08/2022. The premises was inspected by the officer concerned of this department on 22/08/2025 in presence of Mr. Vikrant Tyagi (Attendant) and observed that all the fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education vide letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy class "Group B Educational (School) for ground & first floor only" with effect from02/09/2025 for a period of three years, subject to compliance of the conditions mentioned below:

Issued on ...02/09/2025... at New Delhi.


29/9/2025
Virendra Singh
Chief Fire Officer
Delhi Fire Service


Copy to: -

1. The Deputy Director of Education, GNCT of Delhi, Zone-VII, District North Lucknow Road, Timarpur, Delhi – 110054.
2. The Manager, S.D. Memorial Public School located at 11/22, Kamal Vihar, Kamalpur Mazra, Burari, Delhi-110084.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
4. All the staff members must know the correct method of operation of firefighting system.
5. The owner / occupier shall submit a declaration **every year** in **Form "K"** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <http://delhi.gov.in/wps/wcm/connect/doit/fire/FIRE/Home/Forms>.
6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in **Form 'J'** [sub rule (1) of rule 37] along with a copy of this Certificate, **six months** prior to its expiry".
8. The Fire Safety Certificate is valid only for ground & first floor. In case of any violation, this FSC will be treated as null & void.

INSPECTION REPORT

- | | |
|--|--|
| 1. Name & address of the building | : S.D. Memorial Public School at Kh. No.11/22, Kamal Vihar, Kamalpur Mazra Burari, Delhi-110084. |
| 2. Type of Occupancy | : Educational |
| 3. Composition of building | : Ground & First Floor only |
| 4. Type of Case | : Renewal |
| 5. Details of previous NOC | : F6/DFS/MS/2022/School/929 dated 31/08/2025 |
| 6. Fire Safety directives letter No | : Nil |
| 7. Date of inspection | : 22/08/2025 |
| 8. Name of the Inspecting Officers | : ADO (RN) |
| 9. Name and designation of officers from the building side | : Mr. Vikrant Tyagi (Attendant) |
| 10. Year of Construction | : 2007 |
| 11. Applicant's letter No. | : Online E-Mail I.D dated: 18/08/2025 |

S.No	Minimum Standards on fire prevention and fire safety U/R 33	Director. Of Education Requirements	Provided at site	Remarks MR/NMR
1	Access to building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	Accessible	Accessible	MR
		Directly Accessible	Directly Accessible	MR
		NA	NA	NA
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	02	02	MR
		NA	NA	NA
	b. Width of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	1.50m	1.50m & 1.25m	MR
		NA	NA	NA
	c. Protection of exits			
	<ul style="list-style-type: none"> • Fire check door • Pressurization 	NA	NA	NA
		NA	NA	NA
	d. No. of continuous staircases to terrace	02	02	MR
	e. Width of Corridor	NA	NA	NA
	f. Door Size	01m	1.10m	MR
	3	Compartmentation.		
<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
4 Smoke Management System.				
<ul style="list-style-type: none"> • Basements • Upper floors 	NA	NA	NA	
	Required	Natural Ventilation	MR	
5	Fire Extinguishers			
	<ul style="list-style-type: none"> • Total numbers • Types • ISI marking 	04nos	06nos	MR
		ABC/Co2	ABC-06	MR
		Yes	Yes	MR

6	First-Aid Hose Reels.			
	<ul style="list-style-type: none"> Total numbers on each floor Length of hose reel hose Nozzle diameter 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
7	Automatic fire detection and alarming system			
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
8	MOEFA	Required	Provided	MR
9	Public Address System.	NA	NA	NA
10	Automatic Sprinkler System.			
	<ul style="list-style-type: none"> Basement Upper Floor Sprinkler above false ceiling 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
11	Internal Hydrants			
	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants per floor Hose Box 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
12	Yard Hydrants.			
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	NA	NA	NA
		NA	NA	NA
13	Pumping Arrangements.			
	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping Pump House Access Terrace level <ul style="list-style-type: none"> Discharge of pump Head of the pump Power Supply Auto Starting of pump 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
14	Captive Water Storage for fire fighting.			
	<ul style="list-style-type: none"> Underground tank capacity Draw-off connection Fire service inlet Access to tank Overhead Tank capacity 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	<ul style="list-style-type: none"> Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	

17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	➤ Total Area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Batter backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is **recommended for renewal of fire safety certificate** issued vide this department letter of even no. F6/DFS/MS/2022/School/929 dated 31/08/2025.

C.L Meena
 Signature of the Inspecting Officer
 Name :- C.L Meena
 Designation:- ADO/RN

D.B. Mukharjee
 26/08/2025
 D.B. Mukharjee (DO/NW)

DCFO/1443-ANKR
 Date 26/08/25

Dy cfo (w2)

26/8

cfo / Meena
 27/8/2025

Principal Director

cfo to Issue.
28/08/25

cfo

No
 29/8

ADO (RN)

conf -- P.T.O