

C/31

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI- 110001

No. F6/DFS/MS/School/2025/SZ/ 765

Dated: 03/10/2025

To,

The Manager,
Shail Saraswati Public School,
Street No. 16, Sadh Nagar,
Palam Colony, New Delhi- 110045.

Sub: - Regarding renewal of "FSC" from fire safety point of view in r/o Shail Saraswati Public School at Street No. 16, Sadh Nagar, Palam Colony, New Delhi- 110045.


Sir,

Please refer to your online email Id delhischools3@gmail.com dated 21.08.2025, on the subject cited above. In this connection, it is to inform you that officer concerned of this department inspected the school building on dated 18.09.2025 to verify the fire safety arrangements in accordance with the rules. At the time of inspection Mr. Brijesh Kumar (Manager) of the school was present and it was observed that the previously, this department issued FSC vide letter No. F.6/DFS/MS/School/2022/738 dated 06.07.2022 for ground plus one upper floor only but now school running at ground plus two upper floors, and have following shortcomings:-

1. One of the staircases having width of 0.86 (GF to 2nd floor) & 0.76 m (GF to 1st floor) found provided against requirement of 02 staircases with width of 1.50 m each.
2. Hose reels found provided found not provided.
3. Terrace fire pump of 450 LPM found not provided.
4. Overhead water storage tank of 10,000 ltrs. found not provided.
5. Exit signage's are not provided.

In view of the above, renewal of 'Fire Safety Certificate' cannot be granted at this stage. You are requested to rectify the above-mentioned shortcomings under intimation to this department for taking further necessary action in this matter and running school in absence of requisite fire safety arrangements shall be at the risk & liability of the school management.

Yours faithfully


(Virendra Singh)
Chief Fire Officer

Copy to:-

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.