

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No. F6/DFS/MS/GH/NDZ/2025/ 323

Dated: 09/05 /2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Shan Guest House situated at 753, Old Motor Market, Jama Masjid, Delhi - 110006, comprised of Ground + 04 upper floors: Ground floor - (commercial use), 1st floor - (05 guest rooms + office + reception), 2nd floor - (06 guest rooms), 3rd floor - (06 guest rooms) & 4th floor- (not in use). FSC was granted by this department vide letter no. F6/DFS/MS/GH/NDZ/2021/60 dated 02.02.2021 for total 17 guest rooms upto 3rd floor only. The building/premises was re-inspected by officer concerned of this department on 01.05.2024 in presence of Mohd. Raisuddin (Owner) and found that the building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. The owner has submitted an affidavit on 19.11.2019 stating not to use any floor above third floor for any purpose. Accordingly, the premises is fit for occupancy of (Group-A-1) "Residential", 1st floor - (05 guest rooms), 2nd floor - (06 guest rooms) & 3rd floor - (06 guest period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to conditions under rule 38 of Delhi Fire service Rules, 2010 subject to condition printed below.

Issued on 09 05 2025 at New Delhi by

Delhi Fire Service

Tel: 011-23414000

Copy to:-

- 1. The Commissioner, MCD, Delhi:- with a request to kindly ensure the occupancy as detailed above & deviation, if any.
- 2. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi. w.r.to ID No. 2025041206303 dated 12.04.2025.
- 3. The Licensee, M/s Shan Guest House at 753, Old Motor Market, Jama Masjid, Delhi 110006. Conditions for the validity of fire safety certificate
- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction,
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 8. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto
- 9. The occupancy of above 3rd floor not allowed as per clause 7.31 in UBBL-2016.

1-1	NT.		CTION REPORT					
		me & address of the building	M/s Shan Guest House at 753, Old Motor Market, Jama Masjid, Delhi - 110006.					
2	Building is comprised of (Ground + 04 upper floors)							
			Ground floor – (commercial use)					
			1 st floor – (05 guest rooms + office + reception					
	10		2 nd floor – (06 guest rooms) 3 rd floor – (06 guest rooms) 4 th floor- (not in use as per affidavit dated 19.11.2019)					
3	Ty	Type of occupancy Residential Group A-1						
4		pe of case	Renewal .					
5		tails of previous FSC	F6/DFS/MS/GH/NDZ/2021/60 dated 02.02.2021					
6		e safety direction letter no.						
7	_		Nil					
	Date of inspection 01.05.2025							
8	_	me of the inspecting officers	ADO (MN)					
9		me of the designation of	Mohd. Raisuddin (Owner)					
10		icer from the building side		,				
10		ar of construction	Old					
11	Ap	plicant's letter no.	MCD Online application ID No. 202504120630 dated 12.04.2025					
S.No	Mi	nimum Standards on fire	Requirement/	Provided at Site	Remarks			
		evention and fire safety	Existing fire		MR/			
	rec	uirements U/R 33	safety		NMR			
			arrangements					
1		cess To Building:						
	7,0785	ad width	NA	06 m (approx)	NA			
	-	te width	NA	NA	NA			
	0.000	dth of internal road	NA	NA	NA			
2	Nu	mber, Width, Type and Arra	ngement of Exits:					
	A	Number of staircases						
		a Upper floor	01 no.	01 no.	MR			
-		b Basement	NA	NA	NA			
	В	Width of staircases	, 16					
va i		a Upper floor	80 cms.	Provided	MR			
		b Basement	NA	NA	NA			
	C	Protection of exits		14	055945			
		a Fire check door	NA	NA	NA			
	_	b Pressurization	NA	NA	NA			
	D	No. of continuous	NA	NA	NA			
	177	staircases to terrace	NIA	NIA	NIA			
	E	Width of corridor	NA	NA .	NA			
	F	Door size	1.0 mtr.	1.0 mtr.	MR			
3	1.0	mpartmentation:			1-2020			
	A	Fire check door	NA	NA	NA			
	В	Sealing of electrical shafts	NA	NA	NA			
	C	Fire rating of shaft door	NA	NA	NA			
	D	Water curtain	NA	NA	NA			
	E	Fire dampers	NA	NA	NA			
1	Sm	oke Management System:						
	A	Upper floors	12 ACPH	Provided	MR			
	_	opposition.		THE STATE OF THE S				

5.	Fire Ex	tinguisher:					
	A	Total numbers	06 nos.	08 nos.	M		
	В	Types		Provided	M		
	C		CO ₂ & ABC	Provided	M		
_		ISI marking	Required	Provided			
6	OF THE STATE	id-Hose Reels:		T01	M		
	, A	Total numbers of each	01 no.	01 no.	141		
	В	floor Length of hose reel hose	30 m	30 m	MI		
	C	Nozzle diameter	05 mm	05 mm	M		
_	1999	president and the state of the		03			
7	Automatic Fire Detection And Alarming System: A Type of detectors (CO Required Provided MF						
	. A	Type of detectors (CO	Required	Tiovided	1,722		
	В	type) Location of main panel	Required	Provided at	M		
		Docation of main paner		reception			
	С	Location of repeater	NA	NA	NA		
		panel		D :1-1	M		
	D	Alternate source of power	Required	Provided Provided	MI		
0	E	Hooters	Required NA	NA	NA		
8	MOEF		Required	Provided	M		
9		Address System:	Required	Tioriaca			
10		natic Sprinkler System:	NA	NA	NA		
	A	Basement	NA NA	NA NA	N/		
	В	Upper floor	Se November	NA NA	N/		
	C	Sprinkler above false	NA	NA	147		
11	Internal Hydrants:						
-	A	size of riser/down-comer	NA	NA	NA		
	B	Number of hydrants per	NA	NA	N/		
		floor			N/		
	C Hose box NA NA						
12	Yard Hydrants:						
	A	Total number of hydrants	NA	NA	NA		
	В	Hose box	NA	NA	N/		
13	Pumpi	ng Arrangements:		314			
	A Ground level						
	a) .	Discharge of main pump	NA	NA	N.		
	b)	Head of main pump	NA	NA	N/		
	c)	Number of main pumps	NA	NA	N.		
	d)	Jockey pump out put	NA	NA	N.		
	e)	Jockey pump head	NA	NA	N.		
	f)	Standby pump out put	NA	NA	N.		
	g)	Standby pump head	NA	NA	.N.		
	h)	Auto starting /manual	NA	NA	N.		
100	i)	Stopping Pump house access	NA	-			
	<u>B</u>	Pump house access Terrace level	NA	NA	N		
	a)		Discharge of numer 2005 x Dr. 6				
	b)	Head of the pump	225 LPM 40 m	225 LPM	M		
	c)	Power supply		40 m	M		
	d)	Auto starting of pump	Required	Provided	M		
	-/	rate starting or pump	Required	Provided	M		

4 C	Captive Water Storage For Fire Fighting:			NA	NA	
A		Underground tank capacity	NA	NA	NA	
E	3	Draw-off connection	NA	NA	NA	
	3	Fire service inlet	NA	NA	NA	
I)	Access to tank	NA 0.500 ltm	2,500 ltrs.	MR	
I	E	Overhead tank capacity	2,500 ltrs. Required	Provided	MR	
15 I	Exi	t Signage:	1.0			
	Provision of Lifts:			NA	NA	
_	A	Pressurization of lift shaft	NA	NA NA	NA	
_	В	Pressurization of lift lobby	NA	NA NA	NA	
	C	Communication in lift car	NA	NA NA	NA	
-	D	Firemen's grounding switch	NA		NA	
	E	Lift signage	NA	NA Provided	MR	
17	C+o	ndby Power Supply:	Required	Provided	2.44	
577	NA					
-	Refuge Area:		NA	NA	NA NA	
-	A	Total area	NA	NA	IVA	
	B Location					
19	Fire Control Room:		NA	NA	NA NA	
	A	Detector system panel	NA	NA	NA NA	
	B		NA	NA	NA NA	
	C	Pa system panel	NA	NA	75, 750775	
	D	Battery backup	NA	NA	NA NA	
	E Building floor plans NA		NA	INA		
20	Special Fire Protection Systems For Protection of Special Risks, If Any:				ad at rano	

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

Shortcomings communicated vide letter No.F6/DFS/MS/GH/NDZ/2024/196 dated

Keeping in view of the deemed compliance of minimum standards of fire prevention and 06/05/2024 has been rectified. fire safety measures as required under the Rules, the FSC issued vide letter No F6/DFS/MS/GH/NDZ/2021/60 dated 02.02.2021 is recommended to be renewed upto 3rd floor only, under Rule 35 of the Delhi Fire Service Rules 2010.

> Signature of the Inspecting Officer Name: - Sarabjeet Singh ADO (MN) Designation