



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

7/8 C-28
आज़ादी का
अमृत महोत्सव

No. F6/DFS/MS/School/2025/NDZ/ 650

Dated: 18/08/2025

To,

The Principal,
Shankar Public School,
Main Road Mandawali,
Delhi-110092.

Subject: - Regarding issuance of Fire Safety Certificate in r/o Shankar Public School, Main Road Mandawali, Delhi-110092.

Sir,

Please refer to your outdoor dairy No.3797 dated 16/07/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 24/07/2025 in the presence of Mrs. Rakhee Rawat (Head Mistress) and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/School/NDZ/2025/577 dated 04/07/2025 (copy overleaf).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Enclosed: as above

Virendra Singh
14/8/2025

(VIRENDRA SINGH)
CHIEF FIRE OFFICER
DELHI FIRE SERVICE

ok
(u)

Copy to: -

1. The Director of Education, MCD Civic Centre, Jawahar Lal Nehru Marg, New Delhi-110002.



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आपकी सेवा
आपकी मदद

Dated: 04/07/2025

No. F6/DFS/MS/School/NDZ/2025/577

To,

The Principal,
Shankar Public School,
Main Road, Mandawali,
Delhi - 110092.

Subject: - Regarding grant of Fire Safety Certificate in r/o Shankar Public School located at Main Road, Mandawali, Delhi - 110092.

Sir,

This has a reference to your Outdoor Diary No. 2581 dated 10/06/2025, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 24/06/2025 in the presence of Mrs. Rakhee Rawat (Head Mistress) and observed that building comprised of ground plus three upper floors.

Following shortcomings were observed during time of inspection:

1. First-Aid-Hose Reel provided but not functional.
2. Terrace level fire pump of capacity 450 LPM found removed.
3. Overhead tank of capacity 10,000 liters not provided.
4. Exit & floors Signage's not provided at strategic location in the building.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Director of Education, East Delhi Municipal Corporation, 419, Udyog Sadan, Patparganj Industrial Area, Delhi - 110092.