



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001



C-36

No. F6/DFS/MS/Hospital/2025/NDZ/395

Dated: 31/07/2025

FIRE SAFETY CERTIFICATE

Certified that the Shanti Mukand Hospital located at 2, Institutional Area, Vikas Marg Extn., Delhi 110092, building comprised of two Basement, Ground Floor and Four Upper Floors only owned/occupied by M/s Shri Mukandilal Memorial Foundation for Heart & Medical Care was earlier issued FSC vide letter No. F6/DFS/MS/Hospital/ 2022/NDZ/357 dated 2208/2022. The premises was re-inspected by the officers concerned of this department on 09/07/2025 in the presence of Mr. Annant (Eng. Department) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with rule 33 of Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class "C" 'Institutional Building' with effect from 31/07/2025 for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 31/07/2025 at New Delhi by

(Virendra Singh)
Chief Fire Officer

Copy to,

1. The Medical Supdt. Shanti Mukand Hospital, 2, Institutional Area, Vikas Marg Extn., Delhi 110092
2. The Directorate of Health Services, M.O. I/C Nursing Home Cell, Govt. of NCT of Delhi, F-17, Karkardooma, Delhi-110032

Conditions for the validity of Fire Safety Certificate

1. One single room constructed on the terrace should not be used for any purpose.
2. All the fire safety arrangement provided there in shall be maintained in good working conditions at all times.
3. Loss of life or property due to non-functional fire safety measure shall be at the responsibility of the management.
4. The trained fire-fighter staff should be available round the clock.
5. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
6. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.
8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
9. Basement shall be used strictly as per building Bye-Laws.

INSPECTION REPORT

1. Name & address of the building: Shanti Mukand Hospital, 2, Institutional Area, Vikas Marg Extension, Delhi-110092.
2. Building is comprised of : Two Basements, Ground + 4 Upper Floors & other block Basement, Ground +3 upper floors connected at all floors except basement.
3. Type of Occupancy : Institutional (Hospital Building)
4. Type of Case : Renewal
5. Details of previous NOC : F6/DFS/MS/Hospital/2022/NDZ/357 Dated 22/08/2022
6. Fire Safety directives Letter No. : NBC (Part-IV)
7. Date of inspection : 09/07/2025
8. Name of the Inspecting Officer : Deepak Kumar, A.D.O.(Shd) & A.K. Jaiswal, D.O.(ED)
9. Name and designation of Officer from the building side : Mr. Annant (Eng. Department)
10. Year of Construction : 1994-2004
11. Applicant's letter No. : SMH/Admin/2025/8859 dated 07/07/2025

S No	Minimum standards on fire prevention and fire safety U/R 33	BBL Requirements	Provided at site	Remarks MR/N
1.	Access of building			
	• Road width	12 mtr	30 mtr	MR
	• Gate width	4.5 mtr	4.5 mtr	MR
	• Width of internal road	06 mtr	06 mtr	MR
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases			
	• Upper floors	2	2	MR
	• Basements	2	2	MR
	b. Width of staircases			
	• Upper floors	2 mtr	1.20mtr & 1.80 mtr	MR (Old accepted)
	• Basements	1.25 mtr	1.20mtr & 1.50 mtr	MR (Old accepted)
	c. Protection of exits			
	• Fire check door	Required	Provided	MR
	• Pressurization	Required	Provided	MR
	d. No of continuous staircase to terrace	2	2	MR
	e. Width Of Corridor	1.50 mtr	02 mtr	MR
	f. Door Size	1 mtr	1 mtr, 2 mtr	MR
3.	Compartmentation			
	• Fire check door	Required	Provided	MR
	• Sealing of electrical shafts	Required	Provided	MR
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4.	Smoke managements System			
	• Basements	Required	Provided	MR
	• Upper floors	Required	Provided	MR
5.	Fire Extinguishers			
	• Total numbers	25 nos	35 nos	MR
	• Types	ABC/CO ₂	ABC/CO ₂	MR
	• IS marking	ISI Marked	ISI Marked	MR

2 A

6.	First – Aid Hose Reels			
	• Total numbers on each floor	02 NOS	02 NOS	MR
	• Length of hose reel hose	30 mtr.	30 mtr.	MR
	• Nozzle diameter	5mm.	5mm.	MR
7.	Automatic fire detection and alarming system			
	• Type of detector	Smoke/Heat	Provided	MR
	• Location of Main Panel	Required	Provided	MR
	• Location of Repeater Panel	Required	Provided	MR
	• Alternate source of power	NA	NA	NA
	• Hooters' Location	NA	NA	NA
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	• Basements	Required	Provided	MR
	• Upper Floor	NA	NA	NA
	• Sprinkler above false ceiling	NA	NA	NA
11.	Internal Hydrants			
	• Size of riser/down- comer	100 mm	100 mm ✓	MR
	• Number of hydrants per floor	01 nos	01 nos ✓	MR
	• Hose Box	01 nos	01 nos ✓	MR
12.	Yard Hydrants			
	• Total number of hydrants	NA	08 nos ✓	MR
	• Hose Box	NA	08 nos	MR
13.	Pumping Arrangements			
	• Ground Level			
	• Discharge of main pump	1620 Lpm	1620 Lpm ✓	MR
	➤ Head of main pump	70 mtr	70 mtr ✓	MR
	➤ Number of main pumps	01 no	01 no. ✓	MR
	➤ Jockey pump out put	180 Lpm	180 Lpm ✓	MR
	➤ Jockey pump head	70 mtr	70 mtr	MR
	➤ Standby Pump out put	NA	NA	NA
	➤ Standby Pump Head	NA	NA	NA
	➤ Auto Staring/Manual stopping	NA	NA	NA
	➤ Pump House Access	Required	Provided	MR
	• Terrace level			
	➤ Discharge of pump	N/A	N/A	N/A
	➤ Head of the pump	N/A	N/A	N/A
	➤ Power supply	Required	Provided	MR
	➤ Auto starting of pump	Required	Provided	MR
14.	Captive water Storage for fire fighting			
	• Underground tank capacity	50,000 ltr	50,000 ltr /	MR
	➤ Draw of connection	Required	Provided	MR
	➤ Fire service inlet	Required	Provided	MR
	➤ Access to tank	Required	Provided	MR
	• Overhead Tank capacity	N/A	N/A	N/A

41/52

15	Exit Signage	Required	Provided	MR
16.	Provision of Lifts			
	➤ Pressurization of Lift Shaft	Required	Provided	MR
	➤ Pressurization of lift lobby	NA	NA	NA
	➤ Communication in lift Car	Required	Provided	MR
	➤ Fireman's Grounding Switch	Required	Provided	MR
	➤ Lift Signage	Required	Provided	MR
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area			
	➤ Total area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19.	Fire control room			
	➤ Detector system panel	N/A	N/A	N/A
	➤ Flow Switch Panel	N/A	N/A	N/A
	➤ PA System Panel	N/A	N/A	N/A
	➤ Battery backup	N/A	N/A	N/A
	➤ Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. One room constructed on the terrace floor, management has given an undertaking that this room shall not be used for any hospital purposes.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter No. F6/DFS/MS/Hospital/2022/NDZ/357 Dated 22/08/2022 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Deepak
10/07/2025
Signature of the Inspecting Officer
Name : Deepak Kumar
Designation : A.D.O.(Shahdara)

A.K. Jaiswal
10/07/2025
Signature of the Inspecting Officer
Name : A.K. Jaiswal
Designation : D.O. (East Division)

Dy C.F.O. (G.D.2)
11/07/25

C.F.O.
11/07/2025

Director
12/07/25
Aqul