

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/School/2025 / 969

Dated: 08/08/2025

FIRE SAFETY CERTIFICATE

Certified that the Shanti Vidya Mandir located at D-1, Rajeev Nagar, Bhalaswa Dairy Colony, Delhi-110042 comprised of 02 Blocks Ground & Ground + 02 upper floors only owned/ occupied by Shanti Vidya Mandir was issued Fire Safety Certificated by this department vide letter no. No.F6/DFS/MS/2018/School/WZ/2303 dated 12.10.2018. The premises was inspected by the officer concerned of this department on 16/07/2025 in presence of Smt. Soma Devi (Principal) and observed that all the fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education vide letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy class "Group B Educational (School)" with effect from08.08.2825 for a period of three years, subject to compliance of the conditions mentioned below:

Issued on ... 08 08 2025 at New Delhi by.

Virendra Singh Chief Fire Officer Delhi Fire Service QC4

Copy to: -

- 1. The Deputy Director of Education, GNCT of Delhi, Zone-VII, District North Lucknow Road, Timarpur, Delhi – 110054.
- 2. The Principal, Shanti Vidya Mandir located at D-1, Rajeev Nagar, Bhalaswa Dairy Colony, Delhi-110042

Conditions for the validity of Fire Safety Certificate:

All the means of escape/entry/exit shall be kept free from any obstruction.

All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

All the staff members must know the correct method of operation of firefighting system.

The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-

2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

Name & address of the building

: Shanti Vidya Mandir, D-1, Rajeev Nagar, Bhalaswa Dairy Colony, Delhi-42.

2. Type of Occupancy

: Educational

3. Composition of building

: Ground & 02 upper Floor only

4. Type of Case

: Renewal

5. Details of previous NOC

: F6/DFS/MS/2018/School/WZ/2303 dated 12.10.2018

6. Fire Safety directives letter No

: Nil

Date of inspection

: 16/07/2025

8. Name of the Inspecting Officers

: ADO (RN)

9. Name and designation of officers

. .

from the building side

: Smt. Soma Devi (Principal)

10. Year of Construction

: 2006

11. Applicant's letter No.

: Online E-Mail Dated 8/07/2025

	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per Inspection dated 10.02.2017	Provided at site	Remarks MR/NMR				
	Access to building							
	Road width	06	06m	MR				
	Gate width	Directly Accessible	Directly Accessible	MR				
	• Width of internal road	NA	NA	NA				
	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases		8					
	• Upper Floors	02	02	MR				
	Basements	NA ·	NA	NA				
	b. Width of staircases							
	Upper Floors	1.50m	1.50m & 1.80m	MR				
	Basements	NA	NA	NA				
	c. Protection of exits							
(8)	Fire check door	NA	NA	NA				
	Pressurization	NA	NA	NA				
	d. No. of continuous staircases to terrace	01	01	MR				
	e. Width of Corridor	NA	NA	NA				
	f. Door Size	01m	01m	MR				
3	Compartmentation.							
	Fire check door	NA	NA	NA				
	Sealing of electrical shafts	NA	NA	NA				
	Fire Rating of shaft door	NA	NA	NA				
	Water Curtain	NA	NA	NA				
	Fire Dampers	NA	NA	NA				
4	Smoke Management System.							
	Basements	NA	NA	NA				
	Upper floors	NA	NA	NA				
5	Fire Extinguishers							
	Total numbers	07nos	Provided	MR				
	• Types	ABC/Co2	Provided	MR				
	ISI marking	ISI Marked	Provided					

5	First-Aid Hose Reels.				
	Total numbers on each floor	01	01		
	 Length of hose reel hose 	30m	30m	MR	
	Nozzle diameter			M	
7	Automatic fire detection and alarming system.	5mm	5mm	M	
	Type of detectors	NA	N11	ļ	
	Location of Main Panel	NA NA	NA NA	N/	
	Location of Repeater Panel		NA	N/	
	Alternate source of power	NA	NA	N/	
	Hooters' Location	NA	NA	N/	
8	MOEFA	NA	NA	NA NA	
9	Public Address System.	NA	NA	NA NA	
10	Automatic Sprinkler System.	NA	NA	NA	
	Basement				
	Upper Floor	NA	NA	NA	
	Sprinkler above false ceiling	NA	NA	NA	
11	Internal Hydrants	NA	NA	NA	
	 Size of riser/down-comer Number of hydrants per floor 	NA	NA	NA	
	Hose Box	NA	NA	NA	
12	Yard Hydrants.	NA	NA	NA	
	Total number of hydrants	20			
	Hose Box	NA	NA	NA	
The state of the s		NA	NA	NA	
13	Pumping Arrangements.				
	Ground Level				
	Discharge of main Pump	N/A	N/A	N/A	
	➤ Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A		
	 Jockey Pump out put Jockey pump head 	N/A		N/A	
	Jockey pump headStandby Pump out put	N/A	N/A N/A	N/A	
	Standby Pump Head	N/A		N/A	
	➤ Auto Starting/ Manual stopping	N/A	N/A N/A	N/A	
	➤ Pump House Access	N/A	N/A	N/A	
	Terrace level	IVA	N/A	N/A	
	Discharge of pump	450 LPM	Provided	MR	
	➤ Head of the pump	40m	Provided	MR	
	➤ Power Supply	Required	Provided	MR	
	➤ Auto Starting of pump	Required	Provided	MR	
14	Captive Water Storage for fire fighting.				
	Underground tank capacity	NA NA	NA	_ NA	
	> Draw-off connection	NA	NA	NA	
	➤ Fire service inlet	NA	NA	NA	
	> Access to tank	NA	, NA	NA	
		1		MR	



15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
17	Standby power supply	N/A	N/A	N/A		
18	Refuge Area.					
	N. Washington	N/A	N/A	N/A		
	➤ Total Area ➤ Location	N/A	N/A	N/A		
19	Fire Control Room					
	Date Contain Panel	N/A	N/A			
	Detector System Panel Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. F6/DFS/MS/2025/School/04 dated 02/01/2025.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. F6/DFS/MS/2018/School/WZ/2303 dated 12.10.2018.

D.B. Mukharjee (DO/NW)

Signature of the Inspecting Officer
Name: - C.L. Meena
Designation: - ADO/RN

DCFOlesand de La La La La Constitución de la Consti

22/02/1021 22/02/1021

10 | Mugh

Rincipal Director

Cfo to Same

A00 (RW)

CAL

30/03/03

cont. P.T.O.