

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2025/343

Dated: 15.7.05/2025

FIRE SAFETY CERTIFICATE

Certified that the Shbad Dx. Guest House located at 31, Ram Nagar, Pahar Ganj, New Delhi-110055 comprised of Ground + 03 Upper floors, Basement (Hall / Storage), Ground floor (Reception +03 guest rooms), 1st floor to 3rd floor (05guest rooms at each floor), and terrace (water tank + DG set + lift room), total 18 guest rooms was earlier granted FSC by this department vide letter No. F6/DFS/MS/GH/NDZ/2022/279 dated 13/06/2022. Now, the premises was re-inspected by the officer concerned of this department on 03/05/2025 in the presence of Sh. Devender Singh (Owner) and found that the said the safety that the said guest house building having deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential, Sub Division-A-1 Ground floor (03 guest rooms), 1st floor to 3rd floor (05 guest rooms at each floor), total 18 guest rooms up to third floor only" with effect from ... 15.705.12.25... for period of three years, in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued .15 05 2025...at New Delhi by.

Director

Delhi Fire Service

Copy to:-

1. The Commissioner, MCD, Civic Centre, New Delhi: with a request to ensure the occupancy as detailed above & deviation if any.

2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no. 2025042306965 dated 23/04/2025.

3. The Owner, M/s Shbad Dx. Guest House located at 31, Ram Nagar, Pahar Ganj, New Delhi-

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an
- 8. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the MCD Portal along with a copy of this Certificate, six months prior to its expiry".
- 9. Any flammable material for interior decoration is prohibited.

2,	Type of occupancy:	SPECTION RES	1 14/14			
	ype of occupa-	ng SLI	PORT			
	Palley.					
	dear pal					
3	disement (1. Political la Guest rooms)					
4	Basement (Hall / Storage), Ground floor (Reception rooms at each floor), and terrace (water task + DG set					
7,	Details of					
	previous	THE FOOD	ooms), 1st floor to 3rd f ch floor), and terrace (v 1), total 18 guest room	water tank + DG set		
6,	Fire safety di	rtenewal	g 100III			
7	Fire safety directives No Name of the income	13/06/2022	S/MS/GH/NDZ/2022	/279 dated		
8	Name of the in	N/A	2	- v dated		
0,	Name o "Ilsheot!	03/05/2025	1			
9	Name of the inspecting officer: Name & designation of officer From the building side: Year of construction	ADO (RN)				
10	Year of construction: Applicant's lettered.					
	Applicant's letter No:-	SH. Devend	er Singh (Owner)	1		
S.No.	There No:-			1		
	Minimum Standards on fire	Online id no.	2025042306965 dat	ed 23/04/2025.		
	Prevention and c	Requirement/		Old Case		
,	Prevention and fire safety U/R 33	Existing fire	Provided at site	Remarks		
1.		safety		MR/NMR		
	Access to Building	arrangements				
	2) Gate width	N/A	06 mtr.	MR		
2	3) Width of:	N/A	N/A	N/A		
2.	Number, Width Type & Ar A. Number of staircases	N/A	N/A			
	A. Number of staircases 1. Upper floring	rangement of I	IN/A	N/A		
	1. Upper floors	Boment of I	ZXIIS			
	2. Basements	01 Nos.	01 Nos.	100		
	B. Width as	N/A		MR		
	B. Width of staircase		N/A	N/A		
	1. Upper floors 2. Basements	0.80 mtr.	1.25 mtr.	1100		
	C Protect:	0.80 mtr.	0.93 mtr.	MR		
	C. Protection of exits		0.33 Intr.	MR		
	1. Fire check door	N/A	N/A	NT/A		
	2. Pressurization	N/A	N/A	N/A		
	D. No. of continuous	N/A	N/A	N/A		
	staircase to terrace		IVA	N/A		
	E. Width of corridor	N/A	N/A	NI/A		
3.	F. Door size	1 mtr.	1 mtr.	N/A		
3.	Compartmentation	•		MR		
	1) Fire check door	N/A	N/A	27/		
1	2) Sealing of electrical shafts	N/A	N/A	N/A		
	3) Fire rating of shaft door	N/A	N/A N/A	N/A		
	4) Water curtain	N/A	N/A N/A	N/A		
	5) Fire Dampers	N/A	N/A N/A	N/A		
4.	Smoke Management System	- 11 4 1	IV/A	N/A		
	1) Basements	Required	Exhaust C	1.00		
	2) Upper floors	Required	Exhaust fan	MR		
		quitou	Natural/Exhaust fan	MR		
5.	Fire Extinguishers		1411			
		10				
	1) Total numbers	10 Nos.	12 Nos.	MR		
	2) Types	ABC & CO2	ABC & CO2	MR		
	3) ISI marking	Required	Provided	MR		
6.	First-Aid Hose Reel					
	1) Total number of eachfloor	01	01	MR		
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR		
	3) Nozzle diameter	05 mm	05 mm	MR		
7.	Automatic Fire Detection &	Alarming Syste	em			
	1) Type of detectors CO	Required	Provided	MR		
	2) Location of main panel	Gr. Floor	Provided	MR		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	Required	Provided	MR		
	5) Hooter's Location	Each floor	Provided	MR		
		Δ.		IVIIC		

Q	Mor	M/26				
8.	MOEFA	Required	Provided	MD		
9.	Public Address System	Required		IVIK		
10.	Automatic Sprinkler Syste	m	. Trovided	MR		
	1) Basement	Required	Provided			
	2) Upper floors	N/A	N/A	MR		
	3) Sprinkler above false	N/A		N/A		
	ceiling	IN/A	N/A	N/A		
11.	Internal Hydrants					
	1) Size of riser/down-comer	NIA				
	2) Number of hydrants per		N/A	N/A		
	floor	N/A	N/A	N/A		
	3) Hose box	27/4				
12.	Yard Hydrants	N/A	N/A	N/A		
	1) Total number of hydrants	77/4	1			
	2) Hose box	N/A	N/A	N/A		
13.		N/A	· N/A	N/A		
13.	Pumping Arrangement					
	Ground level Discharge of main	N/A	N/A	N/A		
	, and be of main	N/A	N/A	N/A		
	b) Head of main					
	b) Head of main pump c) Number of main pum	N/A	N/A	N/A		
			N/A	N/A		
	d) Jockey pump out put e) Jockey pump head	N/A	N/A	N/A		
	, pamp neud	N/A	N/A	N/A		
	f) Stand by pump output g) Stand by pump head		N/A	N/A		
	h) Auto starting/Manual	N/A	N/A	N/A		
	stopping	N/A	N/A	N/A		
	2) Terrace level		7			
	a) Discharge of pump	450 LPM	450 LPM	MD		
	b) Head of pump	30 mtr.	30 mtr.	MR MR		
	c) Power supply	Required	Provided	MR		
	d) Auto starting of pump	Required	Provided	MR		
14.	Captive Water Storage for I	Time Et -1 ()				
	full Storage 10r I	ire righting				
	1) II-1-					
	Under ground tank Draw-off connection	N/A	N/A	N/A		
	a) Draw-off connectionb) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	N/A Required	N/A	N/A		
	d) Over head tank	5000 ltr.	Provided 5000 16	MR		
	capacity	Jood III.	5000 ltr.	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.			IVIK		
	a) Pressurization of lift	N/A	N/A	N/A		
	shaft			11/71		
	b) Pressurization of lift	N/A	N/A	N/A		
	lobby c) Communication in	NI/A	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			
	lift car	N/A	N/A	N/A		
	d) Fireman's switch	N/A	N/A	NI/A		
	e) Lift signage	N/A	N/A N/A	N/A N/A		
17.	Stand by Power Supply	Required	Provided	MR		
18.	Refuge Area	N/A	N/A	N/A		
	Total area location	N/A	N/A	N/A		
				IVA		
19.	Fire Control Room	N/A	N/A	N/A		
	a) Detector system	N/A	N/A	N/A		
	panel	N/A	NIA			
	b) Flow switch panel	N/A N/A	N/A N/A	N/A		
	c) PA system panel	IN/A	IN/A	NI/A		

The fire protection systems provided in the building were randomly tested, checked and functional at the company issued and found functional at the time of inspection. The observations/ shortcomings issued and communicated vide this time of inspection. The observations/ shortcomings issued and communicated vide this time of inspection. communicated vide this department letter of even no. F6/DFS/MS/WZ/GH/2025/169 dated:

15/04/2025 have been complied by the management. In view of the deemed compliance of the minimum standards of fire prevention and fire neasures as received vide letter no. measures as required under the rules the FSC issued vide letter no. MS/GH/NDZ/2022/270 details 12/26/2022 F6/DFS/MS/GH/NDZ/2022/279 dated 13/06/2022, renewal under rule 37 of the Delhi Fire Service rules 2010, is recommended and the service rules 2010. rules 2010, is recommended up to third floor only.

> Signature of the Inspe Name: - C.L. Meena Designation: - ADO (RN)

Directa As approved, F.T. Letter is Put up for your signature Please.

Director