



No. F6/DFS/MS/School/NDZ/2025/ 893

Dated: 14/07/2025

FIRE SAFETY CERTIFICATE

Certified that the SNEH International School located at New Rajdhani Enclave, Vikas Marg, Delhi - 110092, earlier building comprised of Basement, Ground plus two upper floors, owned/occupied by SNEH International School is now comprised of Basement, Ground + 3 upper floors have complied with fire prevention and fire safety requirements in accordance with rule 33 of DFS Rules of this department on 02/07/2025 in presence of Shri Subhash Chander (Chairman) and that the Bldg. premises is fit for occupancy class "Educational Building" (Group - B) for Basement, Ground plus three upper floors only with effect from 14/07/2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 14/07/2025 at New Delhi by.

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to: -

1. The Dy. Director of Education, D - Block, Anand Vihar, Delhi-110092.
2. The Principal, SNEH International School located at New Rajdhani Enclave, Vikas Marg, Delhi - 110092.

Conditions for the validity of Fire Safety Certificate

1. Fire Safety Certificate is valid for Basement, Ground plus three upper floors only.
2. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
3. All the means of escape shall be kept free of all the type of obstruction all the time.
4. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
5. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
6. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
7. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

1	Name & address of the building	SNEII International School located at New Rajdhani Enclave, Vikas Marg, Delhi - 110092.		
2	Building is comprised of	Basement, ground plus three upper floors		
3	Type of occupancy	Educational Building		
4	Type of case	Addition/Alteration as 3 rd floor added on existing bldg. (Now G+3 upper floor, Earlier it was G+2 upper floors only)		
5	Details of previous FSC	F6/DFS/MS/School/ND7/2022/621 dated 10/06/2022		
6	Fire safety directives letter no.	NBC Part-IV		
7	Date of inspection	02/07/2025		
8	Name of the inspecting officers	Ashok Kumar Jaiswal, Divisional Officer / East & Yashwant Singh Meena, A.D.O / Laxmi Nagar		
9	Name of the designation of officer from the building side	Mr. Subhash Chander (Chairman)		
10	Year of construction	2004-12		
11	Applicant's letter no.	Outdoor Dairy No. 3011 dated 24/06/2025		
S. No	Minimum standard of fire prevention and fire safety U/R 33	Requirement NBC/UBBL	Provided at site	Remarks MR/NMR
1.	Access to Building:			
A	Road width	6.0 mtrs.	15 mtrs.	MR
B	Gate width	4.5 mtrs	4.5 mtrs.	MR
C	Width of internal road	N/A	N/A	N/A
2.	Number, Width, Type and Arrangement of Exits:			
A	Number of staircases			
a	Upper floor	02 nos.	02 nos.	MR
	Basement	02 nos.	02 nos.	MR
B	Width of staircases			
a	Upper floor	1.5 mtrs. each	1.70 mtrs X 2	MR
	Basement	1.5 mtrs. each	1.70 mtrs X 2	MR
C	Protection of exits			
a	Fire check door	N/A	N/A	N/A
b	Pressurization	N/A	N/A	N/A
D	No. of continuous staircases to terrace		01 no	02 nos
E	Width of corridor		1.5 mtrs	1.5 mtrs
F	Door size		1.0 mtr.	1.0 mtr.
3.	Compartmentation:			
A	Fire check door	NA	NA	NA
B	Sealing of electrical shafts	N/A	N/A	N/A
C	Fire rating of shaft door	N/A	N/A	N/A
D	Water curtain	N/A	N/A	N/A
E	Fire dampers	N/A	N/A	N/A
4.	Smoke Management System:			
A	Basement	N/A	N/A	N/A
B	Upper floor	N/A	N/A	N/A

5. Fire Extinguisher:				
A	Total numbers	16 nos.	16 nos.	MR
B	Types	CO ₂ & ABC	CO ₂ & ABC	MR
C	ISI marking	Required	Provided	MR
6 First-Aid-Hose Reel:				
A	Total numbers of each floor	02 nos.	02 nos.	MR
B	Length of hose reel hose	30 mtrs.	30 mtrs.	MR
C	Nozzle diameter	05 mm	05 mm	MR
7 Automatic Fire Detection and Alarming System:				
A	Type of detectors	N/A	N/A	N/A
B	Location of main panel	N/A	N/A	N/A
C	Location of repeater panel	N/A	N/A	N/A
D	Alternate source of power	N/A	N/A	N/A
E	Hooters	N/A	N/A	N/A
8	MOEFA:	N/A	N/A	N/A
9	Public Address System:	Required	Provided	MR
10 Automatic Sprinkler System:				
A	Basement	Required	Provided	MR
B	Upper floor	N/A	N/A	N/A
C	Sprinkler above false ceiling	N/A	N/A	N/A
11 Internal Hydrants:				
A	Size of riser/down-comer	Required	100 mm	MR
B	Number of hydrants per floor	Required	02 nos each floor	MR
C	Hose box	Required	02 nos each floor	MR
12 Yard Hydrants:				
A	Total number of hydrants	N/A	N/A	N/A
B	Hose box	N/A	N/A	N/A
13 Pumping Arrangements:				
1	Ground level			
A	Discharge of main pump	N/A	N/A	N/A
B	Head of main pump	N/A	N/A	N/A
C	Number of main pumps	N/A	N/A	N/A
D	Jockey pump out put	N/A	N/A	N/A
E	Jockey pump head	N/A	N/A	N/A
F	Standby pump out put	N/A	N/A	N/A
G	Standby pump head	N/A	N/A	N/A
H	Auto starting /manual stopping	N/A	N/A	N/A
I	Pump house access	N/A	N/A	N/A
2	Terrace Level			
A	Discharge of pump each block	02 nos of 450 LPM	01 no of 450 LPM 01 no of 950 LPM	MR
B	Head of the pump	40 mtrs.	40 mtrs.	MR
C	Power supply	Required	Provided	MR
D	Auto starting of pump	Required	Provided	MR

N/20


SNEH International School located at New Rajdhani Enclave, Vikas Marg, Delhi - 110092.

14	Captive Water Storage for Fire Fighting:			
A	Underground tank capacity	N/A	N/A	N/A
B	Draw-off connection	N/A	N/A	N/A
C	Fire service inlet	Required	Provided	MR
D	Access to tank	Required	Provided	MR
E	Overhead tank capacity	15,000 liters	30,000 liters	MR
15	Exit Signage:			
16	Provision of Lifts:			
A	Pressurization of lift shaft	N/A	N/A	N/A
B	Pressurization of lift lobby	N/A	N/A	N/A
C	Communication in lift car	N/A	N/A	N/A
D	Firemen's grounding switch	N/A	N/A	N/A
E	Lift signage	N/A	N/A	N/A
17	Standby Power Supply:			
18	Refuge Area:			
A	Total area	N/A	N/A	N/A
B	Location	N/A	N/A	N/A
19	Fire Control Room:			
A	Detector system panel	N/A	N/A	N/A
B	Flow switch panel	N/A	N/A	N/A
C	PA system panel	N/A	N/A	N/A
D	Battery backup	N/A	N/A	N/A
E	Building floor plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:			

Note: Earlier Building was comprised of Ground plus two upper floors. Now it is Ground & 3rd upper floors and Fire Safety measures have been extended up to 3rd floor as per NBC.

The fire protection system was randomly checked and tested and was found functional at the time of inspection.

Keeping In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules of FSC issued vide letter no. F6/DFS/MS/School/NDZ/2022/621 dated 10/06/2022, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended.


08/07/2025

Signature of the Inspecting Officer
Name: Yashwant Singh Meena
Designation: ADO /Laxmi Nagar


08/07/2025

Signature of the Inspecting Officer
Name : Ashok Kumar Jaiswal
Designation: Divisional Office/ East

By C.F.O (NDZ)

Dirp
09/07/25

C.F.O
10/7/2025

Director
10/7/24

AnytN

P.T.O

M/21

Sir,

F.T Letter is put up for sign. Alesy


11/7/2025

~~Director~~
11/7/21
2