

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2025/186

Dated: 04/04/2025

FIRE SAFETY CERTIFICATE

Certified that the Shipra International Guest House located at 8596, D.B. Gupta Road, Pahar Ganj, New Delhi comprised of Basement + Ground + 03 Upper floors, using Basement (hall + store), Ground floor (Reception + store + 07 guest room), 1st floor to 3rd floor (11 guest rooms + 01 sore room at each floor), total 40 guest rooms was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/NDZ/2022/342 dated 13.07.2022. Now, the premises was inspected by the officer concerned of this department on 24.03.2025 in the presence of Mr. Subodh Kumar (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (Reception + 07 guest room), 1st floor to 3rd floor (11 guest rooms at each floor), total 40 guest rooms guest rooms up to third floor only with effect from .04.2025. for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued ..04 04 202 at New Delhi by.

Copy to:-

1. The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above & deviation if any.

2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no.2025031203416 dated 13.03.2025.

3. The Manager, Shipra International Guest House, 8596, D.B. Gupta Road, Pahar Ganj, New

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the MCD Portal along with a copy of this Certificate, six months prior to its expiry".
- 9. Any flammable material for interior decoration is prohibited.

M/21 INSPECTION REPORT 1. Name & address of the building Shipra International Guest House located at 8596, D.B. Gupta Road, Pahar Ganj, New Delhi 2. Type of occupancy:-Residential, Sub Division-A-1 B+Gr. + 03Upper floors (total 40 Guest rooms) Ground floor (Reception + store + 07 guest room), 1st floor to 3rd floor (11 guest rooms + 01 sore room at each floor), Type of case:-Renewal Details of previous FSC:-No F6/DFS/MS/GH/NDZ/2022/342 dated 13.07.2022 5. Fire safety directives No.-N/A Date of inspection:-24.03.2025 7. Name of the inspecting officer:-ADO (RN) 8. Name & designation of officer From the building side:-Mr. Subodh Kr. (Manager) 9. Year of construction:-2008 10. Applicant's letter No:-Online id no.2025031203416 dated 13.03.2025 Old Case S.No. Minimum Standards on fire Requirement/ Provided at Remarks Prevention and fire safety Existing fire safety MR/NMR site arrangements U/R 33 1. Access to Building 1) Road width MR N/A 09 mtr. N/A 2) Gate width N/A N/A N/A 3)Width of internal road N/A N/A 2. Number, Width Type & Arrangement of Exits A. Number of staircases 01 Nos. MR 1. Upper floors 01 Nos. MR 02 Nos. 02 Nos. 2. Basements B. Width of staircase MR 1.25 mtr. 1.25 mtr. 1. Upper floors MR 1.25 mtr. 1.25 mtr. & 2. Basements 1.35 mtrs. C. Protection of exits Provided MR 1. Fire check door Required 2. Pressurization N/A N/A N/A 01 01 MR D. No. of continuous staircase to terrace N/A N/A N/A E. Width of corridor 1.0 mtr. 1.0 mtr. MR F. Door size Compartmentation 3. N/A N/A N/A 1) Fire check door 2) Sealing of electrical shafts N/A N/A N/A N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A 4) Water curtain N/A 5) Fire Dampers N/A N/A Smoke Management System 4. MR Required Exhaust fan 1) Basements Natural /Exhaust MR 2) Upper floors Required fan Fire Extinguishers 5. MR 15 Nos. 1) Total numbers 15 Nos. ABC & CO2 MR ABC& CO2 2) Types Provided MR 3) ISI marking Required First-Aid Hose Reel 6. MR 01 01 1) Total number of eachfloor 30 mtr. 30 mtr. MR 2) Length of hose reel hose 05 mm 05 mm MR 3) Nozzle diameter **Automatic Fire Detection & Alarming System** 7. Required Provided MR 1) Type of detectors CO Gr. Floor Provided MR 2) Location of main panel N/A 3) Location of repeater panel N/A N/A Provided MR Required 4) Alternate source of power

Provided

MR

Each floor

5) Hooter's Location

0	MOEEA	Required	Provided	MR
8	MOEFA	Required	Provided	MR MR
9.	Public Address System	Required	TTOVICCO	IVIK 9
10.	Automatic Sprinkler System 1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling	11/21		
11.	Internal Hydrants			
11.	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor			
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants		T	Lavia
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			NIA
	Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump		NIA	N/A
	b) Head of main pump	N/A	N/A	N/A N/A
	c) Number of main pump		N/A	N/A N/A
	d) Jockey pump out put	N/A	N/A	N/A N/A
	e) Jockey pump head	N/A	N/A	N/A N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A N/A	N/A
	h) Auto starting/Manual	N/A	N/A	IN/A
	stopping			
	2) Terrace level	900 LPM	900 LPM	MR
	a) Discharge of pump	35 mtr.	35 mtr.	MR
	b) Head of pump		Provided	MR
	c) Power supply	Required Required	Provided	MR
	d) Auto starting of pump	Required	Tiovided	IVIIC
14.	Captive Water Storage for F			
	Under ground tank	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
		Required	Provided	MR
		5000 ltr.	5000 ltr.	MR
	d) Over head tank capacity	3000 Iu.	3000 Iti.	
		Required	Provided	MR
15.	Exit Signage.	Required	Tiovided	1,111
16.	Provision of Lifts.	1	27/1	3774
	a) Pressurization of lift	N/A	N/A	N/A
	shaft	1 2 2 2 2 2		277
	b) Pressurization of lift	N/A	N/A	N/A
	lobby			
	c) Communication in	N/A	N/A	N/A
	lift car			1
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Standby Power Supply	Required	Provided	MR
	Refuge Area	N/A	N/A	N/A
18.			, water-	100,000
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system	N/A	N/A	N/A
	panel	Section 6	30000	
	b) Flow switch panel	N/A	N/A	N/A
		N/A	N/A	N/A
	c) PA system panel d) Battery backup	N/A N/A	N/A N/A	N/A N/A
	d) Hattery backlin	I N/A	I IN/A	IN/A

	 e) Building floor plan 	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any: ABC & CO ₂			MR

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. No.F6/DFS/MS/GH/NDZ/2022/342 dated 13.07.2022, renewal under rule 37 of the Delhi Fire Service rules 2010, is recommended up to third floor only.

Signature of the Inspecting Officer
Name: - C.L. Meena
Designation: - ADO (RN)

DO/CC)

26/3/25

Airo (205)

THORY

Director / M)

Dinector

Antho

As approved, F.T. Letter is feetup for your signature Pl_

Director (Mr.) Ly

A 100 (44)

O phorald U