

C-13

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI- 110001

No. F6/DFS/MS/School/2025/SZ/ 834

Dated: 27/11/2025

To,

The President,
Shishu Bharati Shikshayatan,
3-A/61-66, WEA, Karol Bagh, New Delhi- 110005,

Sub: - Regarding renewal of "FSC" from fire safety point of view in r/o Shishu Bharati Shikshayatan located at 3-A/61-66, WEA, Karol Bagh, New Delhi- 110005.


Sir,

Please refer to your letter No. Nil, dated 10.11.2025, on the subject cited above. In this connection, it is to inform you that officer concerned of this department inspected the school building on dated 13.11.2025 to verify the fire safety arrangements in accordance with the rules. At the time of inspection Principal of the school was present and it was observed that school building comprised of Basement, ground plus three upper floors, using basement (closed), ground plus two upper floor (school), 02 rooms at third floor using for staff room only, and have following shortcomings: -

1. Overhead water storage tank provided capacity of 6,000 ltrs against requirement capacity of 10,000 ltrs.
2. Exit signage's are found not provided.

In view of the above, renewal of 'Fire Safety Certificate' cannot be granted at this stage. You are requested to rectify the above-mentioned shortcomings under intimation to this department for taking further necessary action in this matter and running school in absence of requisite fire safety arrangements shall be at the risk & liability of the school management.

Yours faithfully


(A.K. Malik)

Dy. Chief Fire Officer
South Zone

Copy to:-

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.