



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

2-13

No. F.6/DFS/MS/School/2025/NDZ/ 154

Dated 13/03/2025

To,

The Manager,
ShishuShikshaMandir,
X-103/4, Gali No. 9, Brahmpuri
Delhi-110053..

Sub:- Regarding Issuance of Fire Safety Certificate r/o ShishuShikshaMandir at X-103/4, Gali No. 09, Brahmpuri, Delhi-110053.

Sir,

With reference to your letter no.nil dated 17/02/2025 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection on dated 06/03/2025 of the above mentioned School from fire safety point of view in presence of the Mr. K.P. Verma, Manager of the school. The building comprised of ground plus one upper floor. Following shortcomings were observed during the time of inspection.

1. Second staircase of width 1.10 meter found removed.
2. Exit Signage found removed.

In view of the above, the building cannot be considered for issuance of Fire Safety Certificate at this stage. Therefore, you are requested to rectify the above mentioned shortcomings under intimation to this office for further course of action.

Yours faithfully

(ATEL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to:-

The Dy. Director of Education
B-Block, Yamuna Vihar, Delhi-110053