



108



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No: F.6/DFS/MS/2026/WZ/ School | 56
To,

Dated: 20/01/2026

The Principal,
Shraddha Model School,
H-70, Ranholla Extension,
Nangloi, Delhi-110041.

Sub:- Regarding issuance of Fire Safety Certificate in respect of Shraddha Model School located at H-70, Ranholla Extension, Nangloi, Delhi- 110041.

Sir,

This has reference to your e mail id dated 23/12/2025 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 02.12.2026 to see the compliance of the requisite fire safety measures. Ms. Shraddha was present at the time of inspection.

During the course of inspection it was observed school building is comprised of Ground plus two upper floors. Your request for issuance of FSC is rejected as the following shortcomings were observed:-

1. There is only one staircase of width 1.14 m provided against the requirement of two staircases of 1.5 m width each. Both the staircases shall reach up to the terrace.
2. Class room door width found 0.90 m against the required width of 1.20 m.
3. First aid hose reel found not provided.
4. Terrace level pump of 450 lpm discharge capacity found not provided.
5. Overhead tank of 10,000 ltrs capacity found not provided.
6. Exit signages found not provided.

You are advised to rectify the above-mentioned shortcoming for taking further action as necessary for issuance of Fire Safety Certificate. Till such time the occupancy of the building is at the risk and responsibility of owner/ occupier.

Yours Faithfully

LIV
(6/01/26)
(S.K. Dua)

**Dy. Chief Fire Officer (WZ)
Delhi Fire Service**

Ole R

Copy to :-

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.