

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

अज़ादी व अगृत महोत्सव

No. F6/DFS/MS/Banquet/NDZ/2025/57

Dated: 14 11 2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Shree Shyam Palace Banquet Hall is running in PD area of Ground floor & 1st floor located at Mansarover Park Metro Station, Delhi, comprised of Ground + 02 upper floors, granted Fire Safety Certificate by this department vide F6/DFS/MS/BNQT/2021/NDZ/02 dated 06.12.2021. The Banquet Hall was re-inspected by officer concerned of this department on 13.11.2025 in the presence of Mr. Pankaj (Manager) and found that the Banquet Hall has complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the Banquet Hall is fit for occupancy of Group D "Assembly Building" (Banquet Hall at Ground & 1st floor only) with effect from...14.1.1 2025... and valid upto 31.03.2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.. Issued on 14/11/2025 at New Delhi by

(Dr. S.K. Tomar)

Dy. Chief Fire Officer (NDZ)

Delhi Fire Service

Reference: etl.mcdonline application no. 2025111014696. Copy to:

- 1. The Commissioner MCD, 9th Floor, Shyama Prashad Mukherjee Civic Centre, Delhi 110002.
- 2. The JGM/E&M, DMRC Ltd., Metro Bhawan, Fire Brigade Lane, Barakhamba Road, New Delhi-01:- To ensure the occupancy of the building as per the issued FSC.

Conditions for the validity of Fire Safety Certificate

- 1. This Fire Safety Certificate is valid for Banquet Hall at Ground floor 1st floor only.
- 2. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 3. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- The trained fire fighting staff should be available round the clock.
- 6. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 10. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

		N	114		
<i>*</i>	T	NSPECTION DE	DOD#		
Name	and address of the building:	M/s Shroe Sh	PORT	and received to	
		Ground Garage Shyam Palace Banquet Hall located			
		Park Motor & 1" floor, PD Area, Mansaro			
Type	of occupancy				
gprised of		Ground + 02 upper floors (Banquet Hall is running in			
Y "		Mansarover Park Metro Station)			
Type	of case:				
41.4		To Report of Contracts	OT/2021 AID 7/02 Jan-1	06 12 2021	
		The state of the s	Q1/2021/NDZ/02 dated	00.12.2021	
			3.00		
		Specials (and posses) see	ADO (SDM)		
		Mr. Pankaj (Manager)			
		2010 & 2020			
A PENDENDAN	AND THE PROPERTY OF THE PARTY.				
		Requirements	Provide at site	Remarks	
Pre	evention and Fire Safety U/R			MR/NMF	
33		(6)			
Ac			T	MR	
A		11.7A7925001008		NA NA	
В	PERSONAL VIVINESSINGS		4.000		
C	The second secon	E-2000-62	NA	NA	
Nu		ement of Exits:			
A			Loo	MR	
			AND TANKS	NA	
l.		NA	NA .	INA	
В	- AND - Market and the second		100	MD	
	a) Upper floors	2.0 m each		MR	
			A STANDARD MONTH CONTROL	NA	
		NA	NA	NA	
C	380001800180010000000000000000000000000	fire and the second	T	l vm	
		2.000	The Control of State Co	MR	
				NA	
D		NA	NA	NA	
			D 11-1	MD	
E		Security Manager	_PCIPE AND DECEMBER 1	MR	
427.51	STATISTICAL STREETS I	20 200		MR	
G	Door Size	2.0 m		MR	
3 Cor	nnartmentation:		A 1.17 III & 1.15 III		
	•	Required	Provided	MR	
2000		1251	Provided	MR	
-		Windows Williams	200 September 20		
C		NA	NA	NA	
D	Water curtain	NA	NA ·	NA	
E		NA	NA	NA	
0.760		TWEET ST	MANAGES.		
A	Basements	NA	NA NA	NA	
WATER CO.	LONGAR MAD CORRESPONDE	[1 447 404 247]	150000000	MR	
277	Extinguishers:				
	(37)	22	22 nos.	MR	
A	Total numbers	// noe			
A	Total numbers	22 nos.		K.S.Common	
A B C	Total numbers Types ISI marking	ABC ISI marked	ABC ISI marked	MR MR	
	Type Buildi Type Detail Fire si Date of Name Name from t Year of Reference A B C Nu A B C Nu A B C Nu A B C C Nu A B C C D C C C C C C C C C C C C C C C C	Type of occupancy Building comprised of Type of case: Details of previous FSC Fire safety directives no. Date of inspection: Name of the inspecting officer: Name and designation of the officer from the building side: Year of construction: Reference letter no.: No Minimum standard of Fire Prevention and Fire Safety U/R 33 Access to Building: A Road width B Gate width C Width of internal roads Number, Width, Type & Arrang A No. of Staircase: a) Upper floor b) Basements B Width of the Staircase: a) Upper floors b) Basement C Protection of Exits a) fire check door b) pressurization D No. of continuous staircase to terrace E Width of corridor F No. of Door G Door Size 3 Compartmentation: A Fire check doors B Sealing of horizontal & vertical opening C Fire rating of shaft doors D Water curtain E Fire dampers A Basements B Upper floors	Name and address of the building: Type of occupancy Building comprised of Type of case: Type of case: Details of previous FSC F6/DFS/MS/BN Fire safety directives no. Date of inspection: Name and designation of the officer from the building side: Year of construction: Prevention and Fire Safety U/R 33 Access to Building: A Road width B Gate width C Width of internal roads NA Number, Width, Type & Arrangement of Exits: a) Upper floor b) Basement NA B Width of the Staircase: a) Upper floor b) Basement NA C Protection of Exits a) fire check door b) pressurization D No. of continuous staircase to terrace E Width of corridor C Fire rating of shaft doors C Fire rating of shaft doors C Fire rating of shaft doors D Water curtain NA B Smoke Management System: Provided & main NA C Provided & main NA Required NA NA Required NA Required NA NA Required	Name and address of the building: Ms Shree Shyam Palace Banquet Ground floor & 1st floor, PD Ares Park Metro Station, Delhi-32.	

6	Fi		02 nos.	ouilding manageme 04 nos.	MR			
	A	Total no. at each floor	02 nos. 30 m	30 m	MR			
	B	Length of hose reel	INTERNATION CONTRACTOR	5 mm	MR			
	C	Nozzle diameter	5 mm		112-11-2-31-01-5			
7	Automatic Fire Detection and Alarm System (ADAS): (Provided & maintained by building management)							
		T of detectors	Smoke/heat	Smoke/heat	MR			
	A	Type of detectors	NA	Provided	NA			
	B	Location of main panel Location of repeater panel	NA	NA	NA			
	C	Alternate power source	Required	Battery/DG set	MR			
	D	Hooter's location	Entire building	Provided	MR			
	E		Required	Provided	MR			
9	-	OEFA: blic Address System:	Required	Provided	MR			
10	Automatic Sprinkler System: (Provided & maintained by building management)							
10	A	Basement	NA	NA	NA			
	В	Ground floor/upper floor	NA	Provided	NA			
	C	Sprinklers above false ceiling	NA	NA	NA			
11	133	production of the contract of		ouilding managemen				
	A	Size of down comer	150 mm	150 mm	MR			
	В	No. of hydrants per floor	02 nos.	2 nos.	MR			
	C	Hose box	02 nos.	2 nos.	MR			
12	Ya	rd Hydrants: (Provided	& maintained by b	uilding management				
	A	Total no. of hydrants	NA	Provided	NA			
	В	Hose box	NA	Provided	NA			
13	Pu	mping Arrangements: (Common fir	e fighting system p anagement)	rovided & maintaine	d by			
		b) Number of main number	Sprk: 2850 LPM Head 70 m each	Sprk: 2850 LPM Head 70 m each				
9		b) Number of main pump	01 no.	01 no.	MR			
		c) Discharge & head of jockey pump	2 x 180 LPM & 70 m	2 x 180 LPM & 70 m	MR			
		d) Discharge & head of standby pump	2850 LPM & 70 m	2850 LPM & 70 m	MR			
		e) Auto starting/ manual stopping	Required	Provided	MR			
	B Terrace Level							
		a) Discharge of terrace pump	NA	NA	NA			
		b) Head of terrace pump	NA	NA	NA			
		c) Alternate power supply	NA	NA	NA			
14		d) Auto starting of pump	NA	NA	NIA			
14	Captive Water Storage for Fire Fighting: (Common fire tank provided & maintained							
	A	Underground tank capacity	by building ma	nagement)				
	В	Draw off connection	1,00,000 ltrs Required	1,00,000 ltrs	MR			
	C	Fire service inlet	Required	Provided	MR			
	E	Access to tank	Required	Provided	MR			
	D	Overhead tank capacity	NA	Provided	MR			
15	2220	it Signage:	- 10 - 10 - 10 - 10 - 10 - 10 - 10 - 10	NA	NA			
16	Provision of lift: (Provided & maintained by building management) A Programination of lift: (Provided & maintained by building management)							
10	A	Pressurization of lift shaft	NA maintaine	d by building mana				
	В	Pressurization of lift lobby	NA	NA NA	NA NA			
	C	CONTRACTOR AND	NA	NA	NA			
	D	Fireman switch	NA	NA	NA			
	E	Lift signage	NA	NA	NA			
17	0.	andby Power Supply:	Required	Provided				

M/s Shree Shyam Palace Banquet Hall located at Ground floor & 1st floor, PD Area, Mansarover Park Metro Station, Delhi-32.

M/s Shree Shyam Palace Banquet Hall located at Ground floor & 1st floor, PD Area, Mansarover Park Metro Station, Delhi-32.

18	Refuge Area:					
	A	location	NA	NA	NA	
	В	Total area	NA	NA	NA	
19	Fire Control Room: (Provided & maintained by building management)					
	A	Fire detection system panel	Required	Provided	MR	
	В	Flow switch panel	Required	Provided	MR	
	C	P a system panel	Required	Provided	MR	
	D	Battery backup	Required	Provided	MR	
	E	Building floor plan	Required	Provided	MR	
20	Special Fire Protection for special risk if any					
	A	Special Fire Protection system for Protection of Special Risk, if any:	NA	NA	NA	

<u>LEGENDS:-Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Not Provided (NP) Provide But Not Functional (PNF).</u>

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

The shortcomings issued to the Banquet Hall by this department vide letter no. F6/DFS/MS/Bnqt/NDZ/2025/187 dated 12.11.2025 has been rectified by the management.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/BNQT/2021/NDZ/02 dated 06.12.2021 is recommended to be renewed under Rule 37 of the Delhi Fire Service Rules 2010.

13/11/2025

Signature of the Inspecting Officer
Name Suman Kumar
Designation ADO (SPM)

40 (ch) Muller 13/11/11

Dy. (60 (N 22/)

Principal Director

13/11/22 05/0mg

My. CFO

40

M. Cfo (NDZ)

f-U 10%

A BO (Som)

14/11/52

F.T. letter is lad we for say ly

edital