

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001



No. F.6/DFS/MS/GH/2025/SZ/ 498

Dated: 15/09/2025

## FIRE SAFETY CERTIFICATE

Certified that M/s Shubham Palace Guest House located at 30, Nangli Razapur, East Nizamuddin, New Delhi–110013, comprised of Basement (storage), Ground floor (Rec. + 03 guest rooms), 1<sup>st</sup> Floor (Owner residence), 2<sup>nd</sup> Floor (06 guest rooms) and 3<sup>rd</sup> Floor (sealed by owner), Total 09 Guest Rooms, was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/GH/2021/SZ/52 dated 01/02/2021. The premises was re-inspected by the officer concerned of this department on dated 01/09/2025 in the presence of Sh. Sanjeev Kumar (Owner) and found that the said premises have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Group 'A' Residential" (Lodging House at Ground & 2<sup>nd</sup> Floor only with 09 guest rooms) with effect from 15/09/2025 for a period up to 31/03/2028 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 15 / 09 /2025 at New Delhi by

(Virendra Singh) Chief Fire Officer Delhi Fire Serivce

## Copy to: -

1. The Commissioner, MCD, Civic Centre, JLN Marg, Minto Road, New Delhi–110002 (w.r.t. online application No. 2025081912630 dated 19.08.2025).

2. Sh. Sanjeev Kumar, M/s Shubham Palace Guest House at 30, Nangli Razapur, East Nizamuddin, New Delhi-110013

## Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The basement shall be used strictly in accordance with the BBL.
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry.

N-24

1.		ON REPORT	Palace Guest Hor	use, 30,
1.	Name & address of the building	M/s <b>Shubham Palace Guest House</b> , 30, Nangli Razapur, East Nizamuddin, New Delhi–110013		
2.	Type of Occupancy	Residential & Lodging, "Group A"		
3.	Building Comprised of	Basement, Ground + 03 upper floor.  Basement (storage), Gd. floor (Rec. + 03 guest rooms)  1 <sup>st</sup> Floor (Owner residence), 2 <sup>nd</sup> Floor (06 guest rooms) and 3 <sup>rd</sup> Floor (sealed by owner), Total 09 Guest Rooms		
4.	Type of Case	Renewal		01/02/2021
5.	Details of previous NOC No.	F.6/DFS/MS/G	6H/2021/SZ/52 Dt.	01/02/2021
6.	Fire Safety directives Letter No.	Nil		
7.	Date of inspection	01/09/2025		
8.	Name of the Inspecting Officer	ADO (SJ)		
9.	Name and designation of Officer from the building side	Sh. Sanjeev Kumar (Owner)		
10.	Year of Construction	2009	110/09/2	0025
11.	Applicant's letter No.		2630 dated 19/08/2	Remark
S.	Minimum standards on fire	Old NOC	Provided at site	MR/NM
No.	prevention and fire safety U/R 33	Requirement		1.11011111
1.	Access of building	A	6 mtr	MR
	Road width	Accessible	N/A	N/A
	Gate width	N/A	N/A	N/A
	Width of internal road	N/A	IN/A	14/21
2.	Number, width, Type & Arrangements	of exits		
	a. Number of staircases	0	0	MD
	Upper floors	One One		MR (old case MR (old case
	Basements	One	One	IVIIC (Old Case
	b. Width of staircases	98 cm	98 cm	MR (old case
	<ul><li>Upper floors</li><li>Basements</li></ul>			MR (old case
	c. Protection of exits			•
	Fire check door	N/A	N/A	N/A
	Pressurization	N/A	N/A	N/A
		One	One	MR
	20 11	N/A	N/A	N/A
	e. Width of Corridor  f. Door Size	1 mtr	1 mtr (Final Exit)	
3.	Compartmentation			1,111
15/200	Fire check door	N/A	N/A	N/A
	<ul> <li>Sealing of electrical shafts</li> </ul>	N/A	N/A	N/A
	<ul> <li>Fire Rating of shaft door</li> </ul>	N/A	N/A	N/A
	Water Curtain	N/A	N/A	N/A
	Fire Dampers	N/A	N/A	N/A
4.	Smoke Managements System	NT/A		
-	Basements     Upper floors	N/A N/A	N/A	N/A
	Upper floors  Fire Extinguishers	IN/A	N/A	N/A
5.	Total numbers	Required		
		Required	05 Nos	MR
	Types     ISI marking	ABC/CO <sub>2</sub>	ABC	MR
	ISI marking     First-Aid Hose Reels	ISI marked	Provided	MR
6.				IVIIC
6.	T. 2-1			
6.	Total numbers on each floor	N/A	One	
6.	<ul> <li>Total numbers on each floor</li> <li>Length of hose reel hose</li> <li>Nozzle diameter</li> </ul>	N/A N/A	One 30m	N/A N/A

- 1	V	1
- 1		0
- 1		

7.	Automatic fire detection and alarming	system.		
	Type of detector	Co. Monoxide	Provided	MR
	<ul> <li>Location of Main Panel</li> </ul>	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	Provided	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System	1377	14/11	IN/A
10.	Basements	N/A	Provided	NT/A
		N/A	N/A	N/A
	Upper Floor	N/A		N/A
11.	Sprinkler above false ceiling     Internal Hydrants	IN/A	N/A	N/A
11.	Size of riser/down- comer	N/A	N/A	27/4
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A N/A		N/A
12.	Yard Hydrants	N/A	N/A	N/A
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	
13.	Pumping Arrangements	INA	IN/A	N/A
******	Ground Level			
	Discharge of main pump	N/A	NI/A	7 27/1
	> Head of main pump	N/A	N/A N/A	N/A
	Number of main pumps	N/A	N/A	N/A N/A
	Jockey pump out put	N/A	N/A	N/A N/A
	Jockey pump head	N/A	N/A	N/A
	<ul> <li>Standby Pump out put</li> <li>Standby Pump Head</li> </ul>	N/A	N/A	N/A
	<ul><li>Standby Pump Head</li><li>Auto Staring/Manual stopping</li></ul>	N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level	N/A	N/A	N/A
	Discharge of pump			
	Head of the pump	N/A	900 LPM	N/A
	> Power supply	N/A	40 mtr	N/A
		N/A	Provided	N/A
14.	Auto starting of pump	N/A	Provided	N/A
17.	Captive water Storage for fire fighting	in the second se		
	Underground tank capacity	N/A	N/A	N/A
	> Draw of connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
1.5	Overhead Tank capacity	N/A	5,000 ltrs	N/A
15	Exit Signage	Required	Provided	
16.	Provision of Lifts	rioquired	Tiovided	MR
	Pressurization of Lift Shaft	N/A	N/A	37/1
	Pressurization of lift lobby	N/A	11017707700.00	N/A
	Communication in lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A N/A	N/A	N/A
	Lift Signage	N/A N/A	N/A	N/A
17.	Standby power supply		N/A	N/A
18.	Refuge Area	N/A	Provided	N/A
	> Total area	27/1		
	> Location	N/A	N/A	N/A
		N/A	N/A	N/A



19.	Fire Control Room			
	<ul> <li>Detector system panel</li> <li>Flow Switch Panel</li> <li>PA System Panel</li> <li>Battery backup</li> <li>Building Floor Plans</li> </ul>	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of Special Risks, if any;	N/A	N/A	N/A

The fire protection systems provided in the building were checked, tested at random and found functional at the time of inspection. The shortcomings observed and communicated vide letter No. F6/DFS/MS/GH/NDZ/2025/269 dated 03/06/2025 found complied from fire safety point of view.

The condition of the Gazette notification dated 27/05/2019 on mentioned below found complied.

1	No Vitalian and Gardingament
1.	No Kitchen on rooftop/basement.

No Kitchen Provided MR

2. No Storage of inflammable material on rooftop.

No Storage Provided MR

3. No temporary roofing over the rooftop.

Not Provided MR

4. No Inflammable material of construction in passage/corridor. MR Not Provided

MR No Gas Bank Provided

5. Gas Bank, if any

MR Provided

6. Carbon Monoxide type Detectors.

MR Not Provided

7. Fire Doors of min. 01 hr. rating

(If number of occupants more than 10 on each floor)

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/GH/2021/SZ/52 dated 01/02/2021, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Ihspecting Officer

Name: Santosh Kumar Designation: ADO (SJ)