





GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

No. F6/DFS/MS/GH/2025/NDZ/ 445

Dated: | 8/11/2025

To,

M/s Shyam Guest House (Owner), Property No. 4234, Street Teli Mandi, Pahar Ganj, New Delhi-110055

Sub:- Regarding renewal of Fire Safety Certificate r/o M/s Shyam Guest House located at 4234, Tel Mandi, Pahar Ganj, New Delhi-110055.

Sir,

With reference to MCD application ID No. 2025101114139 dated 11/10/2025 on the subject cited above. In this connection, this is to inform you that the site was inspected by the officer concerned of this department on dated 04/11/2025 in presence of Sh. Sunil Kumar Behl (Owner) it was observed that the shortcomings as communicated earlier vide letter no. F.6/DFS/MS/GH/NDZ/2024/751 dated 31/12/2024 & F.6/DFS/MS/GH/SZ/350 dated 14/08/2025 (Copy enclosed) have not been complied yet.

In view of above the application for renewal of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire Safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

Encl. As above:

(Dr. S. K. TOMAR)
DY. CHIEF FIRE OFFICER
DELHI FIRE SERVICE

6

MCD ID. 2025101114139



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

आज़ादी वा अमृत महोत्सव

No. F6/DFS/MS/GH/NDZ/2024/ 751

Dated: 31122024

To

The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi.

Ref: elt.mcdonline application no. 2024101215589

Sub: Regarding renewal of Fire Safety Certificate in respect of M/s Shyam Guest House located at 4234, Tel Mandi, Pahar Ganj, New Delhi.

Sir,

With reference to the elt.mcdonline application no. 2024101215589 on the subject cited above, it is informed that the said guest house was inspected by the officer concerned of this department on. 23.12.2024 in the presence of Mr. Ameer (Manager) and following shortcoming were observed at the time of inspection.

- 1: Hose reel found non functional.
- 2. CO detector found non functional.
 - 3. Manual Operated Electrical Fire Alarm (MOEFA) system found non functional.
- 4. Fire pump found non functional.
 - 5. Guest house was also found running at 4th & 5th floor though owner has submitted an affidavit dated 05.12.2019 not to use any floor above 3rd floor. Closure/sealing of the same shall be ensured by the local authority/licensing authority.

In view of above shortcomings, the application for renewal of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit

Yours faithfully

Atul Garg)
Director

Delhi Fire Service

Copy to :-

1. The Executive Engineer (Bldg.), MCD, 9th Floor, Dr. SPM Civic Centre, Minto Road, New Delhi-110002. To verify the height of the building under intimation to this department.

clive

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE : NEW DELHI - 110001

No. F6/DFS/MS/GH/SZ/250

Dated: 14../08 /2025

To,

The Commissioner, Municipal Corporation of Delhi, E-1, 9th Floor, Dr. SPM Civic Centre, Minto Road, New Delhi-110002

Sub: Regarding issuance of Fire Safety Certificate in r/o M/s Shyam Guest House located at 4234, Tel Mandi, Pahar Ganj, New Delhi.

Sir,

This has reference to MCD Portal ID No. 2025071411362 dated 14/07/2025 on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 24/07/2025 in the presence of Md. Amir, Manager and to verify the present status of fire safety measures installed in the building. The fire safety arrangements were tested / checked and found following observations:-

1. Manual Operated Electrical Fire Alarm (MOEFA) system found non functional.

2. Guest house was also found running at 4th & 5th floor through owner has submitted an affidavit dated 05/12/2019 not to use any floor above 3rd floor. Closure/sealing of the same shall be ensured by the local authority /licensing authority.

The above observations has already been issued and communicated earlier by this department vide letter of even no 751 dated 31/12/2024.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed

Yours faithfully,

Encl: as above.

(VIRENI CHIEF FIRE OFFICER DELHI FIRE SERVICE