

# GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

No.F.6/DFS/MS/EH/2025/SZI 22 7 NEW DELHI- 110001

Dated: 10/06/2025

#### **FIRE SAFETY CERTIFICATE**

Certified that the M/s SKY ROZO, running at third floor of a building comprised of basement, stilt, ground plus three upper floors located at B-1/625 third floor, Najafgarh road Janakpuri New Delhi-110058, owned/occupied by M/s SKY ROZO, was issued FSC by this department vide letter No. F.6/DFS/MS/EH/2022/SZ/78 dated 05.04.2022. The Restaurant building was re-inspected by the officer concerned of this department on dated 02.06.2025 in the presence of Mr. Anuj Chopra, and found that the restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the restaurant building/premises (third floor only) is fit for occupancy class Group "D" Assembly Building" with effect from 10/06/2025 and valid up-to three years, accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 10/06/2025 at New Delhi.

(Virendra Singh)
Chief Fire Officer
Delhi Fire Service

#### Online application Id 2025051708617 dated 23.05.2025

Copy to: - The Executive Engineer (Building), MCD, Civic Centre, Minto Road, New Delhi.

:-for information regarding use of basement.

### Conditions for validity of Fire Safety Certificate: -

1. This FSC is valid only for third floor.

- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 3. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 4. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

5. The trained staff should be available round the clock.

6. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

7. Basement strictly shall be used as per BBL.

- 8. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 9. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 10. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

## INSPECTION REPORT 1. Name & address of the building:

2. Building is comprised of M/s SKY ROZO eating house at B-1/625 Third floor, Najafgarh

road Janakpuri, New Delhi-110058.

3. Type of Occupancy

B, Stilt, G+3 floors but restaurant at third floor only

4. Type of Case

Group D (Assembly/ Restaurant Building)

5. Details of Previous NOC

Renewal

F.6/DFS/MS/EH/2022/SZ/78 dated 05.04.2022

6. Fire Safety directives letter No Date of inspection

Nil

8.

02.06.2025

Name of Inspecting Officers

: A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side 10. Year of Construction

Mr. Anuj Chopra

11. Applicant's laws N

2013

r. Io.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement/Existing Fire Safety Measures	Provided at site	Remarks MR/NMR
•10	Access to building	Λ		
	Road width	Accessible (09 m)	Provided	MR
	Gate width	N/A	N/A	N/A
	Width of internal road	N/A	N/A	N/A
2.	Number, Width, Type & Arrangement of	Exits	(restaurant is running at TF)	
	a. Number of staircases		•	
	Upper Floors	02 No.'s	02 No.'s	MR
	Basements	N/A	N/A	N/A
		1,17.2		
	b. Width of staircases	1.5 m each	1.5 m each	MR
	Upper Floor	N/A	N/A	N/A
	Basements	IVA		
	c. Protection of exits	N/A	N/A	N/A
	Fire check door	N/A	N/A	N/A
	<ul> <li>Pressurization</li> </ul>	IVA		
	d. No. of continuous staircases to	Required	two	MR
	terrace	N/A	N/A	N/A
	e. Width of Corridor	2.0 m & 1.5 m	2 X 2.0 m & 1X1.5 m	MR
	f. Door Size	2.0 111 62 1.5 1.1		
3.	Compartmentation			N/A
	Fire check door	N/A	N/A	- III
	Sealing of electrical shafts	N/A	N/A	N/A
	Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	Fire Dampers	N/A	N/A	N/A
1554	Smoke Management System		(restaurant is running	at TF)
4.		N/A	N/A	N/A
	Basements     Upper floors	Required	Natural Ventilation	MR
5.	Fire Extinguishers	08 No.'s	<u> </u>	
	Total numbers on each floor	ABC/ CO <sub>2</sub>	Provided	MR
	• Types	ISI marked	Provided	MR
	• IS marking	101 market	ISI marked	MR
6.	First-Aid Hose Reels		LL Co	
	Total numbers on each floor	One	Provided	MR
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	IVIN

MIZ

.	Automatic fire detection and alarming system			
	Type of detectors	N/A	N/A	27/1
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A N/A	N/A	N/A
- 1	Alternate source of power	N/A N/A	N/A	N/A N/A
	Hooters' Location	IVA	N/A	N/A N/A
3.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System		E. Martin	IVA
	Basement	N/A	N/A	
	upper floors	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A N/A
11.	Internal Hydrants			IVA
-	Size of riser/down-comer	100 mm		
	Number of hydrants	01 No.	Provided	MR
	Hose Box	01 No.	Provided Provided	MR
12.	Yard Hydrants		Tiovided	MR
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements	The property	or Tall One, is	
	Ground Level			
	<ul> <li>Discharge of main Pump</li> </ul>	2280 LPM	Provided	100
	➤ Head of Main pump	60 mtrs	Provided	MR
1.0	Number of main pumps	One	Provided	MR
	> Jockey Pump out put	180 LPM	Provided	MR
	<ul> <li>Jockey pump head</li> <li>Standby Pump out put</li> </ul>	60 mtrs	Provided	MR
	> Standby Pump out put	2280 LPM	Provided	MR
- 1	➤ Auto Starting/Manual Stopping	60 mtrs	Provided	MR
	wantan Stopping	Required	Provided	MR MR
ŀ	➤ Pump House Access	Required	Provided	MR
	Terrace level			IVIIC
	Discharge of pump	450 LPM	Provided	MR
	➤ Head of the pump	40 mtrs	Provided	MR
	➤ Power Supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	1,00,000 ltrs	Provided	100
	Draw-off connection	Required	Provided Provided	MR
	➤ Fire service inlet	Required	Provided	MR MR
	Access to tank	Required	Provided	MR
	Overhead Tank capacity	5000 ltrs	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	19-100-00-00-00-00-00-00-00-00-00-00-00-00	200 CO TO	
-	\$	50	also .	
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	• Fireman's Grounding Switch	Required	Provided	MR
17.	• Lift Signags	Required	Provided	MR
1	Standby power supply	Required ,	Provided	MR

		1918	Acruge Area.	75.
ï.			> Total Area > Location	
N/A	N/A	N/A N/A	Fire Control Room	19.
N/A	N/A	IVA		
			Detector System Panel     Flow Services	
N/A	N/A	N/A	Switch Panel	
N/A	N/A	N/A	PA System Panel	
N/A	N/A	N/A	Battery backup	
N/A	N/A	N/A	Building Floor Plans	
N/A	N/A	N/A	Special Fire D.	0.
N/A	N/A	N/A	Protection of special Risks, if any:	
			Alsks, if any:	- C

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings was issued by this department vide letter No. F6/DFS/MS/EH/2025/SZ/172 dated 22.04.2025 has been complied.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F.6/DFS/MS/EH/2022/SZ/78 dated 05.04.2022, renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

> Signature of the Inspecting Officer Name- R.K. Yadav Designation- ADO (JKP)

hetter is, put up for signature