

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

No. F6/DFS/MS/School/SZ/2025/ 75

To

The Principal. South Delhi Model School, K-I/18/174, Sangam Vihar, New Delhi-80.

Regarding renewal of Fire Safety Certificate in respect of South Delhi Model School Sub:located at K-I/18/174, Sangam Vihar, New Delhi-80.

Sir,

With reference to the letter bearing outdoor diary no. 9819 dated 02.12.2024 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (M. Road) from this department on 24.01.2025 in the presence of Mr. Amit Chauhan (Director) and it was observed that the building which was earlier comprised of Ground + 02 upper floors is now comprised of Ground + 03 upper floors. Hence is a case addition/alteration. During the inspection following shortcoming were observed.

- 1. Two staircases of 1.50 meters width from ground floor to terrace shall be provided.
- 2. Hose reel found non functional.
- 3. Fire pump found non functional.
- 4. Overhead tank 10,000 liters not provided.

In view of above shortcomings, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfull

Copy to:-.

1. The Dy. Director of Education, GNCT of New Delhi DISTT. South Sector-3, R.K. Puram, New Delhi-22.