

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No.F6/DFS/MS/GH/NDZ/2025/233

Dated: 22 04 2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Southern Guest House, located at 18/2, Arya Samaj Road, Karol Bagh, New Delhi comprised of Basement+ Ground+ Three Upper Floors using ground floor as shops, first floor used as restaurant, second & third floor each having 08 guest rooms respectively (store in temporary shed on terrace). The FSC was granted by this department vide letter No. F6/DFS/MS/GH/SZ/2022/261 dated 07.06.2022 for 16 guest rooms only. Now, the premises was re-inspected by the officer concerned of this department on 08.04.2025 in presence of Sh. B. Surya Rao, Manager and found that the said guest house building have deemed complied for 2nd & 3rd floor with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, (Guest house), for second floor & third floor each having 08 guest rooms respectively (total 16 guest rooms only) with effect from . 22 0.4. 2025 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on ... 22 04 2025. at New Delhi by.

Copy to:-

- 1. The Commissioner, MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online ID No. 2025032504502 dated 25.03.2025
- 3. The Manager, Southern Guest House, located at 18/2, Arya Samaj Road, Karol Bagh, New Delhi. Condition for the validity of Fire Safety Certificate
 - 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all
 - 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the
 - 3. The trained fire fighting staff should be available round the clock.
 - 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
 - 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if
 - The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
 - 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an
 - 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry. 9. Any flammable material for interior decoration is prohibited.

 - 10. The basement shall be used as per building by law.

		IN	SPECTION REPO	ORT					
1	Nam	ne & address of the		est House, 18/2, Arya	Samaj Road,				
	build	ding	Karol Bagh, New	Delhi					
2	Buil	ding is comprised of		nd+ Three Upper Floo					
3	Тур	e of occupancy	Residential (Gues	t house having 16 gu	est rooms) i.e				
4	Тур	e of case	Renewal	Residential (Guest house having 16 guest rooms) is 2nd flam squart rooms, and floor-squart rooms Renewal					
5	Deta	ails of previous FSC							
6		safety directive letter no.	No. F.6/DFS/MS/GH/SZ/2022/261 dated 07.06.2022 NA						
					9				
7		e of inspection	08.04.2025						
8	Nan offic	1	Suman Kumar, ADO						
9	Name of the designation of Sh. B. Surya Rao, Manager officer from the building side								
10	Yea	r of construction	Before 2007						
11	App	olicant's letter no.	Online ID No. 2025032504502 dated 25.03.2025 Old Cas						
S. No	10.	nimum standard of Fire vention and Fire Safety & 33	Fire safety requirement as per FSC dated 07.06.2022	Provided at site	Remarks MR/NMR				
1	Acc	cess to Building	1						
+	A	Road width	Accessible	09 mts.	NA				
	В	Gate width	NA	Directly Accessible from the road	NA				
			NIA.	NA	NA				
	C	Width of internal roads	NA Semant of Evits	INA	1112				
2		mber, Width, Type & Arr							
	A		01 Nos.	01 Nos.	MR being old				
		a) Upper floor	OT NOS.	011100.	case				
		b) Basements	02 Nos.	02 Nos.	MR being old case				
	В	Width of the staircase:							
		a) Upper floors	1.25 m	1.25 m	MR being old				
		b) Basements	1.25 m	1.25 m	MR being old case				
	C	Protection of Exits							
		a) Fire check door	Required	Provided	MR				
		b) Pressurization	NA	NA	NA				
	D	No. of continuous staircase to terrace:	01 No.	01 No.	MR				
	E	Width of the corridor	1.0 m	1.40	MR				
	F	Door size	1.0 m	78 cm *200 cms	MR being old				
	-				case				
3	-	mpartmentation: Fire check doors	Required	Provided	MR				
	B	Sealing of horizontal & vertical opening	Required	Sealed	MR				
	C	Fire rating of shaft doors	N/A	N/A	N/A				
	D	Water curtain	N/A	N/A	N/A				
	E	Fire dampers	N/A	N/A	N/A				
4	_	noke Management System		Fuhaust Con	110				
	A	Basements	10 a/c per hour	Exhaust fan provided	MR				
	В	Upper floors	12 a/c per hour	Natural Ventilation	MR				
5	Fir	e Extinguishers	1.	Harris de la companya della companya de la companya de la companya della companya					
5	_	T-4-1	03 nos. at each	Provided	MR				
5	A	Total numbers	floor	Trovided	IVIK				
5	A B C	Types ISI marking		Provided	MR				

	Fir	ct A	id Hose Reel	4-20		
	A	Tota	id Hose Reel			
-	B	Len	al no. at each floor	01 nos.	Provided	MR
+	C	Non	gth of hose reel	30 mtrs	Provided	
,		INOZ	zzle diameter	-	Provided	MR
	Au	toma	atic Fire Detection and Alarm Sy	stem (ADAS)	Trovided	MR
	A	Typ	be of detectors	Carbon	Provided	2 (2)
}	D	,		monoxide	riovided	MR
	В	Loc	cation of main Panel	Required	Provided near	27.
	-	-		required	7.1 527	NA
	C	Lo	cation of repeater panel	N/A	reception N/A	27//
	D	Alt	ternate power source	Required		N/A
-	E	Ho	oter's location	N/A	Provided	MR
8		OEF		Required	N/A	N/A
9	Pu	blic	Address System	Required	Provided	MR
10	Aı	uton	natic Sprinkler System	Required	Provided	MR
	A	Ba	asement	Dogwin 1	ъ	_
	B	U	oper floor	Required	Provided	MR
	C	Sp	orinklers above false ceiling	N/A	N/A	N/A
11	Ir	terr	nal Hydrants	N/A	N/A	N/A
	A	Si	ze of the riser/down comer			
	В	N	o. of hydrants per floor	N/A	N/A	N/A
	C	Н	ose box	N/A	N/A	N/A
12	Y		Hydrants	N/A	N/A	N/A
	A	T	otal no. of hydrants			
	E	F	lose box	NA	NA	NA
13	_		ping Arrangements	NA	NA	NA
		1 (Ground Level			
	1	-				
		-	Se of main pullip	N/A	N/A	N/A
			Head of main pump	N/A	N/A	N/A
			Number of main pump	N/A	N/A	N/A
			 Discharge of jockey pump 	N/A	N/A	N/A
			Head of jockey pump	N/A	N/A	N/A
			Discharge of Standby pump	N/A	N/A	N/A
		-	> Head of Standby pump	N/A	N/A	
			Auto starting/ manual stopping		N/A N/A	N/A
		-	Pump house access	N/A	N/A N/A	N/A
	-	В	Terrace Level	IN/A	IN/A	N/A
		-		450 I DM	D) (D
	1	1	Discharge of terrace pump	450 LPM	Provided	MR
		-	> Head of terrace pump	40 m	Provided	MR
		1	> Alternate power supply	Required	Provided	MR
			Auto starting of pump	Required	Provided	MR
1	4	Ca	ptive Water Storage for Fire Figh	ting	Tayla	27/4
		A	Underground tank capacity	N/A	N/A	N/A
		В	Draw off connection	N/A	N/A	N/A N/A
		C	Fire Service Inlet	N/A	N/A N/A	N/A N/A
		E	Access to tank	N/A	Provided (5000	MR
		D	Overhead tank capacity	Old case.	Ltr.)	being o
-	-	17	:: t Signage	Required	Provided	MR
-	15	0.110		10000 10000 0		
-	16	-	Clift aboff	NA	NA	NA
		A	Clift lobby	NA	NA	NA
		B	1:0 000	NA	Provided	NA
		C	·	Required	Provided	MR
		D E		Required	Provided Required	MR MR

18	Refuge Area						
	A	location	NA	NA	NA		
	В	Total area	NA	NA	NA		
19	Fire Control Room						
	A	Fire detection system panel	NA	NA	NA		
	В	Flow switch panel	NA	NA	NA		
	C	P A system panel	NA	NA	NA		
	D	Battery backup	NA	NA	NA		
	E	Building floor plan	NA	NA	NA		
20	Special Fire Protection for special risk if any						
		Special fire protection system for protection of special risk, if any:		N/A	NA		

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view the substantial Compliance of the minimum standards on fire prevention and fire safety required under the rules, the FSC vide letter no. No. F.6/DFS/MS/GH/SZ/2022/261 dated 07.06.2022 renewal under the Rule 37 of the Delhi Fire Service Rules 2010 is recommended for approval up to third floor.

Signature of the Inspecting Officer Name Suman Kumar Designation ADO

Director

letter is lat al for signature by