



c/29



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

No.F.6/DFS/MS/School/2025/NDZ/ 306

Dated: 01/05/2025

To,

The Principal,
S.R. Public School,
D-62, West Jyoti Nagar, Shahdara,
Delhi-110053

Subject:-Regarding renewal of Fire Certificate in r/o S.R. Public School located at D-62, West Jyoti Nagar, Shahdara, Delhi-110093.

Sir,

This is in reference to your letter no. nil dated 01/04/2025 on the subject cited above. In this connection, it is to inform you that officer concerned of this department has visited the school on 19/04/2025 in presence of Principal and observed that the shortcomings as communicated earlier vide letter No. F.6/DFS/MS/School/2019/2216 dated 22/04/2019 (copy enclosed) have not been complied yet.

In view of the above Fire Safety Certificate cannot be considered at this stage. The occupancy of the building/premises in absence of requisite for safety arrangement shall be at the risk and liability of the owner/occupier.

Encl:- As above

Yours faithfully

(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE

Copy to:-

The Director of Education (MCD)
15th Floor, E-Block, Dr. S.P. Mukahrjee Civic Center, JLN Marg, New Delhi-110002

CG

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

No. F6/DFS/MS/School/2019/ 2216

Dated: 22/4/19

To,

The Manager,
M/s S.R. Public School,
D-62, West Jyoti Nagar, Shahdara,
Delhi 110094

Sub:- Regarding Issuance of Fire Safety Certificate in r/o M/s S.R. Public School at D-62, West Jyoti Nagar, Shahdara, Delhi 110094.

Sir,

This is in reference to your letter No. nil dated 12/02/19 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned school from fire safety point of view in presence of Mrs. Lalita, Principal of the School. During the course of inspection, the following points / shortcomings were noticed in the building comprised of ground plus two upper floors.

1. The width of staircase shall be 1.50 meter or an additional staircase of 0.75 meter, shall be provided.
2. First-Aid hose reels (01 nos.) at each floor provided but not functional.
3. A fire pump having 450 LPM output at 40 meters head not provided.
4. Over Head water storage tank 2,000 liters capacity provided at terrace in place of 10,000 liters as required.
5. Exit Signage were not provided.

In view of above, the building can not be considered for issue of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully



(Sunil Chawdhary)
Dy. Chief Fire Officer

Copy to:-

The Director of Education, EDMC
Udyog Sadan, Plot No. 419, FIE,
Patparganj, Delhi 92

ole
OK