



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No: F6/DFS/MS/WZ/2026/122
To,

Dated: 17/04/2026

The Medical Superintendent,
Sri Balaji Action Medical Institute,
FC-34, A-4 Block, Paschim Vihar,
New Delhi - 110063.

Sub: - Inspection report in r/o M/s Sri Balaji Action Medical Institute located at FC-34, A-4 Block, Paschim Vihar, New Delhi - 110063.

Sir,

As per directions of the Competent Authority vide office order no. F6/DFS/HQ/2026/494 dated 20/03/2026, it is submitted you that the surprise inspection of above said Hospital building has been carried out by the officer concerned on 25.03.2026 to see the compliance of the requisite fire safety measures. Sh. Mandeep Lakra (DGM Maintenance) was present at the time of inspection.

Following shortcomings were observed at the time of inspection:-

1. Internal road of 6 m width found obstructed due to new construction.
2. Door closer of fire check doors found removed at some places.
3. Fire check door found removed at some places.
4. Smoke management system in basement and upper floors found removed at some places.
5. Detectors found removed at some places.
6. Automatic sprinkler system found removed at some places
7. Pharmacy store inside the ramp is not permitted.
8. Existing building is interconnected with the newly constructed building and needs to be segregated with fire check doors at each level.

You are advised to rectify the above-mentioned shortcoming under intimation to this department, till than the occupancy of the Building/ Premise in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/ Occupier.

Yours Faithfully

S.K. Dua

Chief Fire Officer
Delhi Fire Service

Copy to:-

1. The Commissioner, MCD, Civic Centre, Minto Road, New Delhi- 110002.